



COUNTRY COACH

Mr. George Person
Chief, Recall Management Office
National Highway Traffic Safety Adm.
400 7th Street, S.W.
Washington, D.C. 20590

November 12, 2204

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 04V-463 began on 08 November 2004 and was completed on 12 November 2004. As required, copies of the final notifications are attached for your files.

If you should have any questions, please feel free to contact me at 541-998-3720 x138.

Sincerely,

Gary Dwyer
Director, Quality Assurance and Compliance Administration
Country Coach Inc.

Enclosures (2) Customer Notification, 04V-463
Dealer Notification, 04V-463

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

October 29, 2004

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 04V-463

Dear Country Coach Service Provider:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach, Inc. has decided that a safety defect exists on certain motor homes it manufactured. LP cook tops were installed with a flexible rubber hose listed for use with LP gas. The use of multiple burners or the use of oversized cooking vessels could cause heat to collect inside the cook top base and result in the melting or burning of the flexible rubber hose. If undetected the hose could burn through and result in a LP gas fed fire.

MODELS AFFECTED:

Model Year: 2004 Allure Motorhomes manufactured from July 2003 to May 2004

Model Year: 2004 Inspire Motorhomes manufactured from May 2003 to March 2004

Model Year: 2005 Inspire Motorhomes manufactured from March 2004 to May 2004

A listing of all affected motorhomes is attached to this letter.

VEHICLE SAFETY
DEFECT NOTICE

Country Coach has determined that the repair for this safety defect will be the replacement of the flexible rubber hose with copper tubing. The repair and associated parts will be performed and provided at no cost to the owner. The labor required to remove and replace the flexible rubber hose is not expected to exceed one and one-half (1.5) hours.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer service department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time (Please see the enclosed Letter to Country Coach Owners).

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

Enclosure: Customer Notification

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.
Gary Obermire, Vice President, Engineering, Country Coach, Inc.

COACH LISTING

04V-463

Coach#	Model	VIN
30990	MLT-40-NPTS-04	4U7A8EY1541103541
30991	MLT-40-NPTS-04	4U7A8EV1441103552
30992	MHL-36-PTSR-04	4U7A6DV1641103553
30993	MLT-40-NPTS-04	4U7A8EV1841103554
30994	MLT-40-CSSR-04	4U7A8EV1741103559
30995	MLT-40-NPTS-04	4U7A8EV1341103560
30996	MLT-40-NPTS-04	4U7A8EV1541103561
30997	MHL-36-PTSR-04	4U7A6DV1341103574
30998	MHL-36-PTSR-04	4U7A6DV1241103565
30999	MLT-40-NPTS-04	4U7A8EV1441103566
31000	MLT-40-NPTS-04	4U7A8EV1641103567
31001	MLT-40-NPTS-04	4U7A8EV1041103578
31002	MLT-40-NPTS-04	4U7A8EV1241103579
31003	MHL-36-PTSR-04	4U7A6DV1941103580
31004	MHL-36-PTSR-04	4U7A6DV1X41103586
31005	MHL-36-PTSR-04	4U7A6DV1241103601
31006	MHL-36-PTSR-04	4U7A6DV1841103604
31007	MLT-40-CSSR-04	4U7A8EV1X41103605
31008	MLT-40-CSSR-04	4U7A8EV1341103624
31009	MLT-40-NPTS-04	4U7A8EV1041103628
31010	MLT-40-CSSR-04	4U7A8EV1241103629
31011	MHL-36-PTSR-04	4U7A6DV1141103637
31012	MHL-36-PTSR-04	4U7A6DV1441103647
31013	MLT-40-ASSG-04	4U7A8EV1341103638
31014	MLT-40-NPTS-04	4U7A8EV1541103639
31015	MLT-40-NPTS-04	4U7A8EV1541103642
31016	MLT-40-NPTS-04	4U7A8EV1641103648
31017	MLT-40-CSSR-04	4U7A8EV1X41103653
31018	MHL-36-PTSR-04	4U7A6DV1141103654
31019	MLT-40-NPTS-04	4U7A8EV1341103655
31020	MLT-40-NPTS-04	4U7A8EV1941103658
31021	MLT-40-NPTS-04	4U7A8EV1141103671
31022	MLT-40-NPTS-04	4U7A8EV1641103682
31023	MLT-40-NPTS-04	4U7A8EV1841103683
31024	MLT-40-ASSG-04	4U7A8EV1141103685
31025	MLT-40-ASSG-04	4U7A8EV1941103692
31026	MLT-40-ASSG-04	4U7A8EV1041103693
31027	MLT-40-NPTS-04	4U7A8EV1341103705
31028	MLT-40-NPTS-04	4U7A8EV1541103706
31029	MLT-40-NPTS-04	4U7A8EV1741103707
31030	MLT-40-NPTS-04	4U7A8EV1941103711
31031	MHL-36-PTSR-04	4U7A6DV1041103712
31032	MHL-36-PTSR-04	4U7A6DV1241103713
31033	MLT-40-NPTS-04	4U7A8EV1641103715
31034	MLT-40-ASSG-04	4U7A8EV1841103733

COACH LISTING

04V-463

Coach#	Model	VIN
31035	MHL-33-SS-AD-04	4U7A6CV1741103734
31036	MLT-40-NPTS-04	4U7A8EV1341103736
31037	MLT-40-NPTS-04	4U7A8EV1041103743
31038	MHL-33-SS-AD-04	4U7A6CV1X41103744
31039	MHL-33-SS-AD-04	4U7A6CV1141103745
31040	MHL-33-SS-AD-04	4U7A6CV1341103746
31041	MHL-33-SS-AD-04	4U7A6CV1541103747
31042	MLT-40-NPTS-04	4U7A8EV1241103758
31043	MHL-33-SS-AD-04	4U7A6CV1141103759
31044	MHL-33-SS-AD-04	4U7A6CV1841103760
31045	MHL-33-SS-AD-04	4U7A6CV1X41103761
31046	MLT-40-NPTS-04	4U7A8EV1441103776
31047	MHL-33-SS-AD-04	4U7A6CV1341103777
31048	MLT-40-NPTS-04	4U7A8EV1641103780
31049	MLT-40-NPTS-04	4U7A8EV1841103781
31050	MLT-40-NPTS-04	4U7A8EV1X41103782
31051	MHL-33-SS-AD-04	4U7A6CV1941103783
31052	MLT-40-NPTS-04	4U7A8EV1341103784
31053	MHL-33-SS-AD-04	4U7A6CV1241103785
31054	MLT-40-NPTS-04	4U7A8EV1441103793
31055	MLT-40-CSSR-04	4U7A8EV1641103794
31056	MHL-36-PTSR-04	4U7A6DV1241103811
31057	MLT-40-NPTS-04	4U7A8EV1841103814
31058	MHL-33-SS-AD-04	4U7A6CV1741103815
31059	MLT-40-CSSR-04	4U7A8EV1541103818
31060	MHL-33-SS-AD-04	4U7A6CV1441103819
31061	MLT-40-NPTS-04	4U7A8EV1341103820
31062	MLT-40-NPTS-04	4U7A8EV1041103824
31063	MLT-40-CSSR-04	4U7A8EV1241103825
31064	MLT-40-NPTS-04	4U7A8EV1441103826
31065	MHL-33-SS-AD-04	4U7A6CV1741103846
31066	MLT-40-NPTS-04	4U7A8EY1741103847
31067	MHL-33-SS-AD-04	4U7A6CV1041103848
31068	MLT-40-NPTS-04	4U7A8EV1641103858
31069	MHL-33-SS-AD-04	4u7a6cv1541103859
31070	MLT-40-NPTS-04	4U7A8EY1X41103860
31071	MLT-40-NPTS-04	4U7A8EY1741103881
31072	MHL-33-SS-AD-04	4U7A6CY1641103882
31073	MLT-40-NPTS-04	4U7A8EY1241103884
31074	MHL-36-PTSR-04	4U7A6DY1741103900
31075	MLT-40-NPTS-04	4U7A8EY1941103901
31076	MHL-36-PTSR-04	4U7A6DY1141103908
31077	MHL-33-SS-AD-04	4U7A6CY1041103909
31078	MHL-33-SS-AD-04	4U7A6CY1241103927
31079	MLT-40-NPTS-04	4U7A8EY1741103928

COACH LISTING

04V-463

Coach#	Model	VIN
31080	MLT-40-NPTS-04	4U7A8EY1841103937
31081	MLT-40-NPTS-04	4U7A8EY1341103943
31082	MLT-40-NPTS-04	4U7A8EY1X41103955
31083	MHL-33-SS-AD-04	4U7A6CY1941103956
31084	MLT-40-NPTS-04	4U7A8DY1341103967
31085	MHL-33-SS-AD-04	4U7A6CY1541103968
31086	MLT-40-NPTS-04	4U7A8DY1241103975
31087	MLT-40-NPTS-04	4U7A8EY1741103976
31088	MHL-36-PTSR-04	4U7A6DY1941103977
31089	MHL-33-SS-AD-04	4U7A6CY1841103978
31090	MHL-36-PTSR-04	4U7A6DY1141103997
31091	MHL-33-SS-AD-04	4U7A6CY1341103998
31092	MLT-40-NPTS-04	4U7A8EY1641104021
31093	MHL-33-SS-AD-04	4U7A6CY1541104022
31094	MHL-33-SS-AD-04	4U7A6CY1741104023
31095	MLT-40-NPTS-04	4U7A8EY1041104032
31096	MHL-33-SS-AD-04	4U7A6CY1X41104033
31097	MLT-40-NPTS-04	4U7A8EY1441104034
31098	MLT-40-NPTS-04	4U7A8EY1641104035
31099	MHL-36-PTSR-04	4U7A6DY1841104036
31100	MHL-33-SS-AD-04	4U7A6Y1941104038
31101	MHL-33-SS-AD-04	4U7A6CY1241104060
51001	MIN-40-GATS-04	4U7K5EK1541103318
51002	MIN-40-GATS-04	4U7K5EK1741103319
51003	MIN-40-GATS-04	4U7K5EK1341103320
51004	MIN-40-GATS-04	4U7K5EK1041103419
51005	MIN-40-GATS-04	4U7K5EK1741103420
51006	MIN-40-GATS-04	4U7K5EK1941103421
51007	MIN-40-GATS-04	4U7K5EK1041103422
51008	MIN-40-GATS-04	4U7K5EK1241103423
51009	MIN-40-GATS-04	4U7K5EK1441103424
51010	MIN-40-GATS-04	4U7K5EK1641103425
51011	MIN-40-GATS-04	4U7K5EK1841103426
51012	MIN-40-GATS-04	4U7K5EK1X41103427
51013	MIN-40-GATS-04	4U7K5EK1141103428
51014	MIN-40-GATS-04	4U7K5EK1341103429
51015	MIN-40-GATS-04	4U7K5EK1X41103430
51016	MIN-40-GATS-04	4U7K5EK1141103431
51017	MIN-40-GATS-04	4U7K5EK1341103432
51018	MIN-40-GATS-04	4U7K5EK1541103433
51019	MIN-40-GATS-04	4u7k5ek1741103434
51020	MIN-40-GATS-04	4U7K5EK1941103435
51021	MIN-40-GATS-04	4U7K5EK1041103436
51022	MIN-40-GATS-04	4U7K5EK1241103437
51023	MIN-40-GATS-04	4U7K5EK1441103438

COACH LISTING

04V-463

Coach#	Model	VIN
51024	MIN-40-GATS-04	4U7K5EK1641103439
51025	MIN-40-GATS-04	4U7K5EK1241103440
51026	MIN-40-GATS-04	4U7K5EK1441103441
51027	MIN-40-GATS-04	4U7K5EK1641103442
51028	MIN-40-GATS-04	4U7K5EK1841103443
51029	MIN-40-GATS-04	4U7K5EK1341103527
51030	MIN-40-GATS-04	4U7K5EK1541103528
51031	MIN-40-GATS-04	4U7K5EK1741103529
51032	MIN-40-GATS-04	4U7K5EK1341103530
51033	MIN-40-GATS-04	4U7K5EK1541103531
51034	MIN-40-GATS-04	4u7k5ek1741103532
51035	MIN-40-GATS-04	4U7K5EK1941103533
51036	MIN-40-GATS-04	4U7K5EK1041103534
51037	MIN-40-GATS-04	4U7K5EK1341103544
51038	MIN-40-GATS-04	4U7K5EK1541103545
51039	MIN-40-GATS-04	4U7K5EK1741103546
51040	MIN-40-GATS-04	4U7K5EK1941103547
51041	MIN-40-GATS-04	4U7K5EK1641103568
51042	MIN-40-GATS-04	4U7K5EK1841103569
51043	MIN-40-DV-ABD-04	4U7K5EK1441103570
51044	MIN-40-GATS-04	4U7K5EK1X41103573
51045	MIN-40-GATS-04	4U7K5EK1941103581
51046	MIN-40-GATS-04	4U7K5EK1041103582
51047	MIN-40-GATS-04	4U7K5EK1241103583
51048	MIN-40-GATS-04	4U7K5EK1X41103587
51049	MIN-40-GATS-04	4U7K5EK1X41103590
51050	MIN-40-DV-ABD-04	4U7K5EK1141103591
51051	MIN-40-DV-ABD-04	4U7K5EK1341103592
51052	MIN-40-GATS-04	4U7K5EK1941103595
51053	MIN-40-GATS-04	4U7K5EK1X41103606
51054	MIN-40-GATS-04	4U7K5EK1141103607
51055	MIN-40-GATS-04	4U7K5EK1341103608
51056	MIN-40-DV-ABD-04	4U7K5EK1141103610
51057	MIN-40-DV-ABD-04	4U7K5EK1341103611
51058	MIN-40-DV-ABD-04	4U7K5EK1541103612
51059	MIN-36-SA-ABCD-04	4U7K5DK1441103613
51060	MIN-40-DV-ABD-04	4U7K5EK1041103615
51061	MIN-40-DV-ABD-04	4U7K5EK1841103619
51062	MIN-40-DV-ABD-04	4U7K5EK1441103620
51063	MIN-40-DV-ABD-04	4U7K5EK1641103621
51064	MIN-36-SA-ABCD-04	4U7K5DK1541103622
51065	MIN-40-DV-ABD-04	4U7K5EK1741103630
51066	MIN-40-GATS-04	4U7K5EK1941103631
51067	MIN-40-DV-ABD-04	4U7K5EK1041103632
51068	MIN-40-DV-ABD-04	4U7K5EK1241103633

COACH LISTING

04V-463

Coach#	Model	VIN
51069	MIN-36-SA-ABCD-04	4U7K5DK1241103660
51070	MIN-36-SA-ABCD-04	4U7K5DK1441103661
51071	MIN-36-SA-ABCD-04	4U7K5DK1641103662
51072	MIN-36-SA-ABCD-04	4U7K5DK1841103663
51073	MIN-36-SA-ABCD-04	4U7K5DK1X41103664
51074	MIN-36-SA-ABCD-04	4U7K5DK1141103665
51075	MIN-36-SA-ABCD-04	4U7K5DK1341103666
51076	MIN-36-SA-ABCD-04	4U7K5DK1541103667
51077	MIN-36-SA-ABCD-04	4U7K5DK1641103676
51078	MIN-40-DV-ABD-04	4U7K5EK1041103677
51079	MIN-40-DV-ABD-04	4U7K5EK1241103678
51080	MIN-40-DV-ABD-04	4U7K5EK1441103679
51081	MIN-40-DV-ABD-04	4U7K5EK1141103686
51082	MIN-36-SA-ABCD-04	4U7K6DK1441103687
51083	MIN-36-SA-ABCD-04	4U7K6DK1641103688
51084	MIN-40-DV-ABD-04	4U7K6EK1041103689
51085	MIN-36-SA-ABCD-04	4U7K6DK1541103696
51086	MIN-36-SA-ABCD-04	4U7K6DK1741103697
51087	MIN-40-DV-ABD-04	4U7K6EK1141103698
51088	MIN-36-SA-ABCD-04	4U7K6DK1041103699
51089	MIN-36-SA-ABCD-04	4U7K6DK1341103700
51090	MIN-40-GATS-04	4U7K6EK1841103701
51091	MIN-36-SA-ABCD-04	4U7K6DK1741103702
51092	MIN-40-DV-ABD-04	4U7K6EK1141103703
51093	MIN-40-DV-ABD-04	4U7K6EK1141103720
51094	MIN-36-SA-ABCD-04	4U7K6DK1041103721
51095	MIN-40-GATS-04	4U7K6EK1541103722
51096	MIN-36-SA-ABCD-04	4U7K6DK1441103723
51097	MIN-40-DV-ABD-04	4U7K6EK1941103724
51098	MIN-36-SA-ABCD-04	4U7K6DK1841103725
51099	MIN-36-SA-ABCD-04	4U7K6DK1X41103726
51100	MIN-40-DV-ABD-04	4U7K6EK1441103727
51101	MIN-36-SA-ABCD-04	4U7K6DK1441103737
51102	MIN-40-DV-ABD-04	4U7K6EK1941103738
51103	MIN-36-SA-AD-04	4U7K6DK1841103739
51104	MIN-36-SA-ABCD-04	4U7K6DK1441103740
51105	MIN-36-SA-ABCD-04	4U7K6DK1041103752
51106	MIN-36-SA-ABCD-04	4U7K6DK1241103753
51107	MIN-36-SA-ABCD-04	4U7K6DK1441103754
51108	MIN-36-SA-ABCD-04	4U7K6DK1641103755
51109	MIN-40-DV-ABD-04	4U7K6EK1641103762
51110	MIN-36-SA-ABCD-04	4U7K6DK1541103763
51111	MIN-36-SA-ABCD-04	4U7K6DK1741103764
51112	MIN-36-SA-ABCD-04	4U7K6DK1941103765
51113	MIN-36-SA-ABCD-04	4U7K6DK1041103766

COACH LISTING

04V-463

Coach#	Model	VIN
51114	MIN-40-DV-ABD-04	4U7K6EK1541103767
51115	MIN-36-SA-ABCD-04	4U7K6DK1441103768
51116	MIN-40-GATS-04	4U7K6EK1941103769
51117	MIN-36-SA-ABCD-04	4U7K6DK1241103770
51118	MIN-40-GATS-04	4U7K6EK1741103771
51119	MIN-36-SA-ABCD-04	4U7K6DK1641103772
51120	MIN-40-DV-ABD-04	4U7K6EK1041103773
51121	MIN-40-GATS-04	4U7K6EK1141103801
51122	MIN-36-SA-ABD-04	4U7K6DK1041103802
51123	MIN-40-DV-ABD-04	4U7K6EK1541103803
51124	MIN-40-DV-ABD-04	4U7K6EK1741103804
51125	MIN-40-DV-ABD-04	4U7K6EK1941103805
51126	MIN-36-SA-ACD-04	4U7K6DK1841103806
51127	MIN-36-SA-ACD-04	4U7K6DK1X41103807
51128	MIN-40-DV-ABD-04	4U7K6EK1141103829
51129	MIN-40-DV-ABD-04	4U7K6EK1841103830
51130	MIN-36-SA-ABCD-04	4U7K6DK1741103831
51131	MIN-40-GATS-04	4U7K6EK1141103832
51132	MIN-40-GATS-04	4U7K6EK1341103833
51133	MIN-40-DV-ABD-04	4U7K6EK1541103834
51134	MIN-36-SA-ABCD-04	4U7K6DK1441103835
51135	MIN-40-DV-ABD-04	4U7K6EK1941103836
51136	MIN-36-SA-ACD-04	4U7K6DK1841103837
51137	MIN-36-SA-ACD-04	4U7K6DK1141103839
51138	MIN-40-GATS-04	4U7K6EK1041103840
51139	MIN-36-SA-ABCD-04	4U7K6DK1X41103841
51140	MIN-36-SA-ABCD-04	4U7K6DK1141103842
51141	MIN-40-GATS-04	4U7K6EK1641103843
51142	MIN-40-DV-ABD-04	4U7K6EK1541103851
51143	MIN-36-SA-ABD-04	4U7K6DK1441103852
51144	MIN-36-SA-ABCD-04	4U7K6DK1641103853
51145	MIN-36-SA-ABCD-04	4U7K6DK1841103854
51146	MIN-40-GATS-04	4U7K6EK1241103855
51147	MIN-36-SA-ABCD-04	4U7K6DK1941103863
51148	MIN-40-GATS-04	4U7K6EK1341103864
51149	MIN-40-GATS-04	4U7K6EK1541103865
51150	MIN-40-DV-ABD-04	4U7K6EK1741103866
51151	MIN-40-DV-ABD-04	4U7K6EK1941103867
51152	MIN-40-DV-ABD-04	4U7K6EK1041103868
51153	MIN-40-DV-ABD-04	4U7K6EK1241103869
51154	MIN-40-DV-ABD-04	4u7k6ek1941103870
51155	MIN-36-SA-ABCD-04	4U7K6DK1841103871
51156	MIN-40-DV-ABD-04	4U7K6EK1241103872
51157	MIN-40-GATS-04	4U7K6EK1441103873
51158	MIN-36-SA-ABCD-04	4U7K6DK1X41103886

COACH LISTING

04V-463

Coach#	Model	VIN
51159	MIN-40-DV-ABD-04	4u7k6ek1441103887
51160	MIN-40-DV-ABD-04	4U7K6EK1641103888
51161	MIN-40-GATS-04	4U7K6EK1441103890
51162	MIN-40-GATS-04	4U7K6EK1641103891
51163	MIN-40-GATS-04	4U7K6EK1841103892
51164	MIN-40-GATS-04	4U7K6EK1X41103893
51165	MIN-36-SA-ABCD-04	4U7K6DK1941103894
51166	MIN-40-DV-ABD-04	4U7K6ES1341103895
51167	MIN-40-DV-ABD-04	4U7K6EK1341103914
51168	MIN-40-DV-ABD-04	4U7K6EK1541103915
51169	MIN-36-SA-ABCD-04	4U7K6DK1441103916
51170	MIN-36-SA-AD-04	4U7K6DK1641103917
51171	MIN-36-SA-ABCD-04	4U7K6DK1841103918
51172	MIN-40-GATS-04	4U7K6EK1241103919
51173	MIN-40-DV-ABD-05	4U7K6ES1751103920
51174	MIN-36-SA-ABCD-05	4U7K6DS1651103921
51175	MIN-40-GATS-05	4U7K6ES1051103922
51176	MIN-40-DV-ABD-05	4U7K6ES1251103923
51177	MIN-40-GATS-05	4U7K6ES1451103924
51178	MIN-36-SA-ABCD-05	4U7K6DS1351103925
51179	MIN-36-SA-ABCD-05	4U7K6DS1051103929
51180	MIN-40-DV-ABD-05	4U7K6ES1X51103930
51181	MIN-40-DV-ABD-05	4U7K6ES1151103931
51182	MIN-40-DV-ABD-05	4U7K6ES1351103932
51183	MIN-40-DV-ABD-05	4U7K6ES1551103933
51184	MIN-36-SA-ABCD-05	4U7K6DS1451103934
51185	MIN-36-SA-ABCD-05	4U7K6DS1151103938
51186	MIN-36-SA-ABCD-05	4U7K6DS1351103939
51187	MIN-40-DV-ABD-05	4U7K6ES1X51103944
51188	MIN-36-SA-ABCD-05	4U7K6DS1951103945
51189	MIN-40-DV-ABD-05	4U7K6ES1351103946
51190	MIN-40-DV-ABD-05	4U7K6ES1551103947
51191	MIN-36-SA-ABD-05	4U7K6DS1551103957
51192	MIN-40-GATS-05	4U7K6ES1X51103958
51193	MIN-36-SA-ABD-05	4U7K6DS1951103959
51194	MIN-36-SA-ABCD-05	4U7K6DS1551103960
51195	MIN-40-DV-ABD-05	4U7K6ES1X51103961
51196	MIN-36-SA-ABCD-05	4U7K6DS1951103962
51197	MIN-40-DV-ABD-05	4U7K6ES1851103988
51198	MIN-36-SA-ABCD-05	4U7K6DS1751103989
51199	MIN-40-DV-ABD-05	4U7K6ES1651103990
51200	MIN-40-DV-ABD-05	4U7K6ES1851103991
51201	MIN-40-GATS-05	4U7K6ES1X51103992
51202	MIN-40-DV-ABD-05	4U7K6ES1151103993
51203	MIN-36-SA-ABCD-05	4U7K6DS1451104002

COACH LISTING

04V-463

Coach#	Model	VIN
51204	MIN-40-GATS-05	4U7K6ES1951104003
51205	MIN-36-SA-ABCD-05	4U7K6DS1851104004
51206	MIN-40-GATS-05	4U7K6ES1251104005
51207	MIN-40-GATS-05	4U7K6ES1451104006
51208	MIN-40-GATS-05	4U7K6FS1651104007
51209	MIN-36-SA-ABCD-05	4U7K6DS1951104013
51210	MIN-40-DV-ABD-05	4U7K6ES1351104014
51211	MIN-36-SA-ABCD-05	4U7K6DS1251104015
51212	MIN-36-SA-ABCD-05	4U7K6DS1451104016
51213	MIN-40-DV-ABD-05	4U7K6ES1951104017
51214	MIN-40-DV-ABD-05	4U7K6ES1051104018
51215	MIN-36-SA-ABCD-05	4U7K6DS1351104024
51216	MIN-36-SA-ABCD-05	4U7K6DS1551104025
51217	MIN-40-GATS-05	4U7K6ES1X51104026
51218	MIN-40-DV-ABD-05	4U7K6ES1151104027
51219	MIN-36-SA-ABCD-05	4U7K6DS1051104028
51220	MIN-36-SA-ABCD-05	4U7K6DS1251104029
51221	MIN-40-DV-ABD-05	4U7K6ES1551104046
51222	MIN-36-SA-ABCD-05	4U7K6DS1451104047
51223	MIN-40-DV-ABD-05	4U7K6ES1951104048
51224	MIN-40-GATS-05	4U7K6ES1051104049
51225	MIN-40-GATS-05	4U7K6ES1751104050
51226	MIN-40-DV-ABD-05	4U7K6ES1951104051
51227	MIN-40-DV-ABD-05	4U7K6ES1051104052
51228	MIN-40-DV-ABD-05	4U7K6ES1251104053
51229	MIN-40-DV-ABD-05	4U7K6ES1451104054
51230	MIN-40-DV-ABD-05	4U7K6ES1651104055
51231	MIN-36-SA-ABCD-05	4U7K6DS1551104056
51232	MIN-40-DV-ABD-05	4U7K6ES1X51104057
51233	MIN-40-DV-ABD-05	4U7K6ES1151104058
51234	MIN-40-GATS-05	4U7K6ES1551104077
51235	MIN-36-SA-ABCD-05	4U7K6DS1451104078
51236	MIN-40-GATS-05	4U7K6ES1951104079
51237	MIN-40-DV-ABD-05	4U7K6ES1551104080



VEHICLE SAFETY
DEFECT NOTICE

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

November 8, 2004

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 04V-463

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach, Inc. has decided that a safety defect exists on certain motor homes it manufactured. LP cook tops were installed with a flexible rubber hose listed for use with LP gas. The use of multiple burners or the use of oversized cooking vessels could cause heat to collect inside the cook top base and result in the melting or burning of the flexible rubber hose. If undetected the hose could burn through and result in a LP gas fed fire.

MODELS AFFECTED:

Model Year: 2004 Allure Motorhomes manufactured from July 2003 to May 2004

Model Year: 2004 Inspire Motorhomes manufactured from May 2003 to March 2004

Model Year: 2005 Inspire Motorhomes manufactured from March 2004 to May 2004

A listing of all affected motorhomes is attached to this letter.

Country Coach has determined that the repair for this safety defect will be the replacement of the flexible rubber hose with copper tubing. The repair and associated parts will be performed and provided at no cost to the owner. The labor required to remove and replace the flexible rubber hose is not expected to exceed one and one-half (1.5) hours. Please present this letter and the enclosed warranty claim to the dealer when you take your motor home in to be serviced. The service facility that does the repairs will need the warranty claim for their billing.

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

Page 1

VEHICLE SAFETY
DEFECT NOTICE

If you need assistance in locating your nearest Country Coach dealer, please contact Country Coach's customer service department at 1-800-452-8015. The service department will refer you to a service facility near you. Country Coach has provided all of its dealers with instructions for making the necessary repairs. If your dealer fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Country Coach customer service by calling 1-800-452-8015 and ask for the Technical Service Representative handling this recall.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Country Coach Inc. Compliance Administration at 1-800-452-8015, extension 382.

If after contacting both your dealer and Country Coach you are not satisfied that the noncompliance has been remedied within a reasonable time, and at no cost to you, you may wish to contact the National Highway Traffic Safety Administration at the following address or call the Auto Safety Hotline's toll free number:

Administrator
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington D.C. 20590

Auto Safety Hotline's toll free number: 1-888-327-4236.

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

Enclosures (2): Vehicle Reply Card
Warranty Claim

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.
Gary Obermire, Vice President, Engineering, Country Coach, Inc.