



S-TYPE

DATE 01/05

7-29USA

SERVICE

ADMINISTRATION BULLETIN

**Brake Fluid Reservoir Warning Obscured –
New Brake Fluid Warning Label –
RECALL R171**

MODEL 2005 MY
S-TYPE
VIN N13089-N35567

Issue:

The plenum chamber finisher obscures the existing embossed warning on the brake fluid reservoir. Therefore, Jaguar Cars is not in compliance with the Federal Motor Vehicle Safety Standard (FMVSS) 135 requirement. As a result, a new brake fluid warning label must be applied to the plenum chamber finisher.

Jaguar Cars will conduct an owner notification campaign. Labels will be sent to customers for 2005 S-TYPE vehicles within the above VIN range. A copy of the customer letter is attached.

Action:

None - this bulletin is for information only.
No action is required by dealers since the label will be mailed directly to customers.

RECALL





JAGUAR CARS
555 MacARTHUR BOULEVARD
MAHWAH NJ 07430
T 800 4 JAGUAR
www.jaguar.com

December 2004

RE: R-171 Recall - Brake Fluid Reservoir Warning Label

Vehicles Affected: 2005 MY S-TYPE

Dear Jaguar Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Jaguar Cars has decided that the brake fluid reservoir warning statement on certain vehicles fails to conform to Federal Motor Vehicle Safety Standard No.135, "Passenger Car Brake Systems."

If you are a recipient of this notice, and an owner of one of the vehicles within the VIN range listed below, this letter is to inform you that your vehicle is included in this recall.

> R171 Brake Fluid Warning Label 2005 S-TYPE N13089-N35567

What is the Concern?

The leaf screen finisher located at the base of the windshield obscures the existing embossed warning on brake fluid reservoir. Therefore your vehicle is not in compliance with the Federal Motor Vehicle Safety Standard "FMVSS" 135 requirement. Additionally, there is a potential risk of using the incorrect specification brake fluid as a result of the warning statement being obscured. Using the incorrect brake fluid could affect the performance of your vehicles braking system. A listing of all recommended fluids can be found in your owner's handbook.

What should you do?

Obtain the new brake fluid warning label enclosed with this mailing and affix it to your vehicle. Detailed fitting instructions are contained on the next page.

How long will it take?

The time to affix a new label to the leaf screen is less than 2 minutes.

Moved or no longer own a Jaguar?

Please fill out the enclosed postage-paid card and return it to Jaguar by simply putting it in the mail.

Attention Leasing Agencies:

Federal regulation requires that you forward this recall notice to the lessee within 10 days.

What should you do if you have further questions?

Please contact your authorized Jaguar Dealer or the Jaguar Customer Relationship Center at 1 800 4JAGUAR (1-800-452-4827), option 9, by e-mail at jaguarowner@jaguar.com, or by mail using the return address listed above.

If you are unable to perform this action please contact the nearest authorized Jaguar Dealer for assistance.


Sincerely,



Benjamin I. Weiner
Customer Satisfaction Manager

Brake Fluid Warning Label - Fitting Instructions

1. Open hood.
2. Locate the leaf screen finisher at the base of the windshield. (Above brake fluid reservoir)
3. Clean the area where the label is to be located using a suitable cleaner. (See photo below)
4. Remove paper backing and affix the new label to leaf screen finisher.
5. Repair Complete.



View From Front of Vehicle