

04V-564

IMPORTANT SAFETY RECALL REMINDER

In December 2004 we notified you of a Safety Recall involving the side stand spring bolt on all **2002 VTX1800C/R** motorcycles. We advised owners that:

The washer for the side stand spring bolt does not have sufficient hardness and may deform, which could cause the bolt to flex and eventually break during side stand operation. In limited circumstances, a retracted side stand could drop while riding, possibly activating the side stand ignition cut-off system. If the ignition is cut, the engine will stall without warning, which could cause a crash.

According to our records, you have not yet had your affected 2002 VTX1800C/R repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. There are now sufficient parts to complete the repair on your motorcycle. **This repair is done free of charge.**

If you have already had your 2002 VTX1800C/R repaired, please let us know by calling toll-free at (866) 784-1870. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,
American Honda Motor Co., Inc.
Motorcycle Division

MTB 10910