

INITIAL DEFECT INFORMATION

05V219
2P.55

(Use separate sheets if insufficient space)

DATE: 5/6/05

1. NAME AND ADDRESS OF COMPANY: DUCATI NORTH AMERICA, INC.
10443 BANDLEY DRIVE
CUPERTINO CA 95014

2. CLASS(S) OF VEHICLES AFFECTED: MONSTER 620 - S2R -
MONSTER 1000 AND S4R MODELS

3. MAKE, MODEL(S) AND MODEL YEAR(S): DUCATI MOTORCYCLES
MONSTER 620 - MONSTER S2R - MONSTER 1000
MONSTER S4R MY 2005

4. VEHICLE IDENTIFICATION NUMBER(S) 117 UNITS - VIN #
PROVIDED WITH IDENTIFICATION LETTERS.

5. TOTAL QUANTITY OF VEHICLES INVOLVED: 117 UNITS.

RECEIVED
2005 JUN 13 P 1:25
OFFICE OF THE ATTORNEY GENERAL

6. DESCRIPTION OF DEFECT: INCORRECT REAR SHOCK ASSEMBLY
BUCKER ARM INSTALLED DURING PRODUCTION

7. SAFETY REGULATION(S)/STANDARD(S) AFFECTED: 573.6 - 577

8. MEASURES TAKEN TO CORRECT DEFECT DEALER WILL INSPECT
AND REPLACE (IF NECESSARY) THE
SHOCK - ASSEMBLY BUCKER ARM.

PREPARED BY RENATO AIME TELEPHONE: (214) 2648327
TITLE: SERVICE - WARRANTY MANAGER

AFTER COMPLETION MAIL OR FACSIMILE TO THE ATTENTION OF:

MR. PATRICIA WALLACE - MS. DELIA LOPEZ
NATIONAL HIGHWAY
TRAFFIC SAFETY
ADMINISTRATION

FAX: 202-366-7882