

CRANE CARRIER COMPANY

August 16, 2005

Patricia Wallace
National Highway Traffic Safety Administration
Department of Transportation
400 Seventh Street, SW
Washington, DC 20590

05V-380
(1 page)

Via Fax: (202) 366-7882

Dear Ms. Wallace:

On August 12, 2005, Crane Carrier Company (manufacturer) decided that a defect related to motor vehicle safety exists in certain motor vehicles, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR, Part 573.6, Defect and Noncompliance Information Report.


Manufacturer: Crane Carrier Company
1925 N. Sheridan Rd.
Tulsa, OK 74158

Contact: Jeffrey L. Carpenter
Director of Service
Phone: (918) 832-7305
Fax: (918) 832-7333

The safety defect relates to a mechanical interference that may exist between the throttle pedal and an access plug in the cab sheet metal. The throttle pedal may contact the access plug and not return to the idle position causing loss of control and vehicle crash without prior warning.

Crane Carrier will supply NHTSA the cause, scope, remedy, and a complete list of affected vehicles as soon as the research is complete. Additionally, a draft copy of the Owner Notification Letter will be sent for review.

Sincerely,



Jeffrey Carpenter
Director of Service