

GM SERVICE AND PARTS OPERATIONS
DCS1331
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 3, 2005

Subject: Upcoming Noncompliance Recall
05002 / Windshield Glass Adhesion

Model: 2005 Buick Rainer
2005 Chevrolet Trailblazer
2005 GMC Envoy

To: All Buick, Chevrolet and GMC Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Used Car
Manager, Service Manager, Parts Manager and Warranty
Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) web site, the media may report that General Motors will be announcing a noncompliance recall involving certain 2005 model year Buick Rainer, Chevrolet Trailblazer and GMC Envoy vehicles.

These vehicles fail to conform to Federal Motor Vehicle Safety Standard 212 - Windshield Mounting. The windshield urethane bead on some of these vehicles may not have adhered to the body in certain areas during the cure process. In vehicles with this condition, the windshield may not be retained in accordance with the safety standard during a vehicle crash. The vehicles were built at the Moraine Assembly Plant from November 3, 2004 through December 7, 2004.

To correct this condition, dealers will replace the windshield on all involved vehicles. This repair will be performed at no charge to the customer.

Approximately 18,000 vehicles are involved. GM is working with its suppliers to obtain the parts needed to correct this condition as quickly as possible. Based on the anticipated schedule, we plan to notify customers about this recall on March 10, 2005.

GMVIS information for this recall will not be available until the recall bulletin is released to dealers on March 3, 2005.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS