

## View Message

Sent On 01/31/2004

Expires On 02/10/2005

From American Honda Auto Engineering

Subject 2005 Odyssey & Pilot Stop Sale Order

Message **PRIORITY**

To: All Honda Service & Sale Managers  
From: Auto Engineering/Technical Research & Support  
Re: 2005 Odyssey & Pilot Stop Sale Order

If you receive this iN message, you may currently have vehicles that are affected by this ORDER.

### Background

American Honda (AHM) has a potential situation involving some 2005 Odysseys and 2005 Pilots that may currently be in your inventory or en route to your dealership.

Please be advised, the factory has reviewed this issue and has confirmed that the attached inspection procedures (below) must be performed on the Lower Steering Joint on any 2005 Odyssey or 2005 Pilot found on the list. To view the inspection procedures, please click on the link attached below.

Also below is a list of (sequential) dealer numbers and Vehicle Identification Numbers (VIN). You are to locate your dealer number and any VIN(s) listed beside your dealer number will need to have the Lower Steering Joint inspected.

NOTE: If you encounter a VIN on the list and the vehicle has been sold, you **must** contact the customer, instruct them not to drive the vehicle, have the vehicle towed back to your dealership, and put the customer in a rental.

Once the inspection has been performed, please use the information below to submit a warranty claim for dealer payment.

### Warranty Information

Labor Operation Code: 510501  
Flat Rate Time: 0.3 hour  
Failed Part Number: 53323-S5A-003, H/C 6455521  
Defect Code: 5DL00  
Symptom Code: P7000

***Click here to view inspection procedures***

DLR #	VIN	DLR #	VIN	DLR #	VIN
206572	5FNRL38475B404252	207385	5FNRL38465B404243	208011	5FNRL38445B404211
206592	5FNRYF185X5B016951	207447	5FNRYF18575B016938	208016	5FNRYF18595B016939
206594	5FNRYF18545B016976	207793	5FNRL38435B404863	208120	5FNRL38435B404247
206601	5FNRYF18525B016975	207793	5FNRL38485B404650	208187	5FNRL38435B404846
206602	5FNRYF18545B017156	207805	5FNRL38495B404284	208193	5FNRL38465B404257
206620	5FNRYF18565B017529	207874	5FNRYF18505B016943	208193	5FNRL38485B404275

<b>206643</b>	5FNRL38405B404268	<b>207880</b>	5FNRYF18565B016963	<b>208216</b>	5FNRL38485B404244
<b>206754</b>	5FNRL38435B404250	<b>207914</b>	5FNRL38415B404232	<b>208216</b>	5FNRL384X5B404245
<b>206754</b>	5FNRL38455B404251	<b>207929</b>	5FNRL38415B404215	<b>208280</b>	5FNRL38475B404204
<b>206917</b>	5FNRL38425B404627	<b>207990</b>	5FNRL38475B404249	<b>208281</b>	5FNRL38415B404263
<b>207385</b>	5FNRL38405B404643	<b>208011</b>	5FNRL38425B404272	<b>208353</b>	5FNRL384X5B404228