

**GM SERVICE AND PARTS OPERATIONS
DCS1398
URGENT - DISTRIBUTE IMMEDIATELY**

Date: May 4, 2005

Subject: 05014 / Product Safety Recall
Ignition Relay Contamination
Service Procedure Revision

Models: 2004 Buick Rendezvous
2004 Pontiac Aztek

To: All Buick and Pontiac Dealers

Attention: Service Manager, Parts Manager and
Warranty Administrator

On April 27, 2005 General Motors announced Product Safety Recall 05014. Please be advised that the service procedure is being revised as follows.

Currently Step 2 states: "Locate the relay for Ignition-1 (60)"

The revised Step 2 will state: "Locate the relay for Ignition-1 (as Ignition-1 location may vary by engine type, refer to the diagram on the inside cover of the electrical center cover for specific location.)"

The Service Information System (SI) version of the recall bulletin will reflect this change in the near future. Please make sure that all affected service personnel are aware of this revision.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS