

**GM SERVICE AND PARTS OPERATIONS
DCS1397
URGENT - DISTRIBUTE IMMEDIATELY**

Date: May 2, 2005

Subject: Upcoming Safety Recall
05044 / Turn Signal/Hazard Flasher Module

Model: 2003-2004 Isuzu Ascender
2003-2004 Chevrolet TrailBlazer
2003-2004 GMC Envoy
2003-2004 Oldsmobile Bravada
2004 Buick Rainier

To: All Buick, Chevrolet, GMC, Isuzu and Oldsmobile Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Used Car
Manager, Service Manager, Parts Manager and Warranty
Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) web site, the media may report that General Motors will be announcing a safety recall involving certain 2003-2004 Isuzu Ascender, Chevrolet TrailBlazer, GMC Envoy and Oldsmobile Bravada, and 2004 Buick Rainier model vehicles.

The directional/hazard signals may not operate as designed. The driver may not be able to clearly signal their intentions to turn, change travel lanes, or potentially warn others of an impaired vehicle operating condition.

To correct this condition, dealers will replace the suspect flasher modules with a new flasher module designed with sealed relays and more durable contact material inside of the relays. This repair will be made at no charge to the customer.

Approximately 286,000 vehicles are involved. GM is working with its suppliers to obtain the required parts as quickly as possible. Dealers will be notified when a date is established for customer notification.

GMVIS information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS