

**GM SERVICE AND PARTS OPERATIONS  
DCS1497  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: December 14, 2005

Subject: 05068 - Product Safety Recall  
Front Wheel Speed Sensor Corrosion  
Additional States Included

Models: 1999-2002 Chevrolet Silverado  
2000-2002 Chevrolet Tahoe, Suburban  
2002 Chevrolet Avalanche  
1999-2002 GMC Sierra  
2000-2002 GMC Yukon, Yukon XL  
Located in the Severe Corrosion Areas Listed

To: Certain Chevrolet and GMC Dealers

Attention: Service Manager, Parts Manager  
and Warranty Administrator

Product Safety Recall 05068 was released on September 23, 2005 via GM Administrative Message WIR20050236 and included 14 states located in severe corrosion areas.

GM has decided to add the states of Delaware, Iowa, Missouri, Maryland, Minnesota, Wisconsin and the District of Columbia to this regional field action.

This decision is based on the analysis of statistical data that was compiled from several field surveys recently conducted by GM engineers. During the surveys, corrosion levels were measured on customer vehicles in these states.

An amended recall bulletin will be released in the near future and dealers will be advised when notification letters are mailed to involved customers. GMVIS information for the additional vehicles will not be available until the amended bulletin is released.

In the interim, if a customer living in Delaware, Iowa, Missouri, Maryland, Minnesota, Wisconsin or the District of Columbia has an involved vehicle and requests that it be repaired due to the subject condition, dealers should perform the service procedure described in recall bulletin 05068. Upon completion of the repair, dealers should use the appropriate V-labor operation from the bulletin and submit a warranty claim to their GM Area Service Manager for authorization and payment. This deviation from normal product recall procedures will remain in effect until the amended bulletin is released.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS