



Mack Trucks, Inc.

**Safety
Recall
ALERT**

Date: September 30, 2005 **Number:** SRA-517-004
To: All U.S. & Canadian Distributors
Attention: Service Manager, Warranty Manager, Parts Manager, Dealer Principal
From: Regulatory Affairs Department
Subject: Safety Recall, SC0307, Brake Cam Lube - Steer and Drive Axle, Grease Only

Safety Recall Summary:

There exists the potential that the brake cam tubes on the steer and drive axle may not have been greased. As a result of this, the brake cam journal may corrode which may lead to the brakes dragging.

The number of vehicles affected is approximately 1,408 (1,137 US, 220 Canada and 51 Export)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to insure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer. All Safety Recalls, which affect new or used inventory, must be performed before the vehicle is sold or leased.

Additionally, Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list is posted on the Truck Dealers Portal
- Repair Instructions are tentatively scheduled for release on October 13, 2005.
- Owner Notices are scheduled to be mailed on October 23, 2005.

Questions:

Contact the Regulatory Affairs Department at (336) 393-2233 if you have questions.