

March 30th, 2005

DEFECT NOTIFICATION

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act of U.S.A.

Prévost Car Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2001-2005 XLII-45 Coaches, 2001-2005 XLII-45 MTH Entertainer, 2003-2004 H3-45 VIP Entertainer and 2002-2005 H3-41 & H3-45 Coaches. Prévost Car Inc., as coach manufacturer, has recently noticed that:

On the previously mentioned vehicles, premature power steering hose wear located in the engine compartment, baggage compartments and in the front service compartment might occur and thus in the long term cause power steering break down. Inspect the hoses mentioned in the safety recall and replace them if there is evidence of wear. For more information or help on how to perform this safety recall, contact your service manager or the nearest service center.

Model	Serial Numbers
XLII-45 Entertainer Model Year : 2001 – 2005	From 2PCY3349311027428 up to 2PCY3349X51028369 incl.
XLII-45 Coaches Model Year : 2001 – 2005	From 2PCX3349911027493 up to 2PCX3349851028513 incl.
H3-41 & H3-45 Coaches Model Year : 2002 – 2005	From 2PCH3349821014403 up to 2PCH3349X51010094 incl.
H3-45 VIP Entertainer Model Year : 2003 – 2004	2PCV3349131014442 – 2PCV3349431014449 – 2PCV3349431014452 2PCV3349131014456 – 2PCV3349531014458 – 2PCV3349331014460 2PCV3349931014463 – 2PCV3349231014465 – 2PCV3349231014479 2PCV3349031014481 – 2PCV3349631014484 – 2PCV3349X31014486 2PCV3349331014491 – 2PCV3349431014497 – 2PCV3349631014503 2PCV3349X31014505 – 2PCV3349X31014519 – 2PCV3349031014531 2PCV3349831014535 – 2PCV3349331014541 – 2PCV3349031014545 2PCV3349331014555 – 2PCV3349031014559 – 2PCV3349231014563 2PCV3349631014565 – 2PCV3349331014572 – 2PCV3349831014583 2PCV3349031014593 – 2PCV3349131014604 – 2PCV3349831014616 2PCV3349031014643 – 2PCV3349231014644 – 2PCV3349131014683 2PCV3349031014688 – 2PCV3349031014691 – 2PCV3349831014695 2PCV3349731014719 – 2PCV3349731014722 – 2PCV3349631014727 2PCV3349231014742 – 2PCV3349431014743 – 2PCV3349X31014746 2PCV3349531014749 – 2PCV3349331014751 – 2PCV3349441014758 2PCV3349541014767 – 2PCV3349041014787 – 2PCV3349441014789 2PCV3349841014794 – 2PCV3349741014804 – 2PCV3349041014806 2PCV3349241014807 – 2PCV3349641014809 – 2PCV3349041014823 2PCV3349141014829

CORRECTIVE ACTIONS:

You must refer to the enclosed Safety Recall no. 05-07 and perform the stated procedure. Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

REPORTING REQUIREMENT:

In order to verify and document the corrective action taken on your vehicle(s) pursuant to the requirements of the Federal Motor Vehicle Safety Regulations, we are enclosing a "**SAFETY RECALL CERTIFICATION**" sheet. When the vehicle(s) is (are) repaired, this (these) sheet(s) must be completed and returned to PRÉVOST CAR INC. head office.

LABOR & PARTS REIMBURSEMENT:

Prévost Car Inc. will reimburse you parts and labor incurred.

Federal laws require that you be informed of your right to notify the Department of Transportation if you are unable to have the defect remedied without charge. The address for this purpose is:

National Highway Traffic Safety Administration

Washington, DC 20590


USA

Auto Safety Hotline: 1-888-327-4236.

If any assistance is required, please contact your local distributor or the PRÉVOST CAR INC. after sales service department.

We regret any inconvenience which this situation may cause you. However, we are concerned about your safety; rest assured that PRÉVOST CAR INC. is making all efforts to remedy the defect as quickly as possible in the interest of motor vehicle safety.

Truly yours,



Josyane Côté, Eng.
Technical Publications Manager.