

December 2005

IMPORTANT SAFETY RECALL INFORMATION

Dear VT750C Owner:

What is the reason for this notice?

Honda Motor Co., Ltd. has decided that a defect which relates to motor vehicle safety exists in certain 2006 model year VT750C motorcycles. A damaged connector in the handlebar mounted headlight switch may cause the headlight to flicker and eventually fail. If riding at night, the sudden loss of headlight operation could result in a crash.

What should you do?

Honda recommends that you avoid riding at night until your VT750C has been repaired. Parts to complete the repair will begin to arrive at dealerships the week of January 9, 2006. If you choose to continue riding after dark, ride cautiously and **be aware that the headlight could flicker and may fail completely. If you detect any problem with your headlight, stop riding and contact your Honda dealer.**

Honda will send you another letter when parts are available. At that time, we'll ask you to call any authorized Honda motorcycle dealer and make an appointment to have your VT750C repaired. The dealer will install new left and right handlebar switch assemblies. Although the repair will take less than two hours, please plan to leave your VT750C for a day to allow the dealer flexibility in scheduling.

Lessor Information.

Honda recommends that any vehicle lessor receiving this recall notice forward a copy of this notice to the lessee.

If you have questions.

If you have any questions about this notice, or need assistance with locating a Honda dealer, please call Honda Motorcycle Customer Service at (888) 327-4236.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

**American Honda Motor Co., Inc.
Motorcycle Division**