

Mercedes-Benz USA, LLC

Rolf Scherer General Manager, Engineering Services



VIA CERTIFIED MAIL

January 29, 2007

National Highway Traffic Safety Administration Attention: George Person, Chief, Recall Analysis Division 400 Seventh Street, SW Washington, D.C. 20590

Dear Mr. Person:

Please find the Quarterly Report of Defect Notification Campaigns for the quarter ending December 31, 2006.

Should you have any questions, please do not hesitate to contact Gary Bowne at 201-573-2719.

Sincerely,

Rolf Scherer General Manager, Engineering Services

RS: sk

Enclosure

MANUFACTURER QUARTER ENDING										
MERCEDES-BENZ USA, LLC. December 31										
MOTOR VEHICLE SAFETY DEFECT REPORT										
QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS										
MBUSA REFERENCE NUMBER		2005080007	2005110001	2006020005	2006040002	2006040003				
ABBREVIATED DESCRIPTION		G55 FUEL	E/CLS/SL	C-Class	R-Class	R-Class				
		RETURN	SBC	AIRBAG	STARTER	SEATBELT				
		LINE	BRACKET *1		HARNESS	BUCKLE				
REPORT NO.	(573.6)	5	5	4	3	3				
CAMPAIGN NO.	b(1)	05V-378	05V-133	05V-560	06V-098	06V-101				
DATE STARTED	b(2)	8/4/2005	12/6/2005	3/15/2006	5/12/2006	5/2/2006				
NOTIFICATION ENDED	b(2)									
NUMBER OF VEHICLES										
INVOLVED IN CAMPAIGN: b(3)		485	194776	60070	6290	2292				
REPAIRED: b(4i)		441	175072	51116	5548	43				
INSPECTED										
REPAIR NOT NEEDED: b(4ii)		0	0	0	0	1929				
CORRECTIVE MEASURES										
COMPLETED: b(5)		441	175072	51116	5548	1972				
UNREACHABLE	b(6)	0	21	5	15	0				
STOLEN		0	0	0	0	.0				
SCRAPPED		0	0		0	0				
SOLD-OWNER UNKNOWN		0	0		0	0				
OUT OF U.S.		0	0			0				
MOVED-NO ADDRESS		0		\$		0				
UNCLAIMED LETTER		0				0				
UNCOOPERATIVE		0	0		0	0				
COMPLETION PERCENT		90.93%	89.88%	85.09%	88.20%	86.04%				

MANUFACTURER					QUA	RTER ENDING				
MERCEDES-BENZ USA, LLC.	Dec	ember 31, 2006								
MOTOR VEHICLE SAFETY DEFECT REPORT										
QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS										
MBUSA REFERENCE NUMBER		2006060003	2006080005	2006080004						
ABBREVIATED DESCRIPTION		SLR	R170	CL/S						
1		ALTERNATOR	TAIL LAMP	INSTRUMENT						
				CLUSTER						
REPORT NO.	(573.6)	3	2	1						
CAMPAIGN NO.	b(1)	06V-220	05V-505	06V-028						
DATE STARTED	b(2)	6/23/2006	9/8/2006	9/27/2006						
NOTIFICATION ENDED	b(2)									
NUMBER OF VEHICLES										
INVOLVED IN CAMPAIGN: b(3)		422	32575	30417						
REPAIRED: b(4i)		332	11730	14347						
INSPECTED										
REPAIR NOT NEEDED: b(4ii)		0	0	0						
CORRECTIVE MEASURES										
COMPLETED: b(5)		332	11730							
UNREACHABLE	b(6)	2	3							
STOLEN		0	0							
SCRAPPED		0	0							
SOLD-OWNER UNKNOWN		0			-					
OUT OF U.S.		0		 						
MOVED-NO ADDRESS		0								
UNCLAIMED LETTER		0			!					
UNCOOPERATIVE		0		[,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
COMPLETION PERCENT		78.67%	36.01%	47.17%	l					

footnote *1:

The affected vehicles in these campaigns overlap and the repair needed varies with the serial number and model. Vehicles which were not repaired under 2004050014 (04V-296) are being repaired under 2005070007 (05V-133). Since vehicles which were unrepaired under 2004050014 are being repaired under 2005070007, those unrepaired vehicles will be "closed" in 2004050014.