



Mercedes-Benz

Mercedes-Benz USA, LLC

Rolf Scherer
General Manager, Engineering Services

VIA CERTIFIED MAIL

October 25, 2006

National Highway Traffic Safety Administration
Attention: George Person, Chief, Recall Analysis Division
400 Seventh Street, SW
Washington, D.C. 20590

Dear Mr. Person:

Please find the Quarterly Report of Defect Notification Campaigns for the quarter ending September 30, 2006.

Should you have any questions, please do not hesitate to contact Gary Bowne at 201-573-2719.

Sincerely,

A handwritten signature in black ink, appearing to read "Rolf Scherer".

Rolf Scherer
General Manager,
Engineering Services

RS: sk

Enclosure



MANUFACTURER
MERCEDES-BENZ USA, LLC.

QUARTER ENDING
September 30, 2006

MOTOR VEHICLE SAFETY DEFECT REPORT
QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS

MBUSA REFERENCE NUMBER ABBREVIATED DESCRIPTION	2006040002 R-Class STARTER HARNESS	2006040003 R-Class SEATBELT BUCKLE	2006060003 SLR ALTERNATOR	2006080005 R170 TAIL LAMP	
REPORT NO. (573.6)	2	2	2	1	
CAMPAIGN NO. b(1)	06V-098	06V-101	06V-220	05V-505	
DATE STARTED b(2)	5/12/2006	5/2/2006	6/23/2006	9/8/2006	
NOTIFICATION ENDED b(2)					
NUMBER OF VEHICLES					
INVOLVED IN CAMPAIGN: b(3)	6284	2292	421	32574	
REPAIRED: b(4i)	4877	33	265	4141	
INSPECTED					
REPAIR NOT NEEDED: b(4ii)	0	1680	0	0	
CORRECTIVE MEASURES					
COMPLETED: b(5)	4877	1713	265	4141	
UNREACHABLE b(6)	0	0	0	0	
STOLEN	0	0	0	0	
SCRAPPED	0	0	0	0	
SOLD-OWNER UNKNOWN	0	0	0	0	
OUT OF U.S.	0	0	0	0	
MOVED-NO ADDRESS	0	0	0	0	
UNCLAIMED LETTER	0	0	0	0	
UNCOOPERATIVE	0	0	0	0	
COMPLETION PERCENT	77.61%	74.74%	62.95%	12.71%	

footnote 1:

The affected vehicles in these campaigns overlap and the repair needed varies with the serial number and model. Vehicles which were not repaired under 2004050014 (04V-296) are being repaired under 2005070007 (05V-133). Since vehicles which were unrepaired under 2004050014 are being repaired under 2005070007, those unrepaired will be "closed" in 2004050014.