## GM SERVICE AND PARTS OPERATIONS

DCS1360

URGENT - DISTRIBUTE IMMEDIATELY

Date: March 9, 2005

Subject: 05039 / Safety Recall

Brake Pushrod Retaining Clip

Models: 2005 Chevrolet Tahoe and Suburban

2005 GMC Yukon and Yukon XL

2005 GMC Denali and and Denali XL

To: All Chevrolet and GMC Dealers

Attention: Service Manager, Parts Manager and

Warranty Administrator

#### PRODUCT FIELD ACTION ANNOUNCEMENT

General Motors is announcing Safety Recall 05039 today. The total number of vehicles involved is 916. Please see the attached bulletin for details. Also attached is a list of the involved vehicles. The list is sorted by dealer Business Associate Code (BAC) for easy reference. If your BAC is not listed, then none of the involved vehicles are assigned to your dealership

#### Customer Notification

GM will begin contacting customers of record via telephone on March 9, 2005. Customers who recently purchased or leased an involved vehicle are to be contacted by the selling dealer as the delivery report may still be in process.

GM Vehicle Inquiry System (GMVIS) GMVIS information will be available on March 10, 2005.

Service Information System (SI) Bulletin 05039 is scheduled to be available in SI on March 11, 2005.

Campaign Initiation Detail Report (CIDR)
A CIDR will not be available in GM DealerWorld for this recall.

PLEASE DOUBLE CLICK ON THE ICON BELOW THEN SINGLE CLICK ON THE LAUNCH BUTTON TO VIEW OR PRINT THE DOCUMENT

(See attached file: 05039 bulletin.pdf) (See attached file: 05039 US VINs.xls)

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS

File In Section: Product Recalls Bulletin No.: 05039

Date: March 2005









## PRODUCT SAFETY RECALL

**BRAKE PEDAL PUSHROD RETAINER** SUBJECT:

MODELS: 2005 CHEVROLET SUBURBAN, TAHOE

2005 GMC YUKON, YUKON XL

## CONDITION

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2005 Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles. Some of these vehicles have a condition in which the brake pedal pushrod retainer may be missing. If the retainer is missing, the brake booster pushrod could disengage from the brake pedal. resulting in a loss of brakes and a possible vehicle crash without prior warning.

## CORRECTION

Dealers are to inspect for the presence of the brake pedal pushrod retainer, and install one if it is missing.

## VEHICLES INVOLVED

Involved are certain 2005 Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles built within these VIN breakpoints:

YEAR	DIVISION	MODEL	FROM	THROUGH
2005	Chevrolet	Suburban	5J212963	5J218157
2005	Chevrolet	Tahoe	5J211423	5J218780
2005	GMC	Yukon	5J206278	5J218221
2005	GMC	Yukon XL	5J215251	5J218187

IMPORTANT: Dealers should confirm vehicle eligibility through GMVIS (GM Vehicle Inquiry System) prior to beginning recall repairs. [Not all vehicles within the above breakpoints may be involved.]

For US: For dealers with involved vehicles, a Campaign Initiation Detail Report containing the complete Vehicle Identification Number, customer name and address data has been prepared and will be loaded to the GM DealerWorld, Recall Information website. Dealers that have no involved vehicles currently assigned will not have a report available in GM DealerWorld.

For Canada: See the Dealer Communication VIN list attached to this email message for a listing of involved vehicles.

Bulletin No.: 05039

<u>For Export</u>: For dealers with involved vehicles, a Campaign Initiation Detail Report containing the complete Vehicle Identification Number, customer name and address data has been prepared, and is being furnished to involved dealers. Dealers that have no involved vehicles currently assigned will not receive a report with the recall bulletin.

The Campaign Initiation Detail Report may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.


## PARTS INFORMATION

It is anticipated that very few vehicles will require a brake pedal pushrod retainer. If one is needed, place orders on a CSO = Customer Special Order.


## SERVICE PROCEDURE

1. Inspect for the presence and proper installation of the brake pushrod retaining clip.

## Non Adjustable Brake Pedal Pushrod Retaining Clip (4)



# Adjustable Brake Pedal Pushrod Retaining Clip (3)



344194

1265181

2. Install a new clip if necessary.

## **COURTESY TRANSPORTATION**

The General Motors Courtesy Transportation Program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranty. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product recall is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no

charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for courtesy transportation guidelines.

### **CLAIM INFORMATION**

Submit a Product Recall Claim with the information indicated below:

REPAIR PERFORMED	PART COUNT	PART NO.	PARTS ALLOW	CC-FC	LABO R OP	LABOR HOURS
Inspect for Brake Pedal Pushrod Retaining Clip – No Further Action Req'd.	N/A	N/A	N/A	MA-96	V1328	0.2
Inspect & Install Brake Pedal Pushrod Retaining Clip	1		*	MA-96	V1329	0.2
Courtesy Transportation	N/A	N/A	N/A	MA-96	**	N/A

- \* The "Parts Allowance" should be the sum total of the current GMSPO Dealer net price plus applicable Mark-Up or Landed Cost Mark-Up (for Export) for the brake pedal pushrod retaining clip needed to complete the repair.
- \*\* Submit courtesy transportation using normal labor operations for courtesy transportation as indicated in the GM Service Policies and Procedures Manual.

Refer to the General Motors WINS Claims Processing Manual for details on Product Recall Claim Submission.

## **CUSTOMER NOTIFICATION - For US and CANADA**

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

## **CUSTOMER NOTIFICATION** – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

## <u>DEALER RECALL RESPONSIBILITY</u> – For US and Export (US States, Territories, and Possessions)

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Page 4 March 2005 Bulletin No.: 05039

## **DEALER RECALL RESPONSIBILITY - ALL**

All unsold new vehicles in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this recall bulletin <u>before</u> customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.

Bulletin No.: 05039

#### March 2005

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For This Recall: General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2005 Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles. Some of these vehicles have a condition in which the brake pedal pushrod retainer may be missing. If the retainer is missing, the brake booster pushrod could disengage from the brake pedal, resulting in a loss of brakes and a possible vehicle crash without prior warning.

What Will Be Done: Your GM dealer will inspect for the presence of the brake pedal pushrod retainer, and install one if it is missing. This service will be performed for you at **no charge**.

How Long Will The Repair Take? This inspection and service correction will take approximately 15 minutes. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

Contacting Your Dealer: To limit any possible inconvenience, we recommend that you contact your GM dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date. Should your dealer be unable to schedule a service date within a reasonable time, you should contact the appropriate Customer Assistance Center at the listed number below. The Customer Assistance Center's hours of operation are from 8:00 AM to 11:00 PM, EST, Monday through Friday.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	
Guam	1-671-648-8650	

If, after contacting the appropriate Customer Assistance Center, you are still not satisfied that we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590 or call 1-888-327-4236.

**Customer Reply Form:** The enclosed customer reply form identifies your vehicle. Presentation of this form to your dealer will assist in making the necessary correction in the shortest possible time. If you no longer own this vehicle, please let us know by completing the form and mailing it back to us.

Courtesy Transportation: If your vehicle is within the New Vehicle Limited Warranty your dealer may provide you with shuttle service or some other form of courtesy transportation while

your vehicle is at the dealership for this repair. Please refer to your Owner's Manual and your dealer for details on Courtesy Transportation.

**Owner Center Online:** This free online service offers vehicle and ownership related information and tools tailored to your specific vehicle. To get the most personalized information for your vehicle, visit **www.mygmlink.com**, and enter your vehicle's 17-character vehicle identification number (VIN) shown on the enclosed customer reply form.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

**General Motors Corporation** 

Enclosure 05039

VIN	BAC
1GKEC16T45J216833	BAC info in process
1GKEK13T95J217662	BAC info in process
1GKEK63U75J216760	BAC info in process
1GKFK66U25J217699	BAC info in process
1GNEC13T85J216826	BAC info in process
1GNEK13TX5J217656	BAC info in process
1GNFK16Z85J218051	BAC info in process
1GNFK16ZX5J216513	BAC info in process
1GNFK16Z75J216601	111153
1GKEK13T25J216627	111224
1GNEK13Z65J215519	111266
1GNFK16Z65J215522	111270
1GNEK13Z75J218199	111345
1GNEK13T95J218216	111494
1GNFK16Z45J215843	111501
1GNFK16Z05J217623	111769
1GNFK16ZX5J215510	111769
1GNFK16ZX5J215491	111792
1GNFK16Z15J215749	111928
1GNFK16ZX5J216592	112082
1GNEK13T35J214565	112141
1GKEK13T65J218171	112173
1GNFK16Z15J215623	112174
1GNFK16Z45J215566	112174
1GNFK16Z45J216636	112174
1GNFK16Z75J215612	112174
1GNFK16Z75J215660	112174
1GNFK16ZX5J215460	112174
1GNFK16ZX5J217385	112174
1GNEC13VX5J215520	112179
1GNEK13T85J216747	112180
1GKEC13Z55J215554	112276
1GNEC13T95J215586	112490
1GNEK13Z15J214567	112490
1GNEC16Z95J212963	112513
1GNEK13T85J217767	112741
1GNEK13T15J211423	112754
1GNEK13T05J218198	112919
1GNEK13TX5J218192	112940
1GNFK16ZX5J215877	112995
1GNEK13ZX5J215605	113062
1GNEK13Z65J215858	113111
1GNEK13TX5J215518	113137
1GNEC16Z45J216905	113171
1GNEC16Z25J215462	113171
1GNFK16Z05J215306	113209
1GNFK16Z45J215504	113209
1GNEC13V35J216590	113217
1GNFK16Z75J215741	113235
1GNFK16ZX5J216978	113235
1GNFK16ZX5J215779	113248

1GKFK66U65J215826	113251
1GNFK16Z25J215744	113252
1GNEK13T15J216699	113578
1GNEK13TX5J215874	113643
1GKFK66U85J217979	
1GKEK13T75J215618	113845
1GNEK13T75J216657	113861
1GNFK16Z65J215357	113923
1GNEC13T25J215574	114076
1GNEC13TX5J218092	114301
	114328
1GNEK13T95J213906	114393
1GNEK13T85J215341	114398
1GNEK13T45J218026	114484
1GNEK13T05J216659	114490
1GNEC13T15J215405	114561
1GNEC13T95J216964	114575
1GKEK63U05J216910	114583
1GKFK66U25J216696	114583
1GKFK66U35J215301	114583
	114626
1GNEK13TX5J215485	
1GNEC13T85J215773	114714
1GNEC13T85J218172	114714
1GNEC13T05J215475	114765
1GNEC13T35J215602	114765
1GNEC13T75J217966	114765
1GKEK63U15J215880	114847
1GNFK16Z15J215363	114925
1GNEK13T75J215833	114977
	115196
1GNFK16ZX5J215393	115196
1GNEK13T15J215729	115210
1GKFK16Z35J215538	115211
1GKFK16Z95J218024	115401
1GKFK16Z95J216032	115414
1GKEK13T55J217013	115425
1GKEK13T65J215853	115437
1GKEK63U15J216754	115515
	115521
1GKEK63U75J215656	115562
1GKEK63UX5J217871	115571
1GKFK66U25J216567	115571
1GKFK66U35J217744	115585
	S
1GKEK63U05J218155	115589
1GKEK63U75J215401	115614
1GKEK63U45J216764	115618
1GKEK63UX5J216669	115619
1GKFK66U65J215583	115634
1GKEK63U05J215384	115651
1GKEK63U35J215718	115653
1GKEK63U25J215628	115670
1GKEK63U95J217831	115688

1GKEK13T65J215884	115694
1GKFK66U85J218064	115694
1GNEK13T05J216550	115713
1GKFK66U55J217759	115714
1GKEK63U35J215332	115731
1GKEK63U35J215976	115731
1GKEK13T35J215857	115779
1GKEK13T05J218179	115797
1GKEK63U65J216622	115802
1GKEK63U45J216781 1GKEK63U75J216581	115805
1GKFK66U45J216571	115822 115836
1GKEK63UX5J217031	115859
1GKFK66U75J215611	115871
1GKEK13T65J218154	115876
1GKEK13T25J215557	115882
1GKEK13T45J215382	115891
1GKEK13TX5J214365	115914
1GKEK63UX5J215506	115914
1GKFK66U55J215509	115915
1GKEK63U85J216573	115936
1GKEK63U85J215486	115958
1GKEK13T85J215840	115972
1GKEK13T85J215790	116058 116058
1GKEK63U25J216584 1GKEK63U35J215430	116064
1GKFK66U95J216937	116067
1GKFK63U35J217680	116096
1GKEK63U55J218149	116119
1GKFK16Z65J217719	116124
1GKFK66U95J215898	116124
1GKEK13T05J215556	116129
1GKEK13T25J218202	116129
1GKFK66U95J217750	116167
1GKEK63U25J215435	116168
1GKEK13T85J217815	116169
1GKFK66U15J215541	116169
1GKFK66U35J215685 1GKEK63U65J215423	116169
1GKFK66U75J217892	116178 116183
1GKEK63U75J216922	116195
1GKFK66U95J216534	116247
1GKEK63U35J217856	116265
1GKFK66U45J215825	116265
1GKEK63U45J214819	116273
1GKFK66U65J215535	116273
1GKFK66U95J215805	116303
1GKEC13T65J215719	116314
1GKEK63U15J215815	116335
1GKFK66U25J216990	116350
1GKFK66U95J217604 1GKEK63U25J215578	116351 116354
IGNEN03U23U2133/8	110004

1GKEC13Z85J215516	116358
1GKEC13T35J215581	116362
1GKEK63U35J215802	116370
1GKEK63U55J216028	116378
1GKEC13T35J217797	116384
1GKEC13T85J216712	116384
1GKEK63U65J215325	116397
1GKFK66UX5J215599	116401
	116404
1GKEK63UX5J216543	116408
1GKEC13T25J215572	116409
1GKFK66U25J215712	116415
1GKEK63U45J215727	116419
1GNEC13T55J218114	116427
1GNEC13T95J215409	116427
1GKFK66U05J215546	116444
1GKFK16Z65J215534	116448
1GKEK63U95J215822	116457
1GKEK63U65J215812	116490
1GKFK66U75J215642	116513
1GKEC13T85J218170	116537
1GKEC13T75J215695	116547
1GKEK63U45J215565	116555
1GKFK66U65J216930	116555
1GKFK66U65J217981	116555 116575
1GKEK63U75J216743	116581
1GKEK63U25J215502 1GKEK63U95J218221	116581
1GKFK66U55J216580	116581
1GKEK63U05J218060	116614
1GKFK66U75J215818	116614
1GKFK66U35J215721	116642
1GKEC13Z35J215911	116646
1GKEC16Z45J217999	116646
1GKEK63U15J216916	116688
1GKEK13T05J217968	116693
1GKEK13T95J215507	116693
1GKFK66U95J218140	116695
1GKFK66U45J215730	116697
1GKEK13T15J215842	116712
1GKEK63UX5J215649	116712
1GKFK66U15J216706	116712
1GKEK63U45J216635	116713
1GKEK13T05J216965	116735
1GKEK63U95J215352	116736
1GKEK63U45J215680	116738
1GKEK63U75J218119	116738
1GKFK66U95J218106	116738
1GKEK63UX5J216526	116739
1GKFK66U55J215932	116754
1GKEC13T05J218194	116792
1GKFK66U55J216711	116817

1GKFK16Z65J215484	117019
1GKEK63UX5J215635	117036
1GKFK66U15J215796	117048
1GKEK13T15J218174	117067
1GKEK13T25J215848	117067
	***************************************
1GKFK66U85J215682	117076
1GKFK66U75J215446	117128
1GKEK13T85J216535	117134
1GKEK13T35J215499	117140
1GKFK66U55J216563	117157
1GKEK13T05J217713	117247
1GKEK63U95J216730	
	and the second s
1GKFK66U35J215346	117305
1GKFK66U85J215441	117305
	117307
1GKFK16Z55J216903	117307
1GKEK63U05J216938	117308
1GKFK66U85J216556	117308
1GKEK13T85J206278	117338
1GKFK66U55J215381	117338
1GKFK66U95J216663	
1	117366
1GKEK13T45J215706	117454
1GKEK63U35J215878	117476
1GKEK63U65J217768	117558
1GKEK63U45J217834	117564
1GKEK63U05J215529	117580
1GKEK13T45J218184	117682
1GKEK13T75J218129	117682
1GKFK66U15J216768	117682
1GKEC13T75J217074	117735
	2.0.0.000 AMADE AND
1GKEK63UX5J218146	117735
1GKFK16Z15J215523	117735
1GKFK66U35J216688	117735
1GKEK63U85J215777	117746
1GKFK66U05J215613	117746
1GKFK66UX5J215490	117752
1GKEK13T95J215331	117774
1GKEK13T55J216640	117781
1GKFK16ZX5J218050	117781
1GKEK63U45J215386	117808
	A CONTRACTOR OF THE PROPERTY O
1GKEK63UX5J215683	
1GKEK63U45J216862	117825
1GKFK66U95J216811	117828
1GKEK63UX5J215411	117927
1GKEK13T35J215714	117946
1GKEK13Z45J218108	117981
1GKEK63U15J216771	117981
1GKEK63U75J216578	117981
CINCINOCO   OUL   OUI   O	
1CKEKEELISE 1246724	117082
1GKFK66U85J216721	117982
1GKFK66U25J216844	118025
	118025 118026

	1
1GKEK13Z95J215785	118035
1GKEK63U45J216697	118042
1GKEK63U55J215641 1GKEK63U05J216809	118218 118225
1GKEK13T55J218145	118233
1GKEC13V55J217057	118244
1GKEC13V65J215396	118244
1GKFK66UX5J217028	118251
1GKEK63U65J217897	118263
1GKEK63U65J215390	118276
1GKFK66U95J215769	118276
1GKEK63U75J215348	118281
1GKEK13T55J215620	118333
1GKEK63UX5J217983	118354
1GKEK63U65J215552	118416
1GKEK63U95J215383 1GKFK16Z85J215762	118416 118416
1GKFK10Z85J21570Z	118436
1GKFK66U95J215819	118445
1GKFK66U05J216860	118459
1GKEK63U75J217682	118464
1GKEK13T95J217659	118493
1GKEK13TX5J215290	118493
1GKEK13T15J215467	118496
1GKFK66UX5J215764	118522
1GKEC13T85J215835	118664
1GKEK13T05J217730	118668
1GKFK66U25J216813	118668
1GKEK63U05J216549	118677
1GKFK66U95J217893	118696 118697
1GKFK66U95J215949	118706
1GKEK13T05J218182	118712
1GKEK13TX5J218190	118712
1GKEK63U05J215532	118717
1GKEK63U45J215808	118732
1GKFK66U85J215780	118732
1GKEK63U35J215735	118733
1GKEK13Z65J215775	118738
1GKEK13Z55J215850	118743
1GKEK13T85J218091	118744
1GKEK13T95J215569	118753
1GKEK63U95J215562	118753
1GKEC13T55J215596	118945 119012
1GKFK66U55J215302 1GKEK63U75J215480	119012
1GKEK630753215460	119243
1GKEK63U35J215816	119253
1GKFK16ZX5J215472	119255
1GKEK13T05J215542	119272
1GKEK13Z85J218161	119284
1GKFK16Z55J216786	119284

	*
1GKEK13Z55J216593	119291
1GKEK13Z75J217048	119291
1GKEK13T35J218158	119293
1GKEK13TX5J216665	119293
1GKFK66U85J215830	119296
1GKEK13Z95J218167	119319
1GKEK13TX5J218142	119320
1GKEK13T65J216680	119320
1GKEK63U55J215512	119390
1GKEK13T15J215839	119429
1GKEK63U55J215347	119454
1GKEC13T05J216039	119564
1GKEC13T05J216591	119564
1GKEC13T25J218181	119564
1GKEC13T45J218151	119564
1GKEC13T95J216962	119564
1GKEK63U25J216679	119595
1GKEK63U85J215438	119595
1GKEC13Z05J215722	130557
1GKFK66U55J215350	130566
1GKFK66UX5J215733	130631
1GKEK13T55J216606	130700
1GKEK13T75J217725	130700
1GKEK63U65J216894	130782
1GKFK66U95J215335	130994
1GKFK66U35J215251	131066
1GKEK63U85J216539	131075
1GKEK63U25J215404	131077
1GKEK63U55J216577	131082
1GKFK66U15J217015	131160
1GKFK66U75J216662	131160
1GNEC16Z25J215882 1GKEC13T45J216819	132225 132250
1GNEK13T45J215580	132340
1GKEC16Z95J215701	132340
1GKEC13TX5J215481	132630
1GNEC13T55J215553	132781
1GNEC13T75J215800	133062
1GNFK16Z45J215793	133067
1GNEC13ZX5J214774	150937
1GNEK13T25J216033	150937
1GNEK13T65J214902	150937
1GNEK13ZX5J215281	150937
1GNFK16Z95J215319	150937
1GNEC16Z45J215379	151650
1GNEC13Z65J215419	151725
1GKFK66U35J216691	151783
1GKFK66U05J216941	152011
1GKFK66U25J215483	152011
1GKFK66U35J216741	152011
1GKFK66U35J216934	152011
1GKFK66U95J216629	152011

1GKEK63U45J215646	157847
1GNEK13Z75J217859	158290
1GKEK63U75J215737	158398
1GNFK16Z75J215657	158421
1GKFK66U55J215767	158440
1GKFK16Z45J218187	158467
1GKEK63U65J216913	158510
1GKEK13T85J218138	158544
1GKEK13T95J216799	158544
1GKFK66U15J215684	158544
1GKFK66U25J216438	158544
1GKEC13T05J215778	158563
1GKEK63U55J215526	158618
1GKEK63U05J216566	158775
1GKEC13T65J218166	158954
1GKEK13T55J215455	158954
1GKEK63U85J216735	159135
1GKFK66U95J216906	159269
1GKEK63U25J217606	159506
1GKFK66U05J216857	159506
1GKFK66U95J216775	160065
1GKFK66U15J215765	160153
1GNFK16Z65J215763	160183
1GNEC13T45J215544	161005
1GNEC13T95J216785	161005
1GKEC16Z05J215375	161287
1GKEC16205J216575	161532
	161532
1GKEK63U45J216988	The state of the s
1GKEK63U05J215434	161657
1GNFK16ZX5J216687	161797
1GKEK63U25J216620	161873
1GKEK13Z25J218141	162589
1GKEK63U35J216951	163372
1GKFK66U65J215681	163372
1GNEK13T15J215875	163891
1GNEK13Z05J215368	164176
1GKEC13T25J216690	164342
1GKFK66U05J216647	164343
1GKEC16Z05J215330	164349
1GKEC16Z35J215841	164349
1GKFK66U75J216757	164349
1GKEC13TX5J215464	164350
1GNEK13T15J216895	164353
1GKEK63U65J215437	164441
1GNEK13T15J215746	164454
1GKEK63U65J215809	164690
1GKFK66U85J215794	165335
1GKEK13T85J215417	165468
1GKEK13TX5J215466	165468
1GKEK63U05J215353	165839
1GNEC13T05J215766	165940
1GNEC13T05J215864	165940

1	405040
1GNEC13T05J218120	165940
1GNEC13T05J218165	165940
1GNEC13T15J216893	165940
1GNEC13T15J218045	165940
1GNEC13T25J215560	165940
1GNEC13T25J215798	165940
1GNEC13T35J215633	165940
1GNEC13T35J215678	165940
1GNEC13T35J215776	165940
1GNEC13T35J216748	165940
1GNEC13T35J218015	165940
1GNEC13T35J218144	165940
1GNEC13T45J215317	165940
1GNEC13T45J215592	165940
1GNEC13T45J215771	165940
1GNEC13T45J215821	165940
1GNEC13T45J216726	165940
1GNEC13T55J215326	165940
1GNEC13T55J215391	165940
1GNEC13T55J215407	165940
1GNEC13T55J215584	165940
1GNEC13T55J215861	165940
1GNEC13T55J216704	165940
1GNEC13T55J217755	165940
1GNEC13T55J217822	165940
1GNEC13T65J215321	165940
1GNEC13T65J215402	165940
1GNEC13T65J215786	165940
1GNEC13T75J215781	165940
1GNEC13T75J215814	165940
1GNEC13T75J215828	165940
1GNEC13T75J218163	165940
1GNEC13T85J215336	165940
1GNEC13T95J215412	165940
1GNEC13TX5J215323	165940
1GNEC13TX5J215337	165940
1GNEC13TX5J215807	165940
1GNEC16Z15J215503	165940
1GNEC16Z25J215395	165940
1GNEC16Z35J215373	165940
1GNEC16Z45J215768	165940
1GNEC16Z55J215679	165940
1GNEC16Z85J215398	165940
1GNEK13T05J215270	165940
1GNEK13T05J215429	165940
1GNEK13T05J215432	165940
1GNEK13T05J215561	165940
1GNEK13T05J215673	165940
1GNEK13T05J215690	165940
1GNEK13T05J215799	165940
1GNEK13T05J215849	165940
1GNEK13T05J215852	165940

	100010	
1GNEK13T05J216841		
1GNEK13T05J216919		
1GNEK13T05J217648	un Samananan and an	
1GNEK13T15J215133	9-14-9-14-14-14-14-14-14-14-14-14-14-14-14-14-	
1GNEK13T15J215567	<del></del>	
1GNEK13T15J215570	······································	
1GNEK13T15J215813		
1GNEK13T15J215827	and an analysis and a second an	
1GNEK13T25J215268		
1GNEK13T25J215271	Marie Commission Commi	
1GNEK13T25J215285		
1GNEK13T25J215416	6-m3/4///////////////////////////////////	
1GNEK13T25J215447	44	
1GNEK13T25J215495	undamental and a superior and a supe	
1GNEK13T25J215545		
1GNEK13T25J215643	1991 Barrier 1991	
1GNEK13T25J215724	······································	
1GNEK13T25J215772		
1GNEK13T25J216565	165940	
1GNEK13T25J217666	165940	
1GNEK13T25J217876	165940	
1GNEK13T25J218123	165940	
1GNEK13T35J215389	165940	
1GNEK13T35J215425	165940	
1GNEK13T35J215456	165940	
1GNEK13T35J215585		
1GNEK13T35J215604		
1GNEK13T35J215831	analy and the control of the control	
1GNEK13T35J217594		
1GNEK13T35J217823		
1GNEK13T35J217949		
1GNEK13T45J215322	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
1GNEK13T45J215403		
1GNEK13T45J215420		
1GNEK13T45J215515		
1GNEK13T45J215787		
1GNEK13T45J215806		
1GNEK13T45J217538		
1GNEK13T45J217684		
1GNEK13T45J217958	A-1-4	
1GNEK13T45J217961	······································	
1GNEK13T55J215619		
1GNEK13T55J215667		
1GNEK13T55J215801		
1GNEK13T55J215846		
1GNEK13T55J218777	······································	
1GNEK13T55J218780	······································	
1GNEK13T65J215399	and the second s	
1GNEK13T65J215550	······································	
1GNEK13T65J215709	······································	
1GNEK13T65J215791	······································	
1GNEK13T65J215810	165940	

1GNEK13T65J215824	165940
1GNEK13T65J215838	165940
1GNEK13T65J215872	165940
1GNEK13T65J215936	165940
1GNEK13T65J216911	165940
1GNEK13T75J215282	165940
1GNEK13T75J215461	165940
1GNEK13T75J215587	165940
1GNEK13T75J215654	165940
1GNEK13T75J218084	165940
1GNEK13T85J215310	165940
1GNEK13T85J215422	165940
1GNEK13T85J215436	165940
1GNEK13T85J215629	165940
1GNEK13T85J215677	165940
1GNEK13T85J215856	165940
1GNEK13T85J216358	165940
1GNEK13T95J215414	165940
1GNEK13T95J215476	165940
1GNEK13T95J215669	165940
1GNEK13T95J215705	165940
1GNEK13T95J215803	165940
1GNEK13T95J215817	165940
1GNEK13T95J215820	165940
1GNEK13T95J216949	165940
1GNEK13T95J217826	165940
1GNEK13T95J218099	165940
1GNEK13TX5J215342	165940
1GNEK13TX5J215406	165940
1GNEK13TX5J215647	165940
1GNEK13TX5J215860	165940
1GNEK13TX5J216572	165940
1GNEK13TX5J216765	165940
1GNEK13TX5J217723	165940
1GNFK16Z05J215354	165940
1GNFK16Z05J215371	165940
1GNFK16Z05J215693	165940
1GNFK16Z15J215377	165940
1GNFK16Z15J215489	165940
1GNFK16Z15J215752	165940
1GNFK16Z25J215758	165940
1GNFK16Z25J215761	165940
1GNFK16Z35J215364	165940
1GNFK16Z45J215745	165940
1GNFK16Z55J215740	165940
1GNFK16Z55J217794	165940
1GNFK16Z65J218002	165940
1GNFK16Z75J215755	165940
1GNFK16Z75J216503	165940
1GNFK16Z85J215358	165940
1GNFK16Z85J215361	165940
1GNFK16Z85J215540	165940
The second secon	<del></del>

1GNFK16Z85J215795	165940
1GNFK16Z85J216879	165940
1GNFK16ZX5J215345	165940
1GNFK16ZX5J215782	165940
1GKFK16Z15J215280	165940
1GKFK66U05J215904	165940
1GKFK66U75J216029	165940
1GNEC13T55J217805	165940
1GNEK13T15J218016	165940
1GKEC13T35J217069	165952
1GKEC13T75J216670	165952
1GKEK63U45J217025	165952
1GKEK63U65J215910	165952
1GKEK13T75J218180	166076
1GKFK66U25J215418	166135
1GKFK66U35J215394	166135
1GKEK63U55J215784	166291
1GKFK66U15J215829	166291
1GNFK16Z95J216728	166312
1GNEC16Z55J215844	166558
1GKEK13T15J215548	166955
	166955
1GKEK13T65J215500	
1GKEK63U85J215634	167046
1GKEK63U05J217930	167112
1GKEK13TX5J215385	167389
1GKFK66U35J216139	167761
1GKFK66U55J215493	167761
1GKEK13TX5J215452	168340
1GNEC16ZX5J216889	168342
1GKEK63U25J215774	169093
1GKFK66U95J215299	169093
1GKEC13T95J218100	169658
1GKEC13TX5J216209	169658
1GKEK13T75J216607	169658
1GKFK16Z95J215866	170745
1GKFK66U45J215811	171040
1GKFK66U45J216814	171040
1GKFK66U75J218122	171243
1GKEK63U85J216931	171701
1GKFK66UX5J215408	
1GNFK16Z05J215547	171984
1GKEK63U45J217929	172183
1GKEC13T95J215598	172218
1GKEC13V65J215477	172543
1GKFK66U75J215687	172614
1GKFK66UX5J217899	172614
1GNEK13T95J216689	172758
1GKEC13T55J215579	172758
1GKFK66U75J216676	172758
1GKFK66U85J215648	172786
1GNEC13T95J217872	172834
1GKEK63U65J215387	172840

	<b>4-000</b> -
1GKEK13T15J215369	172965
1GKFK66U95J217702	173008
1GKFK66U55J215588	176613
1GKFK66U85J215732	177283
1GKEK63UX5J215442	177378
1GKEK63U25J215886	178066
1GKEK13T05J216030	178159
1GKFK16ZX5J216976	178223
1GKEC16Z05J216977	178635
1GKFK66U65J216944	181120
1GKEK13T75J215845	181156
1GKEK13Z65J215453	181444
1GKEK63U35J215413	181524
1GKEK63U65J216619	181524
1GNEC13T25J216739	181817
1GNEC13T65J215609	182704
1GNEC13T75J215571	182704
1GNEC13TX5J215208	182704
1GNEC13TX5J216682	182704
1GKFK16Z65J215307	183998
1GKFK16Z95J215463	183998
1GKEK13Z05J215870	184991
1GKEK13Z55J215797	185245
1GKFK66U85J216959	185416
1GKFK66UX5J216025	185416
1GKEK63U75J215351	185713
1GKEK63U65J215941	186061
1GKEK63U75J215804	186713
1GNEC16Z65J215738	186856
1GKEK63U95J215593	187290
1GNFK16Z35J218085	189457
1GNEK13ZX5J218164	189513
1GKEK13T65J215707	189624
1GKEK63U75J215575	189802
1GKEK13T05J215511	190867
1GKEK13T05J215847	191808
1GKEK63U45J215601	192311
1GKEK13T65J215836	192838
1GKFK66U55J215686	193100
1GKFK66U25J215595	193149
1GKEK63U65J215549	193153
1GNEC16Z35J216720	194400
1GKFK16Z05J216789	194776
1GKFK66U15J216432	195178
1GKFK66U85J216489	195178
1GNEC13T35J216703	195833
1GKEK13T55J215410	196028
1GKEK63UX5J215344	196028
1GKEC13T75J215938	196542
1GKEK63U15J215734	196831
1GKFK66U55J216756	197176
1GNEK13T35J217059	197265

1GNEC13TX5J215905	198889
1GKEK13T65J215528	198932
1GNEC13T95J217810	198933
1GKEK63UX5J215652	199686
1GNEC16Z25J216868	200575
1GKEK13T15J216604	201264
1GKFK66U25J216570	201264
1GKEK13T55J217061	201566
1GNEK13T05J216547	202384
1GNEK13T15J217884	202384
1GNEK13T25J217019	202384
1GNEK13T75J215640	202384
1GNEK13T85J216750	202384
1GNEK13T95J215834	202384
1GNEC13T55J215309	202567
1GKEK63U55J217762	205239
1GKEK63UX5J216994	205239
1GKEK13T25J215770	205277
1GKEK13TX5J215273	205808
1GKEK63U85J215617	205842
1GNEK13T15J216511	206432
1GNEK13T35J216803	206432
1GNEK13T55J217919	206432
1GNEK13T85J215663	206432
1GNFK16Z85J215473 1GKEK63U55J215266	206795 a 207270
1GKEK63U55J215266 1GKEC16Z25J215362	207446
1GKEK63U45J215498	207595
1GNEC16Z15J218157	208013
1GNFK16Z25J216618	208512
1GKFK66U35J218148	208925
1GNEC16Z85J217779	210164
1GKFK66U05J215448	210181
1GKEK63U05J215630	210623
1GKFK66U45J216778	210623
1GKEK13T05J218098	210826
1GNEC13T65J218185	211164
1GNEC13T85J215725	211164
1GNFK16Z85J215750	211473
1GKEC13T65J215946	212302
	Control of the Contro
7	
0.0.0000000000000000000000000000000000	
(2) may 1 11 de 11 11 de 200 de 2	