



Driven to Explore

Fleetwood Enterprises, Inc.
3051 Myers Street / Riverside, CA 92503-5927
PO Box 7638 / Riverside, CA 92513-7638
p: 800-322-8216 / www.fleetwood.com

IMPORTANT PRODUCT RECALL INFORMATION # 50415

June, 2005

**TO: ALL FLEETWOOD DEALER PRINCIPALS,
SERVICE MANAGERS,
AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN # 50415
Spartan Chassis Pneumatic System Steel Braided Line**

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing center located in Decatur, Indiana is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the National Highway Traffic and Motor Vehicle Safety act.

Fleetwood Enterprises, Inc., has determined that a defect relating to motor vehicle safety exists in certain 2004 and 2005 model year American Eagle, American Tradition and Revolution LE brand class A motor homes. These motor homes were manufactured at our Decatur, Indiana manufacturing plant.

We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

On motor homes affected by this recall a pneumatic line can become pinched between the hydraulic filter and a compartment door strut. Chaffing caused by opening and closing the compartment door can cause the filter to rupture and result in a hydraulic fluid leak. This loss of hydraulic fluid causes the power steering feature to not function. This can result in loss of vehicle control, personal injury and/or a vehicle crash.

WHAT SHOULD YOU DO?

Please check your motor home inventory and have the repair procedure performed by contacting Spartan Chassis Customer Service at 1-800-543-4277 and select option 1, on affected units as outlined on the attached service bulletin # 50415. If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motor home. It is imperative that this procedure be completed prior to the sale or lease of the affected units so your customers will not be inconvenienced.

Owners of the above mentioned motor homes have been asked to contact Spartan Customer Service to locate a Spartan Service Center to have the described defective condition remedied.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act of 1966) requires that:

If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Thank you for helping Fleetwood with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your regional Fleetwood Service Center.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Tina Inkrote
Service Coordinator
Recreation Vehicle Division

Recall Bulletin 50415



RECALL BULLETIN:
50415

YEAR(S) AFFECTED:
2004-2005

PRODUCT(S) AFFECTED:
2004-2005
American Eagle,
American Tradition, and
2005 Fleetwood Revolution LE,
Serial Numbers Listed in this Bulletin

MODEL(S) AFFECTED:
All American Coach and Revolution LE

SUBJECT:
Repositioning of the Power Steering Hydraulic Filter

KEYWORDS:
Spartan, Power Steering, Hydraulic

ISSUE DATE:
June, 2005

The purpose of this Recall Bulletin is to inform Fleetwood dealers about a safety recall involving the hydraulic system on identified Spartan chassis.

CONDITION:

A compartment door strut, when the door is closed, will rub against the filter for the power steering fluid. This will eventually wear through the filter canister and power steering fluid will be lost. If this occurs, the power steering assist will no longer function.

CORRECTION:

Dealer/Consumers should contact Spartan Customer Service to locate a Spartan Service Center by calling:

1-800-543-4277 – Then Select Option 1

The current mileage and the last six digits of the Spartan Vehicle Identification Number (V.I.N.) will be required when contacting Spartan.

Schedule the motor home with the Spartan Service Center, as they will make the necessary repairs. Provide the Spartan Service Center with a copy of the attached Spartan repair procedure.

NOTE: This repair may involve breaching the Spartan hydraulic fluid system. Only authorized Spartan Service Centers are qualified to perform this repair.

If you have any questions concerning this Bulletin regarding American Eagle or American Tradition Motor homes, contact American Coach Service at:
1-800-435-7345

For questions concerning Revolution LE Motor Homes, contact Fleetwood Dealer Technical Support at:
1-800-816-9825

© 2005 Fleetwood Enterprises, Inc.

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 194 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles receiving in good inventory, according to the notification, before selling or leasing the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the owner within ten days.

It is impossible to avoid, evaluate and advise the service trade of all conceivable ways in which advice might be given or of the possible reparations consequences of each way. Accordingly, anyone who uses a service procedure or tool must first ensure that neither procedural safety nor vehicle safety will be jeopardized by the selected service methods.

2004 American Coach Serial Numbers

Fleetwood Serial # Spartan V.I.N.		Fleetwood Serial # Spartan V.I.N.	
719J44486723	4VZBR1D923C044757	780Q44487514	4VZBR1D994C045812
719W44486963	4VZBR1D984C045249	780Q44487515	4VZBR1D904C045813
780J44487015	4VZBR1D914C045416	719J44487516	4VZBR1D9X4C045818
719J44487062	4VZBR1D924C045294	719J44487517	4VZBR1D924C045814
719J44487064	4VZBR1D964C045251	719J44487518	4VZBR1D984C045817
719Q44487072	4VZBR1D944C045250	719J44487519	4VZBR1D984C045820
719L44487080	4VZBR1D974C045419	719J44487520	4VZBR1D934C045787
780Q44487142	4VZBR1D904C045536	719J44487521	4VZBR1D954C045788
780L44487241	4VZBR1D994C045535	719J44487522	4VZBR1D974C045789
719W44487258	4VZBR1D954C045418	780L44487523	4VZBR1D994C045809
719W44487259	4VZBR1D964C045587	780L44487524	4VZBR1D954C045810
719W44487260	4VZBR1D984C045588	719J44487526	4VZBR1D9X4C045821
780J44487265	4VZBR1D974C045534	719J44487527	4VZBR1D914C045822
719J44487375	4VZBR1D9X4C045589	719J44487528	4VZBR1D934C045868
719J44487376	4VZBR1D964C045590	719J44487529	4VZBR1D954C045824
719J44487378	4VZBR1D984C045591	719J44487530	4VZBR1D944C045913
719V44487393	4VZBR1D964C045704	719J44487531	4VZBR1D964C045914
719Q44487401	4VZBR1D9X4C045706	719J44487535	4VZBR1D954C045869
719Q44487403	4VZBR1D914C045710	780J44487540	4VZBR1D974C045811
719J44487404	4VZBR1D934C045708	780J44487541	4VZBR1D944C045863
719J44487405	4VZBR1D944C045703	780J44487544	4VZBR1D924C045862
719J44487407	4VZBR1D934C045711	780J44487545	4VZBR1D984C045865
719L44487410	4VZBR1D984C045705	780J44487546	4VZBR1D964C045864
719L44487411	4VZBR1D954C045712	719V44487665	4VZBR1D934C045823
719N44487418	4VZBR1D974C045713	719V44487666	4VZBR1D914C045870
719J44487420	4VZBR1D994C045714	719V44487667	4VZBR1D914C045917
719J44487421	4VZBR1D904C045715	719N44487780	4VZBR1D984C045915
780W44487503	4VZBR1D984C045784	719L44487795	4VZBR1D9X4C045916
780W44487504	4VZBR1D914C045786	719L44487796	4VZBR1D944C045989
719J44487506	4VZBR1D924C045716	719L44487798	4VZBR1D904C045990
719J44487507	4VZBR1D944C045717	719J44487799	4VZBR1D924C045991
719J44487508	4VZBR1D914C045707	780J44487801	4VZBR1D9X4C045866
719J44487509	4VZBR1D954C045709	719Q44487816	4VZBR1D944C045992
719J44487510	4VZBR1D944C045815	780L44487825	4VZBR1D914C045867
719J44487511	4VZBR1D964C045816	780L44487826	4VZBR1D954C045919
719J44487512	4VZBR1D914C045819	780L44487827	4VZBR1D934C045918
780Q44487513	4VZBR1D9X4C045785	780L44487828	4VZBR1D914C045982

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any manufacturer, manufacturer, and their dealer or distributor correct the defect on vehicles remaining in your inventory according to the recall (NHTSA, 1-800-372-1034) the vehicles. Any vehicle dealer receiving this recall notice should forward a copy of the notice to the dealer within ten days.

It is impossible to issue, available and advise the service trade of all possible ways in which safety might be state or of the possible hazardous consequences of each way. Accordingly, anyone who uses a repair procedure or tool must first ensure that neither personal safety nor vehicle safety will be jeopardized by the selected service method.

2004 American Coach Serial Numbers

Fleetwood Serial # Spartan V.I.N.		Fleetwood Serial # Spartan V.I.N.	
780N44487922	4VZBR1D934C045983	780W44488301	4VZBR1D934C046101
719L44487936	4VZBR1D994C046006	780J44488302	4VZBR1D954C046102
719L44487937	4VZBR1D904C046007	780J44488303	4VZBR1D994C046216
780J44487942	4VZBR1D954C045984	780J44488304	4VZBR1D924C046218
780J44487946	4VZBR1D974C045985	780L44488312	4VZBR1D9X4C046127
719W44487956	4VZBR1D924C046008	780L44488313	4VZBR1D914C046128
719W44487958	4VZBR1D944C046009	780L44488315	4VZBR1D934C046129
719W44487959	4VZBR1D974C046005	719L44488316	4VZBR1D964C046254
719J44487960	4VZBR1D994C046023	719L44488319	4VZBR1D914C046260
719J44487961	4VZBR1D904C046024	719J44488320	4VZBR1D984C046322
780L44487968	4VZBR1D994C045986	780Q44488586	4VZBR1D984C046031
780L44487970	4VZBR1D904C045987	719N44488588	4VZBR1D9X4C046323
719L44488074	4VZBR1D924C046025	719V44488596	4VZBR1D934C046325
719L44488075	4VZBR1D944C046026	719V44488597	4VZBR1D954C046326
719L44488076	4VZBR1D964C046027	719W44488598	4VZBR1D914C046324
719L44488077	4VZBR1D984C046028	780V44488607	4VZBR1D9X4C046130
719L44488078	4VZBR1D9X4C046029	719L44488616	4VZBR1D934C046549
780L44488083	4VZBR1D924C045988	719L44488617	4VZBR1D994C046491
780L44488084	4VZBR1D934C046003	719N44488618	4VZBR1D974C046490
780L44488085	4VZBR1D914C046002	719J44488625	4VZBR1D904C046489
719J44488136	4VZBR1D914C046131	719J44488626	4VZBR1D994C046488
719Q44488156	4VZBR1D934C046132	780J44488627	4VZBR1D904C046217
719V44488157	4VZBR1D954C046133	780J44488629	4VZBR1D934C046261
719V44488158	4VZBR1D974C046134	780J44488734	4VZBR1D954C046262
780W44488162	4VZBR1D954C046004	780J44488736	4VZBR1D944C046446
719J44488164	4VZBR1D994C046135	780J44488737	4VZBR1D9X4C046449
719J44488165	4VZBR1D904C046136	780J44488738	4VZBR1D984C046448
719J44488166	4VZBR1D944C046219	719L44488749	4VZBR1D914C046548
780N44488275	4VZBR1D9X4C046032	719L44488750	4VZBR1D914C046551
780N44488277	4VZBR1D964C046030	719L44488786	4VZBR1D9X4C046550
780J44488279	4VZBR1D914C046033	780L44488797	4VZBR1D904C046590
719J44488280	4VZBR1D934C046258	780L44488799	4VZBR1D944C046589
719W44488287	4VZBR1D954C046259	780W44488802	4VZBR1D964C046447
719W44488288	4VZBR1D944C046253	780W44488803	4VZBR1D984C046594
780V44488297	4VZBR1D994C046099	719L44488885	4VZBR1D914C046596
780V44488298	4VZBR1D934C046034	719L44488886	4VZBR1D934C046597
780W44488300	4VZBR1D914C046100	780J44488893	4VZBR1D944C046592

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 134 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must read or otherwise consult the details on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicle. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to locate, evaluate and address the serial tracks of all comparable units in which service might be done or of the possible hazardous consequences of such work. Accordingly, anyone who uses a service procedure or tool must first assure the proper personal safety, the vehicle safety will be jeopardized by the selected service methods.

2004 American Coach Serial Numbers

Fleetwood Serial # Spartan V.I.N.

780J44488896	4VZBR1D924C046591
780J44488897	4VZBR1D9X4C046595
780Q44488899	4VZBR1D964C046593
719N44488911	4VZBR1D974C046599
719N44488912	4VZBR1D914C046601
780W44488914	4VZBR1D924C046638
780W44488915	4VZBR1D944C046639
780V44488921	4VZBR1D964C046710
780J44488924	4VZBR1D984C046711
719V44489018	4VZBR1D9X4C046600
719V44489019	4VZBR1D904C046640
719J44489024	4VZBR1D954C046598
780J44489025	4VZBR1D9X4C046712
719J44489034	4VZBR1D924C046641
780J44489036	4VZBR1D944C046768
780L44489045	4VZBR1D964C046822
780X44489048	4VZBR1D984C046823
719W44489164	4VZBR1D914C046713
780L44489188	4VZBR1D934C045420
780L44489189	4VZBR1D994C046930
719W44489199	4VZBR1D934C046714
719J44489200	4VZBR1D954C046715
780J44489201	4VZBR1D924C046932
780J44489202	4VZBR1D954C046990
780L44489211	4VZBR1D974C046991
780L44489212	4VZBR1D904C046931
780W44489213	4VZBR1D994C046992
780L44489323	4VZBR1D904C046993
780Q44489325	4VZBR1D914C047053
780V44489326	4VZBR1D934C047054
780V44489369	4VZBR1D924C047059
719J44489379	4VZBR1D984C046935
780J44489516	4VZBR1D994C047060
719N44489522	4VZBR1D944C046933
719L44489548	4VZBR1D9X4C047052
780L44489549	4VZBR1D9X4C047066

Fleetwood Serial # Spartan V.I.N.

780J44489550	4VZBR1D964C047064
780V44489567	4VZBR1D984C047065
780J44489687	4VZBR1D934C047068
780L44489693	4VZBR1D914C047067
780L44489695	4VZBR1D954C047069
780W44489705	4VZBR1D914C047070
719J44489717	4VZBR1D994C047057
719L44489722	4VZBR1D934C046938
719L44489723	4VZBR1D9X4C046936
780L44489724	4VZBR1D994C047253
780L44489725	4VZBR1D904C047254
780L44489726	4VZBR1D944C047256
780X44489730	4VZBR1D924C047255
719V44489741	4VZBR1D964C046934
719W44489742	4VZBR1D9X4C046984
780J44489844	4VZBR1D954C047265
780V44489848	4VZBR1D974C047266
719W44489854	4VZBR1D934C046986
719L44489860	4VZBR1D914C046985
780X44489863	4VZBR1D994C047267
719L44489883	4VZBR1D914C046937
719L44489884	4VZBR1D974C046988
780W44490007	4VZBR1D914C047571
780J44490014	4VZBR1D954C047573
780J44490015	4VZBR1D934C047572
780J44490016	4VZBR1D974C047574
780J44490017	4VZBR1D994C047575
719L44490025	4VZBR1D954C046987
719L44490026	4VZBR1D994C046989
719V44490027	4VZBR1D984C047051
719W44490035	4VZBR1D904C047058
719V44490037	4VZBR1D934C047071
780J44490042	4VZBR1D974C047672
780J44490043	4VZBR1D954C047671
780V44490046	4VZBR1D975C047673

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 134 of the National Traffic and Motor Vehicle Safety Act of 1980) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must follow or otherwise correct the details on vehicles remaining in your inventory, according to the instructions. Before selling or leasing the vehicle, any vehicle requiring this recall notice must have a copy of the notice in the dealer's inventory file.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or all the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure not listed here that affects the matter, machine, safety, or vehicle safety (as applicable) by the standard service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial #	Spartan V.I.N.
719W54490065	4VZBR1D955C047073
719W54490066	4VZBR1D975C047074
719W54490067	4VZBR1D935C047072
719Q54490068	4VZBR1D995C047075
719Q54490069	4VZBR1D945C047078
780J54490214	4VZBR1D995C047674
780J54490215	4VZBR1D905C047675
780J54490216	4VZBR1D925C047676
780L54490222	4VZBR1D965C047681
780L54490223	4VZBR1D985C047682
780J54490339	4VZBR1D945C047680
780J54490340	4VZBR1D9X5C047683
780L54490348	4VZBR1D985C047732
780L54490349	4VZBR1D9X5C047733
780V54490357	4VZBR1D935C047735
719J54490362	4VZBR1D925C047077
719W54490367	4VZBR1D905C047076
719W54490368	4VZBR1D965C047079
719L54490375	4VZBR1D925C047080
780L54490378	4VZBR1D915C047734
780J54490385	4VZBR1D955C047736
780J54490389	4VZBR1D995C047805
780W54490395	4VZBR1D9X5C047764
719J54490497	4VZBR1D945C047260
719J54490498	4VZBR1D965C047258
719J54490499	4VZBR1D945C047257
719J54490500	4VZBR1D985C047259
780L54490505	4VZBR1D915C047765
780L54490507	4VZBR1D905C047806
719J54490517	4VZBR1D965C047731
719L54490519	4VZBR1D985C047844
780L54490526	4VZBR1D975C047852
780J54490527	4VZBR1D995C047853
719L54490533	4VZBR1D9X5C047845
719L54490534	4VZBR1D945C047730
780W54490535	4VZBR1D905C047854
780V54490536	4VZBR1D925C047855

Fleetwood Serial #	Spartan V.I.N.
719J54490540	4VZBR1D925C047807
719J54490542	4VZBR1D915C047846
780J54490543	4VZBR1D945C047856
780L54490546	4VZBR1D965C047857
719L54490657	4VZBR1D935C047847
719L54490658	4VZBR1D955C047848
719L54490659	4VZBR1D975C047849
719L54490660	4VZBR1D935C047850
719W54490661	4VZBR1D985C047892
780J54490666	4VZBR1D935C047878
719J54490669	4VZBR1D965C047891
719J54490670	4VZBR1D955C047851
780V54490675	4VZBR1D915C047880
780L54490676	4VZBR1D955C047882
780L54490677	4VZBR1D955C047879
719J54490734	4VZBR1D9X5C047893
719J54490735	4VZBR1D915C047894
719J54490736	4VZBR1D935C047895
719J54490737	4VZBR1D955C047896
719J54490739	4VZBR1D995C047898
719L54490743	4VZBR1D905C047899
719L54490745	4VZBR1D935C047900
719L54490746	4VZBR1D975C047897
780L54490747	4VZBR1D905C047885
780L54490750	4VZBR1D935C047881
780L54490751	4VZBR1D995C047884
780J54490757	4VZBR1D945C047887
780J54490758	4VZBR1D965C047888
780V54490761	4VZBR1D975C047883
780L54490763	4VZBR1D925C047886
780L54490764	4VZBR1D995C047903
780L54490765	4VZBR1D975C047902
780L54490766	4VZBR1D955C047901
780W54490767	4VZBR1D905C047904
780Q54490769	4VZBR1D925C047905
780J54490772	4VZBR1D945C047906
780J54490773	4VZBR1D985C047908

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the instructions, before leasing or selling the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to know, evaluate and advise the service needs of all conceivable ways in which service might be done or of the possible hazardous consequences of such acts. Accordingly, anyone who uses a service procedure or tool must first ensure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial # Spartan V.I.N.

780J54490774	4VZBR1D965C047907
780J54490775	4VZBR1D965C047910
780J54490776	4VZBR1D9X5C047909
780J54490777	4VZBR1D905C048048
719J54490782	4VZBR1D9X5C047912
719J54490783	4VZBR1D935C047914
719L54490784	4VZBR1D915C047913
719L54490785	4VZBR1D955C047915
719V54490889	4VZBR1D975C047916
719L54490890	4VZBR1D995C047917
719L54490891	4VZBR1D905C047918
719L54490892	4VZBR1D905C047921
719J54490893	4VZBR1D995C047920
719J54490894	4VZBR1D925C047919
719J54490895	4VZBR1D935C048058
719J54490896	4VZBR1D955C048059
780J54490898	4VZBR1D985C047911
780J54490899	4VZBR1D995C048050
780J54490900	4VZBR1D995C048047
780J54490901	4VZBR1D905C048051
780J54490902	4VZBR1D925C048052
780L54490905	4VZBR1D945C048053
780L54490906	4VZBR1D965C048054
780L54490907	4VZBR1D9X5C048056
780L54490908	4VZBR1D995C048081
780L54490909	4VZBR1D925C048049
780L54490910	4VZBR1D905C048082
780W54490911	4VZBR1D925C048083
719V54490914	4VZBR1D915C048057
719J54490916	4VZBR1D975C048063
719L54490918	4VZBR1D995C048064
719L54490919	4VZBR1D935C048061
780J54490923	4VZBR1D945C048084
780J54490925	4VZBR1D965C048085
780J54490926	4VZBR1D925C048133
780J54490927	4VZBR1D945C048134
780L54490931	4VZBR1D915C048088

Fleetwood Serial # Spartan V.I.N.

780L54490932	4VZBR1D985C048055
780L54490934	4VZBR1D9X5C048087
780L54490935	4VZBR1D985C048086
719J54491073	4VZBR1D915C048060
719V54491079	4VZBR1D905C048065
719W54491080	4VZBR1D9X5C048140
780J54491088	4VZBR1D965C048135
780J54491186	4VZBR1D985C048136
780J54491187	4VZBR1D995C048162
780J54491188	4VZBR1D965C048197
780J54491191	4VZBR1D925C048200
780J54491192	4VZBR1D955C048286
719Q54491198	4VZBR1D925C048066
719L54491205	4VZBR1D915C048138
780L54491206	4VZBR1D9X5C048199
780L54491207	4VZBR1D915C048284
780L54491208	4VZBR1D9X5C048137
780L54491209	4VZBR1D975C048287
780L54491210	4VZBR1D995C048288
719J54491218	4VZBR1D935C048139
719J54491219	4VZBR1D915C048141
719J54491220	4VZBR1D935C048142
780J54491222	4VZBR1D905C048289
719L54491232	4VZBR1D905C048163
719L54491233	4VZBR1D925C048164
719L54491234	4VZBR1D945C048067
780N54491245	4VZBR1D975C048290
780N54491246	4VZBR1D935C048285
780L54491357	4VZBR1D915C048379
780W54491358	4VZBR1D9X5C048381
780J54491366	4VZBR1D975C048449
719L54491380	4VZBR1D955C048062
719L54491383	4VZBR1D945C048201
719J54491385	4VZBR1D915C048205
719J54491387	4VZBR1D905C048292
719J54491388	4VZBR1D9X5C048204
780V54491395	4VZBR1D935C048450

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 136 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a recall notice to contact the Fleetwood or any component manufacturer, you must appear or otherwise contact the dealer or vehicle retailer at your earliest opportunity, according to the instructions. Before asking or leaving the vehicle, any vehicle is not making this recall notice made for your safety. If you do not follow the recall notice, you may be liable for any damage to the vehicle or any other loss.

It is important to know, evaluate and advise the correct type of all components used in which vehicle might be used or the possible hazardous consequences of such use. Accordingly, anyone who uses a vehicle is responsible for how that vehicle is used and must take all necessary steps to ensure that neither personal safety nor vehicle safety will be jeopardized by the selected service provider.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial # Spartan V.I.N.

780J54491396	4VZBR1D985C048380
780J54491397	4VZBR1D955C048451
719J54491406	4VZBR1D945C048294
719J54491407	4VZBR1D995C048324
719L54491409	4VZBR1D905C048325
719L54491410	4VZBR1D925C048326
780L54491417	4VZBR1D995C048453
780L54491418	4VZBR1D985C048525
781E54491517	4VZBR1J9X5C048417
719L54491524	4VZBR1D935C048206
719J54491531	4VZBR1D915C048530
719J54491532	4VZBR1D925C048455
719J54491533	4VZBR1D935C048528
780J54491534	4VZBR1D9X5C048526
780J54491537	4VZBR1D915C048527
780V54491540	4VZBR1D935C048609
781E54491541	4VZBR1J925C048766
781X54491542	4VZBR1J945C048767
719J54491548	4VZBR1D955C048529
780J54491549	4VZBR1D915C048611
780J54491551	4VZBR1D9X5C048610
780J54491552	4VZBR1D935C048612
780L54491558	4VZBR1D975C048452
780L54491560	4VZBR1D925C048617
780L54491561	4VZBR1D995C048615
780L54491563	4VZBR1D905C048616
780V54491569	4VZBR1D955C048613
780V54491570	4VZBR1D905C048700
719V54491632	4VZBR1D965C048619
719J54491633	4VZBR1D925C048620
719L54491640	4VZBR1D945C048618
780L54491642	4VZBR1D965C048703
780L54491643	4VZBR1D945C048702
780L54491644	4VZBR1D925C048701
780L54491645	4VZBR1D9X5C048705
780J54491652	4VZBR1D975C048614
780J54491654	4VZBR1D915C048706

Fleetwood Serial # Spartan V.I.N.

780J54491757	4VZBR1D935C048707
780J54491758	4VZBR1D955C048787
780V54491765	4VZBR1D975C048791
780V54491766	4VZBR1D995C048789
719V54491767	4VZBR1D995C048792
719V54491768	4VZBR1D935C048710
719V54491769	4VZBR1D975C048709
719J54491776	4VZBR1D955C048711
719J54491777	4VZBR1D975C048712
719L54491779	4VZBR1D945C048621
719L54491780	4VZBR1D905C048793
780J54491789	4VZBR1D955C048790
780J54491790	4VZBR1D945C048893
780J54491791	4VZBR1D985C048945
780J54491792	4VZBR1D9X5C048896
780L54491796	4VZBR1D965C048894
780L54491797	4VZBR1D955C048899
780L54491798	4VZBR1D935C048898
780V54491799	4VZBR1D915C048897
719V54491800	4VZBR1D915C048382
719V54491801	4VZBR1D995C048713
719J54491807	4VZBR1D945C048795
719L54491809	4VZBR1D9X5C048798
719L54491810	4VZBR1D985C048797
781E54491866	4VZBR1J985C048965
781E54491867	4VZBR1J9X5C048966
781E54491868	4VZBR1J965C048964
781E54491869	4VZBR1J915C048970
781E54491870	4VZBR1J915C048967
780L54491872	4VZBR1D965C048944
780L54491873	4VZBR1D955C048949
780L54491874	4VZBR1D915C048950
780J54491875	4VZBR1D9X5C048946
780J54491876	4VZBR1D935C048948
780J54491877	4VZBR1D955C048952
780J54491878	4VZBR1D935C048951
781E54491879	4VZBR1J955C048969

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, service who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial # Spartan V.I.N.

Fleetwood Serial # Spartan V.I.N.

781E54491880	4VZBR1J935C048968
781E54491881	4VZBR1J955C048972
781E54491883	4VZBR1J905C048975
719J54491884	4VZBR1D925C048889
719J54491885	4VZBR1D995C048890
719L54491886	4VZBR1D965C048796
719L54491887	4VZBR1D915C048799
781E54491889	4VZBR1J975C048973
781E54491890	4VZBR1J935C048971
781E54491891	4VZBR1J965C048978
781E54491892	4VZBR1J925C048976
781E54491893	4VZBR1J935C049022
781E54492002	4VZBR1J955C049023
781E54492003	4VZBR1J975C049024
781E54492004	4VZBR1J965C049032
781E54492005	4VZBR1J945C049031
781E54492006	4VZBR1J945C049028
719J54492009	4VZBR1D965C048958
719J54492010	4VZBR1D945C048957
781E54492012	4VZBR1J995C049025
781E54492013	4VZBR1J905C049026
781E54492014	4VZBR1J925C049027
781E54492015	4VZBR1J925C049030
781E54492016	4VZBR1J965C049029
781E54492017	4VZBR1J9X5C049034
781E54492018	4VZBR1J985C049033
781E54492019	4VZBR1J975C049038
781E54492020	4VZBR1J955C049037
781E54492021	4VZBR1J915C049035
780L54492022	4VZBR1D975C048953
780L54492024	4VZBR1D915C048947
780L54492025	4VZBR1D925C048956
781E54492026	4VZBR1J935C049036
781E54492027	4VZBR1J955C049040
781E54492028	4VZBR1J975C049041
781E54492029	4VZBR1J995C049039
781E54492030	4VZBR1J985C049128

781E54492081	4VZBR1J945C048977
781E54492082	4VZBR1J965C049130
781E54492083	4VZBR1J9X5C049132
781E54492084	4VZBR1J985C049131
781E54492085	4VZBR1J955C049135
780J54492086	4VZBR1D995C048954
780J54492088	4VZBR1D975C049021
781E54492089	4VZBR1J935C049134
781E54492090	4VZBR1J9X5C049129
781E54492091	4VZBR1J915C049133
781E54492092	4VZBR1J995C049137
781E54492093	4VZBR1J905C049138
781E54492094	4VZBR1J975C049136
781E54492095	4VZBR1J965C049127
781E54492096	4VZBR1J925C049142
781E54492097	4VZBR1J995C049140
781E54492098	4VZBR1J925C049139
780L54492099	4VZBR1D935C049114
780L54492100	4VZBR1D955C049115
780L54492101	4VZBR1D915C049113
781E54492102	4VZBR1J905C049141
781E54492103	4VZBR1J945C049143
781E54492104	4VZBR1J985C049145
781E54492105	4VZBR1J965C049144
781E54492106	4VZBR1J935C049148
781E54492107	4VZBR1J955C049149
781E54492108	4VZBR1J915C049147
781E54492109	4VZBR1J9X5C049146
781E54492110	4VZBR1J935C049196
781E54492111	4VZBR1J995C049199
719J54492112	4VZBR1D985C048959
781E54492113	4VZBR1J915C049150
781E54492114	4VZBR1J935C049201
781E54492115	4VZBR1J915C049200
781E54492116	4VZBR1J975C049198
781E54492117	4VZBR1J935C049151
781E54492118	4VZBR1J975C049203

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 104 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or safety recall from Fleetwood or any other manufacturer, you must appear or otherwise correct the defects or vehicles mentioned in your vicinity according to the notification. Before taking or making the vehicles, any vehicle repair, including this recall, must be made in a shop of the choice of the dealer within 90 days.

It is understood by these notices and upon the service order of all participating dealers, dealers, and/or the positive identification of each may, accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial # Spartan V.I.N.

781E54492120	4VZBR1J955C049202
781E54492121	4VZBR1J905C049205
781E54492122	4VZBR1J965C049211
781E54492123	4VZBR1J945C049210
781E54492196	4VZBR1J9X5C049213
781E54492197	4VZBR1J915C049214
781E54492198	4VZBR1J935C049215
781E54492199	4VZBR1J985C049212
781E54492200	4VZBR1J995C049218
781E54492201	4VZBR1J975C049217
719L54492202	4VZBR1D945C048960
719W54492203	4VZBR1D965C048961
719W54492204	4VZBR1D905C049121
781E54492206	4VZBR1J975C049220
781E54492207	4VZBR1J995C049204
781E54492208	4VZBR1J945C049207
781E54492209	4VZBR1J995C049249
781E54492210	4VZBR1J925C049206
781X54492211	4VZBR1J975C049248
781X54492212	4VZBR1J975C049251
781X54492213	4VZBR1J955C049250
781E54492266	4VZBR1J945C049255
781E54492267	4VZBR1J965C049256
781E54492268	4VZBR1J995C049252
781E54492269	4VZBR1J925C049254
781E54492270	4VZBR1J905C049253
780L54492271	4VZBR1D985C048895
780L54492272	4VZBR1D975C049116
780L54492273	4VZBR1D905C049118
719L54492274	4VZBR1D925C049122
719L54492275	4VZBR1D945C049123
781X54492276	4VZBR1J955C049216
781X54492277	4VZBR1J905C049219
781X54492278	4VZBR1J985C049257
781X54492279	4VZBR1J965C049208
781X54492280	4VZBR1J9X5C049261
781X54492281	4VZBR1J9X5C049258

Fleetwood Serial # Spartan V.I.N.

780J54492282	4VZBR1D995C049117
780J54492283	4VZBR1D925C049184
780J54492284	4VZBR1D995C049182
719J54492285	4VZBR1D985C049125
719J54492287	4VZBR1D965C049124
781E54492288	4VZBR1J985C049260
781E54492289	4VZBR1J915C049259
781E54492290	4VZBR1J995C049266
781E54492291	4VZBR1J935C049263
781E54492292	4VZBR1J905C049267
781E54492349	4VZBR1J955C049197
781E54492350	4VZBR1J985C049209
781E54492351	4VZBR1J925C049271
781E54492352	4VZBR1J905C049270
781E54492353	4VZBR1J915C049262
719L54492356	4VZBR1D915C049192
719L54492357	4VZBR1D9X5C049191
719L54492358	4VZBR1D955C049194
780N54492359	4VZBR1D905C049183
781X54492363	4VZBR1J945C049272
781X54492364	4VZBR1J955C049264
781X54492365	4VZBR1J975C049265
719N54492367	4VZBR1D975C049195
719R54492369	4VZAT1C985C049544
780L54492370	4VZBR1D945C049185
780L54492371	4VZBR1D925C049119
780L54492372	4VZBR1D995C049120
780L54492373	4VZBR1D985C049187
780L54492374	4VZBR1D985C049190
781X54492428	4VZBR1J945C049269
781X54492429	4VZBR1J925C049268
781X54492430	4VZBR1J995C049302
781X54492431	4VZBR1J905C049303
781X54492432	4VZBR1J925C049304
781X54492433	4VZBR1J9X5C049308
781E54492434	4VZBR1J965C049306
781E54492435	4VZBR1J945C049305

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 104 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your ownership, according to the notification, before using or leasing the vehicle. Any vehicle owner receiving this recall notice must forward a copy of the notice to the dealer within ten days.

It is impossible to show, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial # Spartan V.I.N.

781E54492436	4VZBR1J985C049307
781E54492437	4VZBR1J915C049309
781E54492438	4VZBR1J935C049425
781E54492439	4VZBR1J955C049426
781E54492440	4VZBR1J9X5C049311
719N54492441	4VZBR1D925C049282
719L54492442	4VZBR1D945C049283
781X54492444	4VZBR1J975C049427
781X54492445	4VZBR1J985C049310
781X54492446	4VZBR1J995C049428
781X54492447	4VZBR1J975C049430
781X54492448	4VZBR1J905C049429
781X54492449	4VZBR1J945C049434
781E54492450	4VZBR1J995C049431
781E54492451	4VZBR1J905C049432
781E54492452	4VZBR1J965C049435
781E54492453	4VZBR1J925C049433
781E54492454	4VZBR1J935C049439
781E54492455	4VZBR1J915C049438
781L54492456	4VZBR1J985C048920
781E54492508	4VZBR1J985C049436
781E54492509	4VZBR1J925C049531
781X54492510	4VZBR1J905C049530
781X54492511	4VZBR1J945C049529
781X54492512	4VZBR1J945C049532
781X54492513	4VZBR1J965C049533
781X54492514	4VZBR1J915C049536
781X54492515	4VZBR1J935C049537
781X54492516	4VZBR1J985C049534
719J54492517	4VZBR1D965C049284
719J54492518	4VZBR1D985C049416
780J54492520	4VZBR1D915C049189
780J54492521	4VZBR1D9X5C049188
780W54492522	4VZBR1D955C049275
780W54492523	4VZBR1D935C049274
781E54492524	4VZBR1J9X5C049535
781E54492525	4VZBR1J955C049538

Fleetwood Serial # Spartan V.I.N.

781E54492526	4VZBR1J975C049539
781E54492527	4VZBR1J935C049540
781E54492528	4VZBR1J975C049542
781E54492529	4VZBR1J955C049541
781E54492530	4VZBR1J995C049543
781E54492531	4VZBR1J985C049615
781X54492532	4VZBR1J965C049614
781X54492533	4VZBR1J995C049624
781X54492534	4VZBR1J9X5C049616
781E54492536	4VZBR1J915C049617
781E54492537	4VZBR1J975C049623
781E54492538	4VZBR1J935C049618
781E54492539	4VZBR1J905C049625
781E54492540	4VZBR1J915C049620
781E54492541	4VZBR1J955C049703
781E54492542	4VZBR1J935C049621
781E54492543	4VZBR1J955C049619
781E54492544	4VZBR1J925C049626
781X54492545	4VZBR1J945C049627
781X54492546	4VZBR1J965C049628
781X54492547	4VZBR1J9X5C049700
781X54492548	4VZBR1J975C049699
781X54492549	4VZBR1J915C049701
781X54492550	4VZBR1J995C049705
781X54492551	4VZBR1J975C049704
780L54492554	4VZBR1D925C049279
780L54492555	4VZBR1D975C049276
780L54492556	4VZBR1D975C049410
780L54492557	4VZBR1D995C049277
780W54492558	4VZBR1D905C049278
781L54492559	4VZBR1J955C049622
781L54492560	4VZBR1J905C049706
781L54492561	4VZBR1J925C049707
781L54492562	4VZBR1J965C049709
781L54492615	4VZBR1J925C049710
780L54492661	4VZBR1D995C049280
780L54492662	4VZBR1D905C049281

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 114 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall for failure to comply with instructions for proper use of the vehicle, you must repair or otherwise correct the vehicle or vehicle component in your possession. According to this publication, before selling or leasing the vehicle, any dealer must acknowledge that recall notice must forward a copy of this notice to the lessee or buyer.

It is impossible to know, evaluate and advise the service life of an individual used or leased vehicle. It is the responsibility of the owner or lessee to determine the proper use of the vehicle. Although, anyone who uses a vehicle in a manner that is not intended by the manufacturer must understand that neither personal safety nor vehicle safety will be guaranteed by the selected service methods.

2005 American Coach and Fleetwood Revolution LE Serial Numbers

Fleetwood Serial #	Spartan V.I.N.
781L54492663	4VZBR1J985C049713
781L54492664	4VZBR1J945C049806
781L54492665	4VZBR1J965C049807
781L54492666	4VZBR1J925C049805
781L54492667	4VZBR1J985C049808
781L54492668	4VZBR1J945C049711
781L54492669	4VZBR1J945C049708
719Q54492670	4VZBR1D985C049285
719J54492672	4VZBR1J915C049732
719J54492673	4VZBR1D965C049415
781L54492674	4VZBR1J965C049712
719J54492696	4VZBR1D9X5C049417
780L54492706	4VZBR1D995C049411
719L54492707	4VZBR1D9X5C049286
781L54492761	4VZBR1J935C049702
780J54492893	4VZBR1D925C049413
780J54492894	4VZBR1D905C049412
780W54492895	4VZBR1D935C049551
780L54492896	4VZBR1D945C049414
780L54492897	4VZBR1D975C049553
719N54492898	4VZBR1D9X5C049420
719L54492908	4VZBR1D915C049547
780L54492909	4VZBR1D955C049597
719J54492910	4VZBR1D985C049545
780X54493009	4VZBR1D955C049554
780W54493013	4VZBR1D905C049555
719L54493015	4VZBR1D935C049422
719L54493016	4VZBR1D955C049549
719L54493017	4VZBR1D935C049548
780L54493095	4VZBR1D925C049556
719W54493096	4VZBR1D995C049604
780V54493099	4VZBR1D945C049557

Fleetwood Serial #	Spartan V.I.N.
780V54493100	4VZBR1D915C049600
780V54493109	4VZBR1D935C049601
719J54493110	4VZBR1D905C049605
719J54493111	4VZBR1J955C049734
719L54493113	4VZBR1D915C049550
719L54493114	4VZBR1J9X5C049731
719W54493115	4VZBR1J915C049729
780W54493116	4VZBR1J985C049730
719J54493178	4VZBR1D945C049607
780J54493198	4VZBR1D975C049598
719V54493208	4VZBR1D925C049606
780V54493297	4VZBR1D955C049602
780V54493298	4VZBR1J975C049735
780L54493301	4VZBR1D995C049599
719L54493304	4VZBR1D985C049609
719L54493305	4VZBR1D965C049608
719L54493306	4VZBR1D945C049610
719J54493307	4VZBR1D975C049696
780J54493308	4VZBR1D975C049603
719J54493315	4VZBR1D955C049695
780J54493428	4VZBR1J935C049733
719J54493430	4VZBR1D905C049698
780V54493432	4VZBR1J955C049796
780V54493433	4VZBR1J995C049798
780X54493434	4VZBR1J905C049799
780J54493501	4VZBR1J935C049800
780J54493520	4VZBR1J955C049801
780L54493622	4VZBR1J995C049803
780L54493623	4VZBR1J975C049802
719L54493624	4VZBR1D995C049697
719L54493625	4VZBR1J975C049797
719L54493626	4VZBR1J905C049804

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that, if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must report or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor neglecting this recall notice must forward a copy of the notice to the dealer within ten days.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service method.



Tech Tips

Customer Care

Tech Tip No: MH110504A

Date: November 5, 2004

REV: Release

Subject: Relocation of Hydraulic Filter

Applies To: Fleetwood **VDM Range:** 5-27-03 thru 8-4-0 **Specific Models:** MM, K2

For Internal use only: No

Vocation: Motor Home

Reason Classification: A2

Labor Time: 1.0 Hours

Purpose: Replacement of the Spartan Chassis hydraulic filter mounting bracket and associated replacement of air governor fittings for correction of the Fleetwood service center door strut interference with the filter and gauge.

Please Read the Entire Tech Tip Before Proceeding With Any Work.

Scope:

The scope of these instructions shall apply only to the specific replacement, revision or modifications indicated within these instructions for the Spartan Chassis hydraulic filter mounting bracket and related air governor fittings and connections.

Responsibility:

It is the sole responsibility of the person(s) performing the related repairs, revisions or modifications to ensure full comprehension of these instructions and for the proper inspection and analysis of all of the repairs, revision or modifications which are performed in order to prevent accidental damages due to improperly performed repairs, revisions or modifications.

Part and Service Information:

- Hydraulic Center Bracket Support Part # = 1541-FF1-001
- Air Governor Brass Fitting 45D elbow Part # = 0716-MM5-C01

Safety:

Observe all industry safety standards and secure the vehicle before beginning any work on the hydraulic filter assembly system.

Tech Tip Bulletins are intended for use by professional technicians only. They are written to guide professional technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Tech Tips

Customer Care

Procedure:

- 1.0 Remove the two bolts fastening the hydraulic filter assembly to the support bracket.
- 2.0 Discard the old bracket.
- 3.0 Remove the two bracket retaining bolts which fasten the hydraulic filter assembly bracket support to the convenience center, paying close attention to the support bracket orientation for installation of the new support bracket.
- 4.0 Re-attach the hydraulic filter assembly to the new support bracket (p/n 1541-FF1-001) loosely utilizing the original nuts and bolts.
- 5.0 Referring to drawing # 1500-017 titled "SUB ASM-AIR GOVERNOR" remove the hose connection and the brass fitting from (port) # 4 (refer to drawing to determine port # 4).
- 6.0 Take the new brass 45 degree fitting (p/n 0716-MM5-C01) and apply 81801 pipe sealer with Teflon as required to **ONLY THE PIPE THREADS**.
- 7.0 Referring to drawing PAD1500-017 for the proper orientation of the fitting, install the new 45 degree brass elbow fitting into port # 4 on the air governor and reattach and tighten the hose compression connection.
 - 7.1 **NOTE:** Discard the old hose connection insert and utilize the new one provided with the fitting.
- 8.0 Attach and tighten the new support bracket (p/n 1541-FF1-001) to the convenience center with the two original bolts.
- 9.0 Slide the hydraulic filter center assembly inboard by 1.0" inch and then tighten the nuts and bolts.
- 10.0 Inspect the completed assembly to ensure there are not any interference points with the door strut, hoses or structures. If interference is found, loosen the hydraulic filter assembly at the bracket and adjust on the slotted bracket until the proper clearances are obtained.
- 11.0 Inspect the hydraulic center for leaks and repair as required to correct any problems.

Tech Tip Bulletins are intended for use by professional technicians only. They are written to guide professional technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Tech Tips

Customer Care

- 12.0 Inspect the air governor for any leaks and for the proper hose clearance. Adjust and repair as required to correct any problems.

Filter Element Inspection:

Visually inspect the hydraulic oil filter element for damages from rubbing against the door strut. Replace the filter element if damaged.

NOTE: This step is not covered in the labor rate for this Tech Tip repair procedure.

Related Documents:

- Drawing PAD1500-017 Sub asm-air governor



C:\Documents and
Settings\scmrsha\M

Tech Tip Bulletins are intended for use by professional technicians only. They are written to guide professional technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

