#### **TECHNICAL INSTRUCTIONS**

## **FOR**


# SPECIAL SERVICE CAMPAIGN 70A (NON-COMPLIANCE RECALL)

## 2003 THROUGH MID-2005 MODEL YEAR 'TUNDRA ACCESS CAB CHILD RESTRAINT ANCHORAGE CAUTION LABEL

#### **NOTE:**

Owners will be directly mailed the label for this issue. Please assist any owner with label installation if <u>requested</u>.

# I. OPERATION FLOW CHART



#### II. IDENTIFICATION OF AFFECTED VEHICLES

#### A. AFFECTED VINS

- Check Dealer Daily/TIS to confirm the VIN is involved in this SSC. This will verify the
  vehicle is affected and has not already been completed prior to dealer shipment or by
  another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.


#### III. PREPARATION

#### A. PARTS

The caution label will be included in the owner letter for customer vehicles.

#### IV. WORK PROCEDURE

#### A. INSPECT THE GLOVE BOX FOR THE CAUTION LABEL



1) Is the label already installed?


#### YES

No further action required

#### NO

Proceed to "B. INSTALL THE CAUTION LABEL."

## **B. INSTALL THE CAUTION LABEL**



- 1) Wipe the area where the caution label will be affixed with a clean, dry cloth to remove any dust or dirt.
- 2) Affix the label at the indicated location while smoothing out any air bubbles in the new label.