



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

September 12, 2005

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 05V-373

Dear Country Coach Service Provider:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach has decided that a defect which relates to motor vehicle safety exists in certain 2005 Affinity and Magna motorhomes and 2005 and 2006 Intrigue motorhomes. That HWH hydraulic slide room hoses installed in the engine compartment could cause the HWH slide room hoses to blister and leak due to the engine heat generated in this compartment. Loss of hydraulic fluid could cause the slide room to unexpectedly extend while in-transit. This can result in a vehicle crash.

MODELS AFFECTED (See attached listing for specific units involved):

Model Year: 2005 Affinity Motorhomes manufactured from March 2004 to November 2004

VIN Range: 4U7D9FZ1351104008 – 4U7D9FZ1X51104426

Model Year: 2005 Magna Motorhomes manufactured from March 2004 to November 2004

VIN Range: 4U7V9FZ1151103788 – 4U7C9FZ1251104416

Model Year: 2004 Intrigue Motorhomes manufactured from May 2004 to July 2004

VIN Range: 4U7B8DZ1441103995 – 4U7B8DZ1541104167

Model Year: 2005 Intrigue Motorhomes manufactured from August 2004 to March 2005

VIN Range: 4U7B8DY1951104238 – 4U7B8DZ1151104670

**VEHICLE SAFETY
DEFECT NOTICE**

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer service department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time (Please see the enclosed Letter to Country Coach Owners).

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

Enclosure: Customer Notification

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

September 12, 2005

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 0V5-373

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach has decided that a defect which relates to motor vehicle safety exists in certain 2005 Affinity and Magna motorhomes. That HWH hydraulic slide room hoses installed in the engine compartment could cause the HWH slide room hoses to blister and leak due to the engine heat generated in this compartment. Loss of hydraulic fluid could cause the slide room to unexpectedly extend while in-transit. This can result in a vehicle crash.

MODELS AFFECTED (See attached listing for specific units involved):

Model Year: 2005 Affinity Motorhomes manufactured from March 2004 to November 2004

VIN Range: 4U7D9FZ1351104008 – 4U7D9FZ1X51104426

Model Year: 2005 Magna Motorhomes manufactured from March 2004 to November 2004

VIN Range: 4U7V9FZ1151103788 – 4U7C9FZ1251104416

Model Year: 2004 Intrigue Motorhomes manufactured from May 2004 to July 2004

VIN Range: 4U7B8DZ1441103995 – 4U7B8DZ1541104167

Model Year: 2005 Intrigue Motorhomes manufactured from August 2004 to March 2005

VIN Range: 4U7B8DY1951104238 – 4U7B8DZ1151104670

Country Coach has determined that the repair for this safety defect will be the relocation of the affected hoses out of the engine compartment. This repair and associated parts will be performed and provided at no cost to the owner. The labor required to perform this repair is not expected to exceed six (6.0) hours. Please present this letter and the enclosed warranty claim to the dealer when you take your motorhome in to be serviced. The service facility that does the repairs will need the warranty claim for their billing.

remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Country Coach customer service by calling 1-800-452-8015 and ask for the Technical Service Representative handling this recall.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Country Coach Inc. Compliance Administration at 1-800-452-8015, extension 8382.

If after contacting both your dealer and Country Coach you are not satisfied that the noncompliance has been remedied within a reasonable time, and at no cost to you, you may wish to contact the National Highway Traffic Safety Administration:

Administrator
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington D.C. 20590

Vehicle Safety Hotline's toll free number: 1-888-327-4236 (TTY: 1-800-424-9153)


On-line at: [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV)

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.

Enclosures (2): Vehicle Reply Card
Warranty Claim

COACH LISTING 05V-373

CC#	Model	VIN
6368	MMT-45-RM-ABCD-05	4U7C9FZ1451103798
6369	MMT-45-RM-ABCD-05	4U7C9FZ1651103799
6373	MMT-45-RM-ABCD-05	4U7C9FZ1751103889
6375	MMT-45-RM-ABCD-05	4U7C9FZ1651103897
6377	MMT-42-MN-ABCD-05	4U7C9EZ1551103903
6378	MMT-42-MN-ABCD-05	4U7C9EZ1251103910
6385	MMT-45-RM-ABCD-05	4U7C9FZ1551103969
6388	MMT-45-RM-ABCD-05	4U7C9FZ1851103979
6390	MMT-45-RM-ABCD-05	4U7C9FZ1X51103983
6393	MMT-45-RM-ABCD-05	4U7C9FZ1551103986
6394	MAT-45-SL-ABCD-05	4U7D9FZ1351104008
6395	MMT-45-RM-ABCD-05	4U7C9FZ1051104009
6399	MMT-42-MN-ABCD-05	4U7C9EZ1651104039
6400	MAT-45-SL-ABCD-05	4U7D9FZ1X51104040
6401	MMT-45-RM-ABCD-05	4U7C9FZ1951104042
6404	MMT-45-RM-ABCD-05	4U7C9FZ1451104045
6405	MMT-42-MN-ACD-05	4U7C9EZ1451104069
6415	MAT-45-AV-ABCD-05	4U7D9FZ1451104132
6416	MMT-45-RM-ABCD-05	4U7C9FZ1251104139
6419	MMT-45-RM-ABCD-05	4U7C9FZ1151104164
6428	MMT-42-MN-ABCD-05	4U7C9EZ1251104197
6429	MAT-45-AV-ABCD-05	4U7D9FZ1451104213
6435	MMT-40-MT-ABCD-05	4U7C9DZ1851104232
6440	MAT-45-AV-ABCD-05	4U7D9FZ1251104260
6441	MMT-45-RM-ABCD-05	4U7C9FZ1X51104261
6442	MAT-42-AP-ABCD-05	4U7D9EZ1251104270
6447	MMT-42-MN-ABCD-05	4U7C9EZ1951104309
6449	MMT-45-RM-ABCD-05	4U7C9FZ1151104312
6450	MAT-45-AV-ABCD-05	4U7D9FZ1151104332
6451	MMT-40-MT-ABCD-05	4U7C9DZ1251104341
6452	MAT-45-AV-ABCD-05	4U7D9FZ1X51104345
6455	MMT-42-VG-ABCD-05	4U7C9EZ1951104343
6457	MMT-40-MT-ABCD-05	4U7C9DZ1951104367
6464	MMT-45-RM-ABCD-05	4U7C9FZ1451104403
6466	MMT-42-MN-ABCD-05	4U7C9EZ1251104409
6467	MAT-45-AV-ABCD-05	4U7D9FZ1X51104426
6468	MMT-45-RM-ABCD-05	4U7C9FZ1251104416
11830	MIT-40-SN-ABCD-04	4U7B8DZ1441103995
11831	MIT-40-SN-ABCD-04	4U7B8DY1441103996
11832	MIT-40-SN-ABCD-04	4U7B8DY1X41103999
11833	MIT-40-SN-ABCD-04	4U7B8DY1041104000
11837	MIT-40-SN-ABCD-04	4U7B8DY1041104031
11838	MIT-40-SN-ABCD-04	4U7B8DY1141104037
11842	MIT-40-SN-ABCD-04	4U7B8DZ1X41104066
11843	MIT-40-SN-ACD-04	4U7B8DY1741104091

COACH LISTING 05V-373

11846	MIT-40-SN-ABCD-04	4U7B8DY1241104094
11848	MIT-40-SN-ACD-04	4U7B8DY1X41104103
11853	MIT-40-SN-ABCD-04	4U7B8DY1X41104120
11854	MIT-40-SN-ABCD-04	4U7B8DZ1X41104133
11855	MIT-40-SN-ABCD-04	4U7B8DY1541104140
11857	MIT-40-SN-ABCD-04	4U7B8DZ1541104167
11864	MIT-40-SN-ABCD-05	4U7B8DY1951104238
11866	MIT-40-SN-ABCD-05	4U7B8DY1751104240
11869	MIT-40-SN-ACD-05	4U7B8DY1351104249
11871	MIT-40-SN-ABCD-05	4U7B8DY1551104253
11873	MIT-40-SN-ABCD-05	4U7B8DY1951104255
11875	MIT-40-SN-ABCD-05	4U7B8DY1251104257
11877	MIT-40-SN-ABCD-05	4U7B8DY1851104263
11879	MIT-40-SN-ABCD-05	4U7B8DY1X51104295
11881	MIT-40-SN-ABCD-05	4U7B8DZ1151104314
11882	MIT-40-SN-ABCD-05	4U7B8DY1151104315
11883	MIT-40-SN-ABCD-05	4U7B8DY1951104319
11885	MIT-40-SN-ABCD-05	4U7B8DZ1351104346
11887	MIT-40-SN-ABCD-05	4U7B8DY1651104360
11888	MIT-40-SN-ACD-05	4U7B8DY1X51104359
11892	MIT-40-SN-ABCD-05	4U7B8DY1551104382
11894	MIT-40-SN-ABCD-05	4U7B8DZ1051104384
11898	MIT-40-SN-ABCD-05	4U7B8DZ1551104462
11904	MIT-40-SN-ABCD-05	4U7B8DY1151104492
11905	MIT-40-SN-ABCD-05	4U7B8DZ1551104493
11907	MIT-40-SN-ABCD-05	4U7B8DY1751104500
11909	MIT-40-SN-ABCD-05	4U7B8DZ1251104502
11911	MIT-40-SN-ABCD-05	4U7B8DY1351104509
11914	MIT-40-SN-ABCD-05	4U7B8DY1551104544
11915	MIT-40-SN-ABCD-05	4U7B8DZ1051104563
11918	MIT-40-SN-ABCD-05	4U7B8DY1051104564
11920	MIT-40-SN-ABCD-05	4U7B8DY1651104598
11922	MIT-40-SN-ABCD-05	4U7B8DZ1751104625
11924	MIT-40-SN-ABCD-05	4U7B8DZ1151104670