



U.S. Department  
of Transportation

400 Seventh Street, SW  
Washington, DC 20590

**National Highway  
Traffic Safety  
Administration**

*September 22, 2006*

ROBERT BABCOCK  
MANAGER, CERTIFICATION AND  
COMPLIANCE AFFAIRS  
HYUNDAI-KIA MOTORS  
6800 GEDDES ROAD  
SUPERIOR TOWNSHIP MI 48198

NVS-215  
06V-356

Subject: STOP LAMP SWITCH WIRING HARNESS

Dear MR. BABCOCK:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**  
HYUNDAI/ENTOURAGE/2007

**NHTSA Campaign Number:** 06V-356

**Mfg's Report Date:** September 13, 2006

**Components:** ELECTRICAL SYSTEM:WIRING

**Potential Number of Units Affected:** 790

**Summary:**

ON CERTAIN MINIVANS EQUIPPED WITH ADJUSTABLE BRAKE PEDALS, THE STOP LAMP SWITCH WIRING HARNESS MAY BE OUT OF POSITION. AN IMPROPERLY POSITIONED STOP LAMP SWITCH WIRING HARNESS COULD MAKE CONTACT WITH THE U-JOINT ASSEMBLY OF THE STEERING COLUMN. REPEATED CONTACT MAY EVENTUALLY CAUSE THE WIRING HARNESS INSULATION TO CHAFE.

**Consequence:**

CHAFED INSULATION COULD CAUSE A SHORT OF THE WIRING HARNESS RESULTING IN THE LOSS OF BRAKE LIGHTS, ENGINE STALLING, OR AN INABILITY TO START THE VEHICLE INCREASING THE RISK OF A CRASH.

**Remedy:**

DEALERS WILL INSPECT THE WIRING HARNESS FOR CHAFING AND, REPAIR IF NECESSARY. IN ADDITION, THE DEALER WILL SECURE THE WIRING HARNESS TO PREVENT CONTACT WITH THE U-JOINT ASSEMBLY. THE RECALL IS EXPECTED TO BEGIN ON OCTOBER 6, 2006. OWNERS MAY CONTACT HYUNDAI AT 1-800-633-5151.

**Notes:**

HYUNDAI RECALL NO. 078. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin on October 6, 2006. Therefore, the first quarterly report will be due on or before January 30, 2007.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at [patricia.wallace@dot.gov](mailto:patricia.wallace@dot.gov) or [delia.lopez@dot.gov](mailto:delia.lopez@dot.gov). We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person  
Chief, Recall Management Division  
Office of Defects Investigation, Enforcement