

U.S. Department of Transportation

National Highway Traffic Safety Administration

October 27, 2006

GAY KENT DIRECTOR, PRODUCT INVESTIGATIONS GENERAL MOTORS CORP. FOR SAAB CARS USA, INC. 30500 MOUND ROAD - 480-106-304 WARREN MI 48090-9055 NVS-215 06V-410

400 Seventh Street, SW

Washington, DC 20590

Subject: ENGINE STALLING

Dear MS. KENT:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: SAAB/9-5/2002-2003

NHTSA Campaign Number: 06V-410

Mfg's Report Date: October 23, 2006

Components: ELECTRICAL SYSTEM:IGNITION:MODULE

Potential Number of Units Affected: 5,078

Summary:

CERTAIN PASSENGER VEHICLES EQUIPPED WITH B308 6-CYLINDER GASOLINE ENGINES MAY EXPERIENCE OVERHEATING AND BURNOUT OF THE ISOLATED GATED BIPOLAR TRANSISTOR (IGBT) WITHIN THE IGNITION DISCHARGE MODULE (IDM) DUE TO INCREASED SUSCEPTIBILITY TO ELECTRICAL LOADS.

Consequence:

OVERHEATING OF THE IGBT OCCURS MOST OFTEN AT ENGINE START-UP, BUT IT MAY ALSO OCCUR WHILE THE ENGINE IS RUNNING. ENGINE STALLING MAY OCCUR, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL INSPECT TO SEE WHAT VERSION IDM IS IN THE VEHICLE AND REPLACE THE IDM IF IT IS A VERSION BUILT PRIOR TO JANUARY 2003. THE RECALL IS EXPECTED TO BEGIN DURING DECEMBER 2005. OWNERS MAY CONTACT SAAB AT 1-800-955-9007. NOTE: THIS RECALL IS AN EXPANSION OF A PREVIOUS CAMPAIGN (PLEASE SEE 05V399).

Notes:

SAAB RECALL NO. 05087/15021B. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

This recall was the subject of a Preliminary Evaluation, PE05-017, conducted by the Office of Defects Investigation.

Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during December 2006. Therefore, the first quarterly report will be due on or before January 30, 2007.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at <u>patricia.wallace@dot.gov</u> or <u>delia.lopez@dot.gov</u>. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person Chief, Recall Management Division Office of Defects Investigation Enforcement