



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

December 21, 2006

RON MUNDT
HARLEY-DAVIDSON MOTOR COMPANY
3700 JUNEAU AVENUE
MILWAUKEE WI 53208

NVS-215
06V-476

Subject: VOLTAGE REGULATOR

Dear MR. MUNDT:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HARLEY DAVIDSON/XL1200C/2007
HARLEY DAVIDSON/XL1200L/2007
HARLEY DAVIDSON/XL1200R/2007
HARLEY DAVIDSON/XL50/2007
HARLEY DAVIDSON/XL883/2007
HARLEY DAVIDSON/XL883C/2007
HARLEY DAVIDSON/XL883L/2007
HARLEY DAVIDSON/XL883R/2007

NHTSA Campaign Number: 06V-476

Mfg's Report Date: December 14, 2006

Components: ELECTRICAL SYSTEM: ALTERNATOR/GENERATOR/REGULATOR

Potential Number of Units Affected: 18,758

Summary:

ON CERTAIN MOTORCYCLES, AS A RESULT OF A GREATER BODY THICKNESS THAN USED IN PREVIOUS MODEL YEARS, THE VOLTAGE REGULATOR MAY CONTACT THE FRONT FENDER UNDER CERTAIN CONDITIONS. IN SOME CASES THIS CONTACT MAY ALLOW THE FRONT FENDER TO CATCH ON THE TOP SIDE OF THE REGULATOR BODY WHICH COULD IMPEDE THE OPERATOR'S ABILITY TO STEER THE VEHICLE.

Consequence:

THIS COULD RESULT IN A CRASH WHICH COULD CAUSE INJURY OR DEATH TO THE RIDER.

Remedy:

DEALERS WILL INSTALL AN INTERMEDIATE MOUNTING BRACKET THAT WILL RELOCATE THE VOLTAGE REGULATOR TO A POSITION WHICH PROVIDES MORE CLEARANCE FROM THE FRONT FENDER. HARLEY-DAVIDSON HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT HARLEY-DAVIDSON AT 1-414-343-4056.

Notes:

HARLEY-DAVIDSON RECALL NO. 0128. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

We have reviewed your proposed owner letter and it meets the requirements of Part 577.


Please provide the following additional information and be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners as soon as it becomes available.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement