06 E-018 (6 pg s.)

# Safety Defect and Noncompliance Report Guide for Equipment PART 573 Defect and Noncompliance Report<sup>4</sup>

On January 26 , 2006, For	reign Parts Dist., Inc. decided that (a defect which
• • • • • • • • • • • • • • • • • • • •	ncompliance with Federal Motor Vehicle Safety Standard
	vehicle equipment listed below, and is furnishing
· ·	Traffic Safety Administration in accordance with 49
CFR Part 573 <u>Defect and Noncompl</u>	liance Reports.
Date this report was prepared:	January 30, 2006
Furnish the manufacturer's identified	cation code for this recall (if applicable): 171.611.701B
owner of the recalled item of equipm	of the fabricating manufacturer/brand name/trademark nent. If the recalled item of equipment is imported, ess of the designated agent as prescribed by 49 U.S.C.
JP Group A/S	Imported by: Foreign Parts Distributors, Inc.
Hjulmagervej 5	545 W. 18th Street
DK-8800, Viborg Denmark	Hialeah, FL 33010
Identify the corporate official, by na respect to this recall.  Steve Feig - President, Foreig	me and title, whom the agency should contact with make and title, whom the agency should contact with
<b>Telephone Number:</b> (305) 885–864	46 ext. 11 <b>Fax No.:</b> (305) 88 <b>9</b> -3824
Name and Title of Person who prepare	ared this report.
Steve Feio	
/ <b>)</b> / <b>)</b>	
President	
Signed: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	SiDeN1
(,t° (),	and the second
1	Tribute of the control of the contro
- · · <del>- · ·</del>	· · · · · · · · · · · · · · · · · · ·

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. Jon White at (202) 366-5226 or by FAX at (202) 366-7882.

<sup>&</sup>lt;sup>4</sup>Each manufacturer must furnish a report, to the Associate Administrator for Safety Assurance, for each defect or noncompliance condition which relates to motor vehicle safety.

### I. Identify the Recalled Items of Equipment

2. Identify the Items of Equipment Involved in this Recall, for each make and model or

applicable item of equipment product line (provide illustrations or photographs as necessary to describe the item of equipment), provide: Generic name of the item: hydraulic brake hose Make: JP Group A/S \_\_\_ Model: \_\_\_\_\_\_ **Part Number**: 171.611.701B **Size**: 320 mm Function: transfer of brake fluid Other information which characterizes/distinguishes the items of equipment to be recalled: 171.611.701L A L T - marked on hose / replacement part for Volkswagen ("VW") Rabbit (1975-84); VW Golf (1985-92); VW Jetta (1980-92) Make: \_\_\_\_\_ Model: \_\_\_\_ Part Number: \_\_\_\_\_ Size: \_\_\_\_ Other information which characterizes/distinguishes the items of equipment to be recalled: Make: \_\_\_\_\_ Model: \_\_\_\_\_ Part Number: \_\_\_\_\_ Size: \_\_\_\_ Function: Model Years Involved: Other information which characterizes/distinguishes the items of equipment to be recalled: Make: \_\_\_\_\_ Model: \_\_\_\_ Part Number: \_\_\_\_\_ Size: \_\_\_\_\_ Function: Other information which characterizes/distinguishes the items of equipment to be recalled:

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Widgets equipped with certain items of equipment from January 1, 1996, through April 1, 1997, then what was the percentage of the recalled Widgets of all Widgets manufactured during that time period.

100% of hydraulic brake hoses part 171.611.701B imported by Foreign Parts Distributors, Inc. from JP Group A/S

### II. Identifying the Recall Population

3. Furnish the total number of items of equipment recalled potentially containing the defect or noncompliance.

Model	Year	Number of Items Potentially Involved
JP Group A/S hydraulic	2004-2006 sales of	266 Total
brake hose part 171.611.701B	replacement parts	
Total Number Potentially Affected be Recall:	y the266	
4. Furnish the approximate percent to actually contain the defect or none	9	6 imported hydraulic brake
Identify and describe how the recall recalled models were selected and the of the recalled items of equipment:	population was determinedi e basis for the beginning and	n particular how the final dates of manufacture
were deemed defective and subj	ect to recall. The impor	rter maintained computer
records of all its purchasers	of such hydraulic brake h	nose.

# III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.
Improper equipment markings under FMVSS 106, failure of hydraulic brake hose
water absorption-burst tests, single hose failure of hyraulic brake hose burst
strength test as set forth in Intertek Testing Report No.106-ITS-06-004/06-3078536
(the "Intertek Report")
Describe the cause(s) of the defect or noncompliance condition.  Failure of foreign manufacturer to include required markings. Production defect.
Describe the consequence(s) of the defect or noncompliance condition.
Possible brake hose rupture, but neither the original manufacturer nor the
importer has ever had the item returned or has been advised of any adverse
consequence by any customer.
Identify any warning which can (a) precede or (b) occur.  Unknown
If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.  JP Group A/S
Hjulmagervej 5
DK-8800, Viborg Denmark
Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:  Martin Pedersen - General Manager

## IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims. None reported. Defect noted in NHTSA after market product testing.							
7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.							
See copy of the Intertek Report attached hereto.							
V. Identify the Remedy							
8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.							
Ceased sales and removed product from shelf and returned to vendor (JP Group).							

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

Remedy-will be replaced with FMVSS 106 compliant brake hose.

Remedy component will have two clearly identifiable stripes <sup>1</sup>/16 of an inch in width on opposite sides of hose, identification of manufacturer stamped or etched on end fitting. Recalled component did not have the preceding distinguishing characteristics. Replacement item will be certified as having met the performance testing parameters of FMVSS 106.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

Company	ceased	purchas	se of a	and re	moved	exist.	ing st	tock bi	rake	hoses t	rom stoc	k,
and will	replac	ce previ	ously	sold	brake	hoses	with	FMVSS	106	certifi	ed brake	hoses
			-									<del></del>

### VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

Importer (Foreign Parts Distributors) has contacted by phone all of its purchasers of the defective brake hoses, and a substantial number of the hoses are being returned for refund or replacement (see attached recall phone log). Importer will, within 30 days, provide formal, written notification of the recall of the defective brake hoses and will provide each of its customers with posters and/or bulletins to aid its customers in notifying their customers of the recall.

#### VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) for review prior to mailing.

Note: These documents are to be submitted separately from those provided in accordance with Part 573.8 requirements.