



BUELL MOTORCYCLE COMPANY
3700 WEST JUNEAU AVE. MILWAUKEE, WI 53201
414.342.4880 | buell.com

06E-061
(2pgs.)

July 7, 2006

Ms. Kathleen C. DeMeter
Director of Office of Defects Investigation
National Highway Traffic Safety Administration
US Department of Transportation, Room 5326
400 Seventh Street, SW
Washington, DC 20590

Dear Ms. DeMeter:

The following information is submitted in accordance with National Highway Traffic Safety Administration's reporting regulations, 49CFR Part 573.6.

Buell Distribution Company, LLC has learned that a condition affecting safety exists on certain accessory tall windscreens.

IDENTIFICATION OF EQUIPMENT POTENTIALLY CONTAINING THE DEFECT:

The part number for the accessory tall windscreen involved in this recall is PN 58214-06YA. It has been sold exclusively for use on the 2006 MY Buell Ulysses model motorcycle. There have been approximately 303 accessory (aftermarket) tall windscreens shipped with this condition.

DESCRIPTION OF DEFECT:

Buell Distribution Company, LLC has determined that the retention fasteners for the subject accessory tall windscreen could fail. As a result, the accessory tall windscreen could become dislodged while the vehicle is being ridden at highway speed. The result of this defect is that the windscreen may either strike or distract the rider, possibly causing death or injury.

SUPPLIER INFORMATION:

New Berlin Plastics
Mark Siewert
Executive Contact
5725 South Westridge Drive
New Berlin, WISCONSIN 53151 US
Phone: 262-784-3120 ext. 105
Fax: 262-784-0140
CellPhone: 414-416-5413
Email: msiewert@nbplastics.com

CHRONOLOGY OF EVENTS:

In April, 2006, we started receiving reports of the Ulysses accessory windscreen disengagement in the field. A shipping hold was placed on the accessory windscreen at our distribution center on April 28, 2006, while an investigation and analysis was launched. On June 29, 2006 Buell Distribution Company, LLC declared a safety recall on the Ulysses Accessory Tall Windscreen, part # 58214-06YA.

DESCRIPTION OF THE PROGRAM TO REMEDY THE DEFECT:

The correction for this issue is to replace the two lower mounting pins with bolts.

BUELL PRE-NOTIFICATION REMEDY REIMBURSEMENT PROGRAM:

Buell incorporates by reference herein the general reimbursement plan it has previously provided to NHTSA for reimbursing customers for remedy costs incurred prior to notification of this recall.

PART 577 NOTICE LETTER:

A draft of the owner notification letter is attached.

Please advise the undersigned of the campaign number assigned by ODI to this recall.

Sincerely,



Ronald L. Mundt
For Buell Distribution Company, LLC