## **VOLKSWAGEN** of America, Inc.

400-215

2006 WAR 22 P 3: 37

DEFECTS INVESTIGATION

Product Compliance 3800 Hamlin Road Auburn Hills, MI 48326 Phone: 1 (248) 754-5000 Fax: 1 (248) 754-5093

March 20, 2006

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
U.S. Department of Transportation
400 Seventh Street, S.W.
Washington, DC 20590

Subject: Amended Notification of Recall Pursuant to 49 CFR Part 573 (2006)

2003 Model Year Volkswagen Passat; Audi A4 Quattro, and Audi A6 vehicles equipped

with 2.8LV6, 1.8L Turbo, or 3.0L engine; Fuel Pump - NHTSA No. 06V-017

Dear Mr. Smith:

This will amend our Notification of Recall Pursuant to 49 CFR Part 573 (2006) submitted on January 17, 2006. The following parts have been updated:

## 573.6 (c) (2) Identification of Vehicles

VIN Numbers

: Volkswagen Passat:

of Affected Vehicles WVW\_\_\_3B\_3\_149975 - WVW\_\_\_3B\_3\_432806

Audi A6:

WAU 4B 3N018382 - WAU\_ \_ 4B\_3N098715

Audi A4 Quattro:

WAU\_\_\_8E\_3A166675 - WAU\_\_\_8E\_3A356965

## 573.6 (c) (4) Percentage of Vehicles Actually Containing Defect

VWoA has determined that approximately 78% of vehicles within this VIN range are affected; as approximately 22% have already had the defective fuel pump replaced under warranty with non-affected service parts free of charge to the customer.

## 573.6 (c) (8) Proposed Remedial Program

VWoA plans to notify all owners of unrepaired affected vehicles and will instruct these owners to arrange an appointment with an authorized dealer. The dealers will install a new fuel pump with improved carbon brush sets at no cost to customers.

Sincerely,

John Maddox

Product Compliance Officer