



COUNTRY COACH

Mr. George Person
Chief, Recall Management Office
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington, D.C. 20590

June 21, 2006

Subject: 573 Submittal

Dear Mr. Person:

Country Coach was notified certain motor home shells manufactured by Prevost Car Inc. may have a safety defect in the exhaust system of the Detroit Diesel Series 60 motor home engine. The turbocharger could fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

To date, Country Coach, Inc. has not been notified of any incidents or accidents involving the subject equipment.

Country Coach will mail the Safety Notification and a copy of the Detroit Diesel Corporation notification to the owners of the affected motor homes. All necessary repairs will be made through an authorized Detroit Diesel distributor with all reimbursements for labor and parts processed through the Detroit Diesel Corporation pursuant to the attached Safety Defect Report Pursuant to 49 CFR Part 573. This work will be performed free of charge to the owner's of Country Coach motor homes with the Series 60 Detroit Diesel engine on a Prevost Car, Inc. chassis.

Please let me know if you have any questions.

Sincerely,

Dick Sabath
Country Coach Inc.
Senior Manager, Compliance Administration

Enclosures

Safety Defect Report
Detroit Diesel Corp. Campaign Bulletin DDC 06C-4

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

06 JUN 21 P 2:54
DEPT. OF INVESTIGATION

06V-285
(9 pages)

**Safety Defect Report
Pursuant to 49 CFR part 573**

Country Coach, Inc. has been notified that certain motor home shells manufactured by Prevost Car may have a safety defect in the exhaust system of the Detroit Diesel Series 60 Motor Home engine. Country Coach is providing notification to your office in accordance with 49 CFR Part 573.

The information required by your regulations follows.

1. 573.5 (c)(1) Manufacturer's name and address.

Country Coach, Inc.
135 East First Ave.
P.O. Box 400
Junction City, OR 97448

2. 573.5 (c)(2) Equipment involved in this notification:

Model Years: 2001
VIN Range: 2PCW33495Y1027187
Vehicle Type: MPV
Bodystyle: Motor Home
Beginning and Ending Manufacturing Dates: Nov 2000

Model Years: 2005
VIN Range: 2PCW3349941028322 – 2PCW3349X51028377
Vehicle Type: MPV
Bodystyle: Motor Home
Beginning and Ending Manufacturing Dates: May – Oct 2004

Model Years: 2006
VIN Range: 2PCW339251028390 – 2PCW3349151028686
Vehicle Type: MPV
Bodystyle: Motor Home
Beginning and Ending Manufacturing Dates: Nov – Dec 2005

Model Years: 2007
VIN Range: 2PCW3349X51028721 – 2PCW3349861028791
Vehicle Type: MPV
Bodystyle: Motor Home
Beginning and Ending Manufacturing Dates: Jan – May 2006

3. **573.5 (c)(3) Total number of items of equipment:**

A cumulative total of 25 motor homes are involved all of which are consumer owned.

4. **573.5 (c)(4) Approximate percentage of equipment estimated to actually contain the noncompliance:**

According to Prevost Car, Inc., 100% of the motor homes identified in item 2, above, may exhibit this safety defect.

5. **573.5 (c)(5) Description of the noncompliance:**

Brief summary of noncompliance:

Country Coach was notified certain motor home shells manufactured by Prevost Car Inc. may have a safety defect in the exhaust system of the Detroit Diesel Series 60 motor home engine. The turbocharger could fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

A copy of the notice from Prevost Car Inc. is attached.

6. **If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.**

Primary:

Prevost Car Inc.
Highway Coach Manufacturer
After-Sales Service Department/Service
850, ch. Olivier
Saint-Nicolas, Quebec, Canada, G7A 2N1

Secondary:

Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, MI 48239-4001

7. Chronological summary of events leading to this determination:

July 19, 2006, Prevost Car Inc. notified Country Coach, Inc. that a Safety Recall (DDC 06C-4) had been issued by Detroit Diesel Corporation regarding the exhaust system in certain Series 60 Motor Home engines.

To date there have been no incidents reported to Country Coach, Inc. involving this defect.

8. 573.5 (c)(8) Description of proposed remedy:

Detroit Diesel Corporation will make all necessary repairs through an authorized Detroit Diesel distributor. All reimbursements for labor and parts will be processed through the Detroit Diesel Corporation. This work will be performed free of charge to the owner's of Country Coach motor homes with the Series 60 Detroit Diesel engine on a Prevost Car, Inc. chassis.

9. Program for Remedy Campaign:

Country Coach, Inc. will notify all owners of the affected motor homes of Detroit Diesel's offer to repair the defect in the exhaust system free of charge. Noncompliance notices including copies of the notifications from Prevost Car, Inc. and Detroit Diesel Corporation will be mailed to the owners of the affected motor homes and a Dealer Vehicle Safety Noncompliance Service Bulletin will be mailed to all dealers on or before 1 August 2006. All mailings will be by Certified Mail, Return Receipt Requested, and First Class Mail.

PREVOST

June 12, 2006

COUNTRY COACH, INC.
135 EAST FIRST AVENUE
JUNCTION CITY OR 97448
US

Dear Customer,

The following is to inform you of an important Safety Recall (DDC 06C-4) that needs to be done in the exhaust systems in certain Series 60 coach or Motor Home engines.

Detroit Diesel Corporation has determined that the turbocharger can fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.


As per Detroit Diesel Corporation, your vehicle is equipped with one of these affected engines. DDC will repair your engine at no charge to you by reprogramming the ECM to prevent the possibility of a turbocharger failure progressing to an engine compartment fire. DDC estimates that it will take 0.5 hour to reprogram your engine. In addition to reprogramming your engine, certain model year engines will need to have a barometric pressure sensors and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. **Please contact your authorized Detroit Diesel distributor to arrange a service date.**

Along with this letter is an official copy of the letter received from Detroit Diesel Corporation. Please take note that the affected coach serial number and engine serial number are listed at the end of this letter.

Should you have any questions, you can either contact the undersigned or your local Detroit Diesel dealer.

We are sorry for the inconvenience this may have caused you. Thank you for your understanding.

Sincerely,



Josyane Côté, Eng.
Publication Manager & Technical Representative
Enclosure

Coach VIN number:

2PCW3349361028822
2PCW3349411027560
2PCW3349X51028377
2PCW3349251028390
2PCW3349351028396
2PCW3349551028416
2PCW3349251028423
2PCW3349251028440
2PCW3349X51028489
2PCW3349751028496
2PCW3349051028534
2PCW3349851028572
2PCW3349651028604
2PCW3349051028615
2PCW3349X51028640
2PCW3349651028683
2PCW3349151028686
2PCW3349X51028721

Engine serial number:

06R0836997
06R0628494
06R0759800
06R0760106
06R0762800
06R0769173
06R0770765
06R0774278
06R0784099
06R0785206
06R0798593
06R0805188
06R0809893
06R0812557
06R0818124
06R0830350
06R0827772
06R0835724

PRÉVOST CAR INC.

MANUFACTURIER D'AUTOCARS • HIGHWAY COACH MANUFACTURER
AFTER-SALES SERVICE DEPARTMENT / SERVICE APRÈS-VENTE
850, ch. Olivier, Saint-Nicolas, (Qc), Canada, G7A 2N1 • Tél. : (418) 831-2046, Fax : (418) 831-9301



Attention Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Detroit Diesel Corporation (DDC) has decided that a defect which relates to motor vehicle safety exists in the exhaust systems in certain Series 60 Coach and Motor Home engines.

The turbocharger can fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

Records available to us indicate that your vehicle is equipped with one of these affected engines. DDC will repair your engine at no charge to you by reprogramming the ECM to prevent the possibility of a turbocharger failure progressing to an engine compartment fire. We estimate that it will take approximately 0.5 hours to reprogram your engine. In addition to reprogramming the ECM, certain model year engines will need to have barometric pressure sensors and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. Please contact your authorized repair facility to arrange a service date.

If you have any questions about this recall campaign, you may call 313-592-3708. If you believe that DDC has failed or is unable to remedy the defect without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you had this reprogramming done before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. **If you are the lessor of this vehicle, Federal Law requires that you forward this notice to the lessee within ten days.** For more information, contact Warranty Administration at Detroit Diesel Corporation, 13400 Outer Drive West, Detroit, MI 48239 or call (313) 592-5791.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your continued satisfaction with our products.

**DETROIT DIESEL CORPORATION
CAMPAIGN BULLETIN 06C-4
SERVICE ADMINISTRATION CAMPAIGN COORDINATOR (BX-5)**

RECEIVED

JUN 19 2006

DETROIT DIESEL

CORPORATION



COUNTRY COACH, INC.
135 EAST FIRST AVENUE
JUNCTION CITY OR 97448
US

Safety Recall 06C-4

Attention Equipment Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Detroit Diesel Corporation (DDC) has decided that a defect which relates to motor vehicle safety exists in the exhaust systems in certain Series 60 Coach and Motor Home engines.

The turbocharger can fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

Records available to us indicate that your vehicle is equipped with one of these affected engines. DDC will repair your engine at no charge to you by reprogramming the ECM to prevent the possibility of a turbocharger failure progressing to an engine compartment fire. We estimate that it will take approximately 0.5 hours to reprogram your engine. In addition to reprogramming the ECM, certain model year engines will need to have barometric pressure sensors and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. Please contact your authorized repair facility to arrange a service date.

If you have any questions about this recall campaign, you may call 313-592-5800. If you believe that DDC has failed or is unable to remedy the defect without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

DETROIT DIESEL

CORPORATION



If you had this reprogramming done before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. **If you are the lessor of this vehicle, Federal Law requires that you forward this notice to the lessee within ten days.** For more information, contact Warranty Administration at Detroit Diesel Corporation, 13400 Outer Drive West, Detroit, MI 48239 or call (313) 592-3708.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your continued satisfaction with our products.

**DETROIT DIESEL CORPORATION
CAMPAIGN BULLETIN 06C-4
SERVICE ADMINISTRATION CAMPAIGN COORDINATOR (BX-5)**

DETROIT DIESEL

CORPORATION



Engine Serial Number	VIN	Type
06R0830350	2PCW3349651028683	XL MTH
06R0843592	2PCW3349951028757	XL MTH
06R0855284	2PCW3349461028800	XL MTH
06R0849454	2PCW3349161028785	XL MTH
06R0844836	2PCW3349051028761	XL MTH
06R0842152	2PCW3349851028748	XL MTH
06R0835724	2PCW3349X51028721	XL MTH
06R0774278	2PCW3349251028440	XL MTH
06R0762800	2PCW3349351028396	XL MTH
06R0769173	2PCW3349551028416	XL MTH
06R0850369	2PCW3349761028791	XL MTH
06R0770765	2PCW3349251028423	XL MTH
06R0827772	2PCW3349151028686	XL MTH
06R0784099	2PCW3349X51028489	XL MTH
06R0785206	2PCW3349751028496	XL MTH
06R0798593	2PCW3349051028534	XL MTH
06R0812557	2PCW3349051028615	XL MTH
06R0805188	2PCW3349851028572	XL MTH
06R0759800	2PCW3349X51028377	XL MTH
06R0818124	2PCW3349X51028640	XL MTH
06R0574892	2PCW33495Y1027187	XL MTH
06R0628494	2PCW3349411027560	XL MTH
06R0760106	2PCW3349251028390	XL MTH
06R0836934	2PCW3349551028724	XL MTH
06R0809893	2PCW3349651028604	XL MTH
06R0836997	2PCW3349361028822	XL MTH

