

revised  
8/30/06

06 V-320

2 Pages

August 25, 2006

Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
U.S. Department of Transportation  
400 Seventh Street S.W.  
Washington, DC. 20590

Dear Sir or Madam:

Pursuant to 49 CFR Part 573, Jayco, Inc. ("Jayco" or the "Company") is submitting this report to NHTSA concerning a recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.5(c)(2)

Affected vehicles are Model Year 1994 - 2002 Jayco motorhomes models,

- 1994 Eagle 210 RB/DB, 220 RK, 230 RB/DB, 280 IB/QB WB/B, 270 DB/TB, 280 IB QB/TB, 290 FL WB/B, 290 SB WB/B, 290 DB/TB, 290 DB/TB/B WB/B.
  - 1995 Eagle 211 RB, 222 RK, 231 RB, 283 IB, 294 FL, 295 SB, 296 DB.
  - 1995 Designer 2110 RB, 2220 RK, 2310 RB, 2830 IB, 2940 FL, 2950 SB, 2960 DB
  - 1996 Eagle 211 RB, 222 RK, 231 RB, 283 IB, 294 FL, 295 SB
  - 1996 Designer 2110 RB, 2830 IB, 2940 FL, 2950 SB
  - 1997 Eagle 211 RB, 222 RK, 231 RB, 283 IB, 294 FL, 295 SB
  - 1997 Designer 2830 IB, 2940 FL,
  - 1998 Eagle 323S, 324 FL, 211 RB, 222 RK, 231 RB, 267F, 283G, 313H, 323K, 283 IB, 294R, 294 FL, 295 SB
  - 1998 Designer 323OS, 324O FL, 2830G, 3130H, 3230K, 2830 IB, 324OP, 2940 FL, 2730W
  - 1999 Eagle 267F, 283G, 313H, 323K, 294R
  - 1999 Designer 2830G, 3130H, 3230K, 324OP, 2730W
  - 2000 Eagle 267F, 283G, 313H, 261P, 294R, 286S
  - 2000 Designer 2830G, 3130H, 3230K, 2730W
  - 2001 Eagle 283G, 313H, 261P, 286S, 238Y
  - 2001 Designer 2830G, 3130H, 3150J, 3230K, 2730W
  - 2002 Eagle 283G, 313H, 261P, 286S, 238Y
  - 2002 Designer 2830G, 3150J, 3230K, 2770V
  - 2002 Greyhawk 28RB, 31RB, 26SS, 28GS, 24SS
  - 2002 Granite Ridge 2800RB, 3100SS, 3200S, 2700DS
- manufactured on Ford chassis' that were built between July 1993 and June 2002.

The recall population was determined from Jayco's manufacturing records from the Company's manufacturing plant in Middlebury, Indiana, which built on the above mentioned chassis.

573.5(c)(3)

A total of Six thousand two hundred eighty five (6285) motorhomes are subject to this recall. Specific Vehicle Identification Numbers (VIN) are as follows:  
1FDKE30G8PHA96931 through 1FDXE45S42HB44491.

573.5(c)(4)

Jayco has no estimate regarding the number of motorhomes affected by this condition. The population of affected vehicles is identifiable by referencing the VIN number range for which the vendor sold us the chassis.

573.5(c)(5)

Ford Motor Company notified Jayco of recall 06V-286 on August 21, 2006 that the potential of the under hood speed control deactivation switch may overheat, smoke, or burn when the vehicle is parked or when it is being driven. If these conditions are not addressed the vehicle may result in an under hood fire.

573.5(c)(6)

Ford Motor Company notified Jayco of this recall. Jayco is not aware of any injuries related to this issue.

573.5(c)(8)

Ford Motor Company indicated that the remedy for affected chassis' is to install a fused harness into the speed control system.

Ford Motor Company has supplied you with copies of the repair instructions, dealer and owner notification letters. Jayco's understanding is that Ford started customer and dealer notifications in August 2006.

Thank you for your assistance,

Sincerely



David C. VanderMolen  
Jayco Technical Research Department  
Senior Technical Research Liaison