

**GM SERVICE AND PARTS OPERATIONS**  
**DCS**  
**URGENT - DISTRIBUTE IMMEDIATELY**

Date: April 19, 2006

Subject: Product Safety Recall 06029  
Rear Suspension Link Assembly (Toe Link) Welding

Models: 2005 Cadillac STS and SRX

To: All Cadillac Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Service  
Manager, Used Car Manager, Parts Manager and Warranty  
Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a safety recall involving certain 2005 model year Cadillac STS and SRX vehicles.

On some of these vehicles the rear suspension toe links used on both left and right sides of the rear suspension may have a toe link assembly with little or no weld penetration into the connecting rod.

If the toe link separated from the bushing, a rear wheel may rotate (toe in or toe out) and influence vehicle control. Damage to other suspension components can occur from contact with the toe link. The driver may hear noise from the separated parts alerting him/her that something has occurred.

To correct this condition, dealers are to inspect the right and left toe link for the suspect serial numbers and replace as required. If a toe link is replaced, the dealer will perform a wheel alignment.

Approximately 23,000 vehicles are involved and GM is working with its suppliers to obtain the required parts as quickly as possible. Customer notification is scheduled to begin in May 2006.

GM Vehicle Inquiry System (GMVIS) information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS