

2006 ISUZU *i*-280 AND *i*-350 SAFETY RECALL CAMPAIGN
BRAKE LAMPS INOPERATIVE OR CONTINUOUS ILLUMINATION

To: Dealership Executive Management

Affected Vehicles:

Certain 2006 Isuzu *i*-280 and *i*-350 vehicles with a VIN range from 6870001 through 68703896.

Condition:

These vehicles may have a brake lamp switch that may not work as designed. The performance of the brakes is not affected. However, this condition could cause the simultaneous loss of all brake lamps or cause all of the brake lamps to stay on continuously. Both of these conditions could fail to warn others of the driver's intentions and could lead to a vehicle crash. Also, if equipped, the cruise control will become inoperative.

Dealer Action:

Dealers are to replace the brake lamp switch assembly at no charge to the customer.

<u>Campaign Timetable</u>	<u>Date</u>
---------------------------	-------------

Technical Service Bulletin To Be Mailed To Dealers	12/07/06
--	----------

Owner Notification Begins	12/11/06
---------------------------	----------

Please ensure that all appropriate personnel within your dealership are aware of this safety recall campaign and familiarize themselves with Recall Campaign Bulletin SB06-09-S002 in order to be able to respond to inquiries from Isuzu customers.

Sincerely,
ISUZU MOTORS AMERICA, INC.