

GM SERVICE AND PARTS OPERATIONS  
DCS1578  
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 26, 2006

Subject: Upcoming Safety Recall  
06030 - Inoperative or Continuously Illuminated Brake Lamps

Model: 2004-2006 Chevrolet Colorado  
2004-2006 GMC Canyon  
2006 Isuzu i-280 and i-350

To: All Chevrolet, GMC and Isuzu Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Used Car Manager,  
Service Manager, Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) web site, the media may report that General Motors will be announcing a safety recall involving certain 2004-2006 model year Chevrolet Colorado and GMC Canyon vehicles and 2006 model year Isuzu i-280 and i-350 vehicles.

Some vehicles may experience the permanent loss of brake lamp function or brake lamps that are illuminated at all times. The center high-mounted stop lamp (CHMSL) is affected in both instances. Also, if equipped, the cruise control will become inoperative. Any trailer brake lamps which are connected to the vehicle's brake lamp wiring will mimic the vehicle's brake lamps when either condition occurs.

To correct both conditions, dealers are to replace the brake lamp switch assembly. Dealers will perform this repair at no charge to customers.

Approximately 405,000 vehicles are involved and GM is working with its suppliers to obtain the required parts as quickly as possible. Dealers will be advised when a release date has been established for this recall.

GMVIS information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS