



NISSAN NORTH AMERICA, INC.

Corporate Office

P.O. Box 685001

Franklin, TN 37068-5001

Telephone (615) 725-1000

December 18, 2006

Mr. George Person
Chief, Recall Analysis Division
Office of Defects Investigation
Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Ref: 06V-328, 06V-244

Dear Mr. Person:

The enclosed communication is being provided pursuant to 49 CFR Part 573.6(c)(9).

Technical Compliance Department

Encl.

06V-328, 06V-244

Subject: 2003 - 2006 FX35 /FX45 Voluntary Recall Campaign – Update #1

Attention: Dealer Principal, Sales, Service and Parts Managers

*******Campaign Announcement Update #1 *******

Infiniti is conducting a Voluntary Recall Campaign on approximately 106,000 model year 2003 - 2006 Infiniti FX35/FX45 vehicles for a Federal Motor Vehicle Safety Standard (FMVSS) non-compliance issue. Some of the headlamps and the rear combination lamps do not meet some of the requirements of FMVSS 108.

To comply with the requirements of FMVSS 108, Infiniti will replace the headlamps and the rear combination lamps with new compliant ones.

IMPORTANT

PLEASE TAKE CARE CONCERNING APPLICABILITY TO INDIVIDUAL VEHICLES:

- **Some of the vehicles only need replacement of either headlamps OR rear combination lamps**
- **Most of the vehicles will need replacement of both headlamps and rear combination lamps.**

*******Dealer Inventory *******

Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to delivery under a sale or lease. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration (NHTSA).

Effective immediately, please use Service Comm (R0608) headlamps and (R0607) rear combination lamps to determine which FX35/45 vehicles, if any in your inventory may require these campaign repairs prior to being retailed. These vehicles must remain on sales hold until the recall is performed.

******* Parts Retention *******

There is a three day Warranty parts hold before scrapping the non-compliant headlamps and rear combination lamps. A drilling procedure found in the TSB is required to render the lamps unusable. The Xenon bulbs from the headlamps should be removed and disposed of per local and state regulations.

******* Owner Notification *******

Infiniti will start to mail Owner Notification Letters the week of December 18, 2006. The Service Campaign Bulletin will be published on ASIST during this time.

******* Parts Availability *******

Infiniti has scheduled weekly shipments of parts to all retailers for at least the first several weeks of the campaign. The weekly parts shipments will include a larger percentage of headlamp kits and rear combination lamp kits for the standard model (B6000-CG02A / B6500-CG02A) than for the sport model (B6000-CL02A / B6500-CL02A). This reflects the higher percentage of standard models in the campaign vehicle population. You can expect to receive an initial shipment of parts by Tuesday, December 19, 2006.

If you do not receive an initial supply of parts by this date or if you have any additional questions related to this campaign, please contact your Dealer Parts and Service Manager (DPSM).

Note: The PNC code for the draft procedure P6012 will no longer be used as of Monday, December 18, 2006.

The permanent campaign PNC's in its replacement are the following

- R0607 Replace both Headlamps
- R0608 Replace both Rear Combination Lamps

The two PNC codes are needed if the vehicle requires replacement of both the Headlamps and the Rear Combination lamps.

Infiniti Sales Operations
12/15/2006