

GM SERVICE AND PARTS OPERATIONS
DCS 1623
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 12, 2006

Subject: Upcoming Product Safety Recall 06013
DRL and Turn Signal Inoperative

Models: 2004-2005 Cadillac XLR

To: All Cadillac Dealers

Attention: Dealer Operator, General Manager, Sales Manager,
Service Manager, Used Car Manager, Parts Manager
and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a safety recall involving certain 2004 and 2005 model year Cadillac XLR vehicles equipped with daytime running lamps (DRL).

On these vehicles, the DRL, turn signal, and parking lamps use the same bulb. The bulb may become damaged from vibration within a loose fitting socket or air entering the bulb due to an inadequate seal. Both of these conditions will cause the bulb to burn out prematurely.

If this were to occur, the driver would notice that the arrow in the instrument panel would flash faster than normal when the turn signal is activated.

To correct this condition, dealers are to replace the socket and bulb in both lamps.

Approximately 8,000 vehicles are involved and GM is working with its suppliers to obtain the required parts as quickly as possible. Customer notification is scheduled to begin in July, 2006.

GM Vehicle Inquiry System (GMVIS) information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS