



*****RECALL NOTICE*****

Dealer Notice

NHTSA Recall # 06V-416

TCI Recall # 06V-416

November 9, 2009

Attention Dealer TCI Dealer:

This notice is sent in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. No. 577.13, *Notification to dealers and distributors*.

Transportation Collaborative Inc. on Behalf of US Bus Corporation has decided that a defect, which relates to motor vehicle safety, exists on certain vehicles that were manufactured by US Bus Corporation inadvertently obscuring rear view mirror labels.

The non-compliance involves Federal Motor Vehicle Safety Standard No. 111 "Rearview mirrors". Specifically, this noncompliance was caused by inadvertent obscuring of a label as required in the standard. This label addresses the use of the front cross-viewing mirrors, and what should and should not be viewed through these mirrors. It is possible that we inadvertently obscured this label while installing interior rearview mirror.

Our remedy for this defect is to affix the enclosed label to the vehicle dash to the right of the instrument cluster, as shown in the enclosed photograph, so that it is in clear view of the seated driver.

In order to ensure that all vehicles that are subject to the recall are corrected, we will perform the following actions:

- Transportation Collaborative Inc. will notify the appropriate customers and advise them to inspect their vehicle(s) for the proper label.
- TCI will further request a reply from those customers indicating whether their vehicle is affected or not.

Enclosed with this letter is a copy of the information, which describes details of the recall condition and the recall correction.

Also enclosed with this letter are copies of the information that will be sent to each customer. Should you have any vehicles in your stock that require the recall service work, please make certain that these vehicles are corrected. As per Federal Motor





Vehicle Safety Standard No. 577.13 which states that is a, *violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used (including tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.*
If you have any questions about this recall please call Transportation Collaborative Inc. Customer Service at 1-845-988-0419.
Sincerely,

Jose Vazquez

Transportation Collaborative Inc.



7 LAKE STATION ROAD

WARWICK, NY 10990

PHONE: (845) 988-2333



FMVS 111 Crossover Mirror Warning Label			RECALL#06V-416
BY: Jose Vasquez	DEPARTMENT: Warranty/ Recalls	DATE: 11/06/2009	REVISION: 2

MODEL:

US Bus Corporation Universe and Sturdibus School Buses manufactured between January 1, 1998 thru October 23, 2006

ISSUE:

Non-compliance with Federal Motor Vehicle Safety Standard 111, "Rear View Mirror" Specifically the inadvertent obscuring of a label as required by the standard. This instructs a seated driver on how to use the Crossover mirrors.

PROCEDURE:

- Vehicle Preparation -

1. Vehicle must be place in Park.
2. The vehicle key must be in the off position.

Remedy

1. Open the Drivers door and inspect the header above the driver seat for the Crossover mirror label as show in **Figure 1**.
2. If the crossover mirror label is obscured by vehicle's rear view mirror as show in **Figure 2**. Then the vehicle requires the remedy.
3. Affix the label supplied as show in **Figure 3** to the left side of the drivers steering wheel on the dash as shown in **Figure 4 and 5**.

Decal installed on front header




Figure 1

if the label is obscured by
Rear view mirror



Figure 2



FMVS 111 Crossover Mirror Warning Label		RECALL#06V-416	
BY: Jose Vasquez	DEPARTMENT: Warranty/ Recalls	DATE: 11/06/2009	REVISION: 2

Required label as per FMVS 111




Figure 3

Affix Label Here



Figure 4

Label Must be affixed as shown



Figure 5