



December 7, 2006

2006 Mazda5 Stop Delivery-Hold

Dear Mazda Dealer,

We regret to inform you that retail delivery of certain 2006 Mazda5 models in your inventory must immediately be suspended. Mazda Motor Corporation has decided to conduct a regional Recall campaign in **31** cold/wet weather states and a regional Special Service Program (SSP) in **19** remaining states to replace the sliding door latches on certain 2006 Mazda5 vehicles produced from April 12, 2005 through February 1, 2006.

ACTION REQUIRED

Beginning today, December 5, 2006, the following 2006 Mazda5 vehicles produced from April 12, 2005 through February 1, 2006 in your inventory must be inspected and repaired prior to customer delivery. Delivering subject vehicles without performing the necessary inspection and/or repair is prohibited. Failure to perform applicable recalls before delivery can result in extensive dealer fines and penalties from the Federal Government.

SUBJECT VEHICLES IN YOUR INVENTORY

JM1CR293X60113412

Parts and repair information will be sent to you by December 13th, 2006.

Once 2006 Mazda5 dealer inventory has been inspected and repaired, customer delivery may resume. Mazda will initiate the recall campaign to address retailed vehicles later this month. We apologize for any inconvenience that this stop delivery may cause, and we appreciate your cooperation in the interest of safety and customer satisfaction.

Sincerely,

David Zuchowski
V.P., Sales & Field Operations
Mazda North American Operations