

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
AC Delco Part Numbers 25167028, 25313292, 89032310 and 89032323  
NHTSA Recall Number 06E-088

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain AC Delco brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

AC Delco and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you**.

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that AC Delco/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
Delphi Part Numbers FG0215-11B1, FG0203-11B1, FG0228-11B1, 25339759,  
25339771 and 25339784  
NHTSA Recall Number 06E-088

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain Delphi brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

Delphi and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:

1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you**.

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that Delphi/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
AIRTEX Part Numbers E7089M, E7094M, E7113M and E7129M  
NHTSA Recall Number 06E-091

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain AIRTEX brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

AIRTEX and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you**.

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that AIRTEX/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
CARQUEST Part Numbers E7089M, E7094M, E7113M and E7129M  
NHTSA Recall Number 06E-091

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain CARQUEST brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

CARQUEST and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you**.

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that CARQUEST/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.



<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
MASTER Part Numbers E7089M, E7094M, E7113M and E7129M  
NHTSA Recall Number 06E-091

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain MASTER brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

MASTER and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you.**

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that MASTER/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
Bosch Part Numbers N67639, N67642, N67653, N67714, F00E190641,  
F00E190647, F00E190667 and F00E199213  
NHTSA Recall Number 06E-088

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain Bosch brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

Bosch and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you.**

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that Bosch/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.

<<Date>>

«Company»  
«Contact»  
«Address»  
«Address\_2»  
«City», «State» «ZIP\_Code»  
«Country»

Re: Notice of Safety Recall of Fuel Pump Modules  
Carter or NAPA Part Numbers P74693M, P74706M, P74802M and P76033B  
NHTSA Recall Number 06E-088

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

TI Group Automotive Systems (TIGAS) has decided that a defect which relates to motor vehicle safety exists in certain Carter/NAPA brand *aftermarket* fuel pump module manufactured by TIGAS between June 1, 2006 and September 24, 2006.

The root cause of the failure associated with this defect is the use of out-of-specification polymer material which is used in the manufacture of a “flapper valve” which serves to retain fuel in the reservoir of the module assembly. The defect results in a swelling of the valve material which can restrict the free movement of the valve and the free flow of fuel into the fuel pump. These conditions could lead to stall, rough running or no start.

Please review the following information carefully and follow all applicable instructions.

**Note: THIS RECALL ONLY PERTAINS TO AFTERMARKET FUEL PUMP MODULES AND HAS NO APPLICATION TO ANY ORIGINAL EQUIPMENT FUEL PUMP MODULES INSTALLED ON VEHICLES BY DAIMLERCHRYSLER.**

Carter/NAPA and TIGAS have initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owners. Please complete the following instructions to determine whether you should take advantage of this program.

Instructions:


1. If you own or have serviced one of the following motor vehicles and if you installed or had a mechanic or garage install an **AFTERMARKET** fuel pump module on the vehicle since June 1, 2006, proceed to Instruction # 4.
  - 1995-1997 Chrysler Cirrus
  - 1996-1999 Chrysler Sebring
  - 1995-1996 Dodge Stratus
  - 1996-1997 Plymouth Breeze
  - 1996-2000 Chrysler, Dodge and Plymouth Mini-Vans
  - 1998-2000 Chrysler Cirrus, Dodge Stratus or Plymouth Breeze
  - 1999-2000 Chrysler Sebring
  - 1998-2000 Chrysler/Plymouth Voyager, Grand Voyager, Dodge Caravan or Grand Caravan
2. If you own one of the vehicles listed above and have not had a fuel pump module replaced, or had one replaced before June 1, 2006 proceed to Instruction # 3.
3. Your fuel pump module **is not** covered by this recall. Phone Recall Management at **1-866-867-3759** for confirmation and no further action is required on your part.
4. Your fuel pump module **may be** covered by this recall. Please contact Recall Management Inc. at **1-866-867-3759** for instructions on how you can have your vehicle and fuel pump module inspected. If the module is found to be subject to the recall it will be **replaced at no cost to you.**

**NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL RECALL MANAGEMENT INC. AT 1-866-867-3759 FOR ASSISTANCE or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

In accordance with federal law, if you believe that Carter/NAPA/TIGAS have failed to adequately remedy the defect discussed in this notice without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590, or by calling the toll-free Vehicle Safety Hotline at 1-800-424-9393 (TTY: 888-327-4236); or go to <http://www.safercar.gov>.

**Thank you for your cooperation in this matter. Any questions regarding this recall or any information discussed in this notice should be referred to Recall Management Inc. at 1-866-867-3759 or log on to our web site for this recall at [www.recallresponse.com](http://www.recallresponse.com).**

Sincerely,



Kenneth R. Van Hook  
Recall Management Inc.