

# DAIMLERCHRYSLER

2006 APR -7 P 2:13

DEFECTS INVESTIGATION

DaimlerChrysler Corporation

Stephan J. Speth

Director

Vehicle Compliance & Safety Affairs

April 5, 2006

Mr. Daniel Smith  
Associate Administrator, Safety Assurance  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Dear Mr. Smith:

Reference: NHTSA Identification Number 06V-036

Enclosed are representative copies of communications relating to the 2006 model year vehicles involved in the referenced recall. DaimlerChrysler expects to notify dealers during the week of April 10, 2006 and to begin owner notification during the week of April 17, 2006. The exact number of manufactured vehicles in the recall is 14,837.

The involved Vehicle Identification Number range is:


<u>Low</u>	<u>High</u>
6W100046	6W178199

(VIN last eight characters) - 6 = 2006; W = Toledo North Assembly Plant, Toledo, OH; and the last six digits = sequential number.

**We caution that the above range represents only the lowest and highest VIN sequential numbers included in the recall. This range cannot be used to determine conclusively that a vehicle is involved in the recall because most of vehicles with a VIN within the range are not affected by the recall.**

This completes DaimlerChrysler's package of information for this recall as required by the Defects Report Regulation.

Sincerely,



Stephan J. Speth, Director  
Vehicle Compliance and Safety Affairs

Enclosure: Recall F02

cc: K.C. DeMeter

*Buckle up  
for Safety!*

**SAFETY RECALL F02 – OXYGEN SENSOR WIRING**

Dear: (Name)

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. DaimlerChrysler Corporation has decided that a defect, which relates to motor vehicle safety, exists in some **2006 model year Jeep® Liberty 4x2 vehicles equipped with an automatic transmission.**

***The problem is...*** The oxygen sensor wiring on your vehicle (VIN: XXXXXXXXXXXXXXXXXXXX) may come in contact with the exhaust system, which can cause an underbody fire.

***What your dealer will do...*** DaimlerChrysler will repair your vehicle free of charge (parts and labor). To do this, your dealer will secure the oxygen sensor wiring away from the exhaust system and repair the wiring if necessary. The work will take up to ½ hour to complete. However, additional time may be necessary depending on how dealer appointments are scheduled and processed.

***What you must do to ensure your safety...*** Simply **contact your dealer** right away to schedule a service appointment. Ask the dealer to hold the part for your vehicle or to order it before your appointment. **Remember to bring this letter with you to your dealer.**

***If you need help...*** If you have questions or concerns which your dealer is unable to resolve, please contact DaimlerChrysler at 1-800-853-1403.

Please help us update our records, by filling out the enclosed prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle. Be sure to print the last eight (8) characters of the VIN (VVVVVVVV) and notification code F02 on the postcard.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: DaimlerChrysler P.O. Box 4639 Oak Ridge, TN 37831, Attention: Reimbursement.

If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.

We're sorry for any inconvenience, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Services Field Operations  
DaimlerChrysler Corporation  
Notification Code F02

*Note to lessors receiving this recall: Federal regulation requires that you forward this recall notice to the lessee within 10 days.*