DAIMLERCHRYSLER

RECEIVED WYS-215

2005 JUN 21

DaimlerChrysler Corporation

Stephan J. Speth

OFFICE Director
DEFECTS INVESTIGATION

OFFICE DIRECTOR

O

June 16, 2006

Mr. Daniel Smith
Associate Administrator, Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Mr. Smith:

Reference: NHTSA Identification Number 06V-067

Enclosed are representative revised copies of communications relating to the 2005 and 2006 model year vehicles involved in the referenced recall. The "2005" model year referenced was inadvertently omitted from the owner letter

Accordingly, the owner letter forwarded in our June 5, 2006 letter should be discarded since it will not be used for the owner notification.

DaimlerChrysler expects to begin notification to Dodge Durango owners during the week of June 19, 2006, and to minivan owners in about one month as originally planned.

This completes DaimlerChrysler's package of information for this recall as required by the Defects Report Regulation.

Sincerely,

for Stephan J. Speth, Director

Vehicle Compliance and Safety Affairs

Enclosure: Recall F10

cc: K.C. DeMeter

DaimlerChrysler



SAFETY RECALL F10 - WINDSHIELD WIPER MOTOR

Dear: (Name)

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

DaimlerChrysler Corporation has decided that a defect, which relates to motor vehicle safety, exists in some 2005 and 2006 model year Chrysler Town & Country, Dodge Caravan, Grand Caravan and Durango vehicles. Additionally, this recall also involves a small number of 2001 through 2006 model year Town & Country, Caravan and Grand Caravan vehicles that have had a service replacement windshield wiper motor installed.

The problem is...

The windshield wiper motor armature shaft on your vehicle inoperative. This can impair the driver's vision and cause a crash without warning.

What your dealer will do...

DaimlerChrysler will repair your vehicle free of charge (parts and labor). To do this, your dealer will inspect the windshield wiper motor on your vehicle and replace it if necessary. The work will take about 1 hour to complete. However, additional time may be necessary depending on how dealer appointments are scheduled and processed.

What you must do to ensure your safety...

Simply contact your dealer right away to schedule a service appointment. Ask the dealer to hold the part for your vehicle or to order it before your appointment. Remember to bring this letter with you to your dealer.

If you need help... If you have questions or concerns which your dealer is unable to resolve, please contact DaimlerChrysler at 1-800-853-1403.

Please help us update our records, by filling out the enclosed prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle. Be sure to print the last eight (8) characters of the VIN (VVVVVVV) and notification code F10 on the postcard.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: DaimlerChrysler P.O. Box 4639 Oak Ridge, TN 37831, Attention: Reimbursement.

If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to http://www.safercar.gov.

We're sorry for any inconvenience, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

> Customer Services Field Operations DaimlerChrysler Corporation Notification Code F10