

SAFETY RECALL NOTICE

August 2006

Workhorse Recall No. 60601-C
NHTSA Recall No. 06V-225

Dear Workhorse Custom Chassis Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Workhorse Custom Chassis has decided that a defect which relates to motor vehicle safety exists in Model Year 2004, 2005, and some 2006 W20, W22, W24, P32, W18, W52 and FE20 chassis models equipped with GM L18 (8.1 liter) engines.

Our records indicate that you may be the owner of one of the following brands of vehicles that are built on a Workhorse chassis:

AIRSTREAM INC	LYNCH TRUCK CENTER
ALTEC HILINE, LLC	McCORMICK MOTORS
AMERICAN CUSTOM COACH	MONACO COACH CORP
BENDIX COMMERCIAL VEHICLE SYS	R. VISION INC. (MONACO)
CABLE CAR CONCEPTS	MORGAN OLSON CORPORATION
CANADA POST	NATIONAL RV INC
CHAMPION BUS INC	NEWMAR CORPORATION
COACHMAN	REXHALL INDUSTRIES, INC.
GEORGIE BOY MFG LLC (COACHMAN)	SUPREME CORPORATION
DAMON CORPORATION	EURO LINER (TESCHNER MOTORHOME)
DOUBLE K INC	TIFFIN MOTOR HOMES
ELDORADO NATIONAL	TRANSEO
FLEETWOOD MOTOR HOMES	TRIPLE E RECREATIONAL VEHICLE
FLEETWOOD PENNSYLVANIA	UNION CITY BODY COMPANY
FLOUNDER MOTOR HOMES OF CALIF.	UNIVERSAL SPECIALTY VEHICLES
FOREST RIVER	UTILIMASTER CORP
FOUR WINDS INTERNATIONAL	VERITRANS SPECIALTY VEHICLES
GULF STREAM COACH	WINNEBAGO INDUSTRIES

Workhorse is recalling these vehicles to replace a defective fuel rail pulse damper retainer clip. Federal regulations require that any vehicle lessor receiving this Recall Notice must forward a copy of this notice to the lessee within ten days.

REASON FOR THIS SAFETY RECALL CAMPAIGN

The subject GM L18 engine is equipped with a fuel rail pulse damper retainer clip, which may have been incorrectly heat treated. GM has advised us that the retainer clip on the subject engine may fracture without warning, resulting in inadequate retention of the damper. If the damper becomes loose, pressurized fuel may spray onto the engine.

RISK TO MOTOR VEHICLE SAFETY

In the presence of an ignition source, this may cause a fire possibly resulting in property damage, personal injury, or death.

WHAT WE WILL DO

Workhorse will replace the retainer clip with a non-defective part at no charge.

WHAT YOU SHOULD DO

To ensure that you have a new clip available to you when you visit an authorized Workhorse Dealer, we have included a clip with this letter. Please contact your Workhorse Custom Chassis dealer to arrange a service date. Refer to Service Bulletin No. 60101-C and provide your 17-digit VIN. The dealer labor time to perform this service should be approximately 1 hour. You will not be charged for this repair. Replacement parts are currently available for your dealership to order, or you may give the dealer the included clip.

If you have previously had this defect corrected, you may be eligible for reimbursement. Please contact Workhorse at (877) 946-7731 to determine reimbursement eligibility.

If you are unable to obtain the specified repair promptly and without charge, please contact Workhorse Custom Chassis at (877) 946-7731. If you believe that Workhorse Custom Chassis has failed or is unable to remedy the condition outlined above without charge within a reasonable period of time, you may contact the Administrator, National Highway and Traffic Safety Administration, at 400 Seventh Street, S.W., Washington, D.C. 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4326 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>

* * *

We apologize for any inconvenience this may cause. We have taken this action in the interest of your safety and continued satisfaction with our products.

Workhorse Custom Chassis