



Mr. George Person
Chief, Recall Management Office
National Highway Traffic Safety Adm.
400 7th Street, S.W.
Washington, D.C. 20590

RECEIVED
100 SEP 18 P 12:53
OFFICE OF THE ATTORNEY GENERAL

15 August 2006

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 06V-291 began and was completed on August 14th. As required, copies of the final notifications are being faxed for your files. Should you require original copies please contact Karen McDonnall at kmcdonnall@countrycoach.com.

Please feel free to contact me at 541-998-3720 x8382 should you have any questions.

Sincerely,

Dick Sabath
Senior Manager, Compliance Administration
Country Coach Inc.

Enclosures (2) Customer Notification, 06V-291
Dealer Notification, 06V-291

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED,
AND FIRST CLASS MAIL

August 14, 2006

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 06V-291

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

DESCRIPTION OF SAFETY DEFECT:

Prevost Car Inc. has decided that certain bus shells converted to motor homes by Country Coach Inc. may have a safety defect in the pivots mounting plate on the windshield wiper mechanism. If this part is defective, a failure of the wiper mechanism may occur while in use, making the wipers totally inoperative. Inoperative wipers under inclement weather conditions could cause a crash due to impaired visibility.

MODELS AFFECTED:

Model Years: 2007

VIN Range: 2PCW3349X51028721 – 2PCW3349461028800

Not all units within this VIN range are affected. Please refer to the attached Listing for specific units.

Prevost Car Inc. will provide to all Country Coach owners, dealerships and authorized repair centers the necessary materials to remedy the pivots mounting plate of the windshield wiper mechanism. It is estimated that the inspection will take ¼ hour and repair will take 1.0 hour. Prevost Car Inc. will make all reimbursements for labor and parts through their A.F.A. process. This work will be performed free of charge. If you need assistance in locating the nearest Prevost service facility, please contact Country Coach's customer service department at 1-800-452-8015.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Prevost Car Inc. at 418-831-5432.

Country Coach bus conversion dealers have been notified of this recall. If your dealer or the service facility fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Prevost Car Inc. at 418-831-5432 for further assistance.

If after contacting both the dealer/service facility and Prevost Car Inc. you are not satisfied that the noncompliance has been remedied within a reasonable time at no cost to you, you may wish to contact the National Highway Traffic Safety Administration at the following address or call the Auto Safety Hotline's toll free number:

Administrator
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington D.C. 40990

Or call the Vehicle Safety Hotline's toll free number at 1-888-327-4236 (TTY: 1-800-424-9153)

Or go to <http://www.safercar.gov>

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Dick Sabath
Senior Manager, Compliance Administration

Enclosures (2)

06V-291 Coach Listing

Coach #	VIN
L048	2PCW3349X51028721
L049	2PCW3349551028724
L050	2PCW3349851028748
L051	2PCW3349951028757
L052	2PCW3349051028761
L053	2PCW3349461028800