

Link-Belt Construction Equipment Company

Safety Notice 2006-501

This is to inform you of a potential issue with the steering system on your Link-Belt all-terrain crane. IMMEDIATE ACTION IS REQUIRED.

Attention Link-Belt Crane Owner:

SERIAL NUMBER AFFECTED: P4J6-8950

MACHINE MODEL AFFECTED: ATC-3130 II

The problem is.. Link-Belt has been notified by the vendor that there is a possibility of a malfunction of the steering system. If the engine fails there will be no emergency steering. Towing the machine may damage the steering gear resulting in a loss of steer function.

Until the time that the steer gear is changed, do not tow the machine under any circumstance.

Our records indicate that above mentioned Link-Belt hydraulic crane may have a suspect steering gear.

What you must do.. Contact your local Link-Belt distributor immediately to make arrangements to schedule the crane to make the repairs as soon as possible. Under no circumstance is the machine to be towed until the new parts are installed.

What Link-Belt will do. LBCE has replacement parts in stock and will work with your local distributor to ensure that repair is done in a timely manner.

If you have questions.. Please contact your local Link-Belt distributor.

We are very sorry for this inconvenience and the hardship that it may cause, however we are committed to ensuring the safety of all Link-Belt customers. Thank you for your prompt attention to this matter.