



Timothy A. Blubaugh
Director
Government Technical Affairs

Freightliner LLC
4747 N. Channel Avenue
Portland, OR 97217-7699
503.745.5219 Telephone
503.745.6800 Facsimile
TimothyBlubaugh@Freightliner.com

July 12, 2006

Dan Smith
Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Re: Defect Information Report (FL-476), NHTSA 06V-190

Mr. Smith:

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Freightliner LLC herewith submits supplemental defect information concerning the shield for the cab Power Distribution Module on certain Freightliner Argosy, Century Class S/T and Columbia trucks.

Please contact me if you have any questions.

Sincerely yours,

Timothy Blubaugh

Cc: Michael Mason, CAL-OSHA
DOSH, Legal Unit
10th Floor
455 Golden Gate Avenue
San Francisco, CA 94102

Certified Mail Article Number: 7003 3150 0004 1405 0587

RECEIVED
2006 JUL 21 A 10:51
U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION

Section 573.6 Non-Compliance Information Report
FL-476, Front Axle I-Beam; NHTSA no. 06V-190
Supplement No.: 1

July 12, 2006

(c) (1) Manufacturer: FREIGHTLINER LLC
P.O. BOX 3849
Portland, Oregon 97208
(503) 745-5219

(c) (8) Estimated Owner Notification Dates: Customer notification by first class mail using Freightliner records will be completed approximately August 30, 2006.