



RECALL CAMPAIGN

9901069 - 06V-123 / 06-088

Subject:	Incorrect tire pressure on the Federal Certification Label and Tire Loading Information Placard
Units Affected:	2006 Jay Flight Travel Trailers • 61P60051 - 0070, 0072 - 0110, 0151, 0153- 0155, 0157, 0159, 0161 - 0163, 0165, 0169 - 0170, 0176 - 0180
Action Required:	Remove incorrect Federal Certification Label and Tire Loading Information Placard. Replace with a correct Federal Certification Label and Tire Loading Information Placard
Job Operation Code:	9901069
Series Code:	N/A
Repair Time:	.3 hours
Kit Part Number:	N/A
Parts Kit Includes:	N/A
Tools Required:	Shop rags, acetone
Additional Requirements:	N/A

Instructions

Inspect the Federal Certification Label and the Tire Loading Information Placard on the trailer (Fig. 1 & Fig. 2). Check the information referring to the tire pressure. If this reads 65 PSI (448 kPa), the labels must be removed and replaced as instructed below.

MANUFACTURED BY: JAYCO, INC. DATE _____
 FABRIQUÉ PAR: _____
 INC. VEHICLE MFG. BY: _____
 VÉHICULE FABRIQUÉ PAR: _____
 GVWR/PNBV: KG _____ V.I.N./N.I.V. _____
 GAWR/PNBE: KG _____
 FRONT/DEVANT _____
 INT/CENTRAL _____
 REAR/ARRIÈRE _____
 TYPE OF VEHICLE/TYPE DE VÉHICULE: MOTOR HOME/AUTOCARAVANE
 MULTIPURPOSE PASSENGER VEHICLE/VÉHICULE DE TOURISME À USAGES MULTIPLES
 THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND STANDARDS PRESCRIBED UNDER THE CANADIAN MOTOR VEHICLE SAFETY REGULATIONS EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.
 CE VÉHICULE CONFORME À TOUTES LES NORMES QUI LUI SONT APPLICABLES EN VERTU DU RÈGLEMENT SUR LA SÉCURITÉ DES VÉHICULES AUTOMOBILE DU CANADA EN VIGUEUR À LA DATE SA FABRICATION CI-DESSUS.

Fig. 1

TIRE	SIZE	COLD TIRE PRESSURE
FRONT		
REAR		
SPARE		

SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION
FD-323

Fig. 2

1. Peel off the incorrect Federal Certification label and the Tire Loading Information Placard from the unit and discard it.
2. Use acetone to remove adhesive residue from the trailer. Apply the acetone with a rag, rubbing in a circular motion.
3. Allow the surface to dry for approximately thirty (30) seconds.
4. Remove the protective back off the new Federal Certification label and the Tire Loading Information Placard, align the labels in the appropriate position and adhere the labels to the trailer. Make sure to remove any air bubbles from the sticker.



Caution: Once the new labels have come in contact with the trailer, **DO NOT** attempt to remove or adjust it. If this occurs, the label will be permanently damaged and will not adhere properly to the trailer. If the label is damaged, a new label must be ordered.



RETAIL OWNER REPLY FORM
Federal Certification Label Recall
Jay Flight Travel Trailer

Customer Information
Label Here

Phone #: Home: _____ Work: _____

Please sign on the below line if you have performed the repair. If you no longer own the travel trailer, please notify us with the enclosed recall reply card.

I have performed the recall according to the instructions provided by Jayco, Inc.

Signature: _____ Date: _____

Please return the completed form
in the postage paid envelope provided.
Thank you
Jayco After Market Services