



## COUNTRY COACH

Mr. George Person  
Chief, Recall Management Office  
National Highway Traffic Safety Adm.  
400 7th Street, S.W.  
Washington, D.C. 20590

10 August 2006

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 06V-285 began and was completed on August 8th. As required, copies of the final notifications are being faxed for your files. Should you require original copies please contact Karen McDonnall at [kmcdonnall@countrycoach.com](mailto:kmcdonnall@countrycoach.com).

Please feel free to contact me at 541-998-3720 x8382 should you have any questions.

Sincerely,

Dick Sabath  
Senior Manager, Compliance Administration  
Country Coach Inc.

Enclosures (2) Customer Notification, 06V-285  
Dealer Notification, 06V-285

2006 AUG 16 11:57

RECEIVED

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448



COUNTRY COACH

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED,  
AND FIRST CLASS MAIL

August 7, 2006

**RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 05V-253**

Dear Country Coach Service Provider:

This bulletin is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

**DESCRIPTION OF NONCOMPLIANCE:**

Prevost Car Inc. has decided that certain bus shells converted to motor homes by Country Coach Inc. may have a safety defect in the exhaust system of the Detroit Diesel Series 60 Motor Home engine. The turbocharger could fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

**MODELS AFFECTED:**

**Model Year:** 2001  
**VIN Range:** 2PCW33495Y1027187

**Model Year:** 2005  
**VIN Range:** 2PCW3349941028322 – 2PCW3349X51028377

**Model Year:** 2006  
**VIN Range:** 2PCW339251028390 – 2PCW3349151028686

**Model Year:** 2007  
**VIN Range:** 2PCW3349X51028721 – 2PCW3349861028791

**Not all units within these VIN ranges are affected. Please refer to the attached Listing for specific units.**

The attached Detroit Diesel Corporation notification directs that all necessary repairs are to be made by an authorized Detroit Diesel distributor. All reimbursements for labor and parts will be processed through the Detroit Diesel Corporation. If a vehicle is equipped with one of the affected engines, Detroit Diesel Corporation will reprogram the ECM to prevent the possibility of a turbocharger failure. It is estimated that this will take 0.5 hours. In addition, certain model year engines will need to have a barometric processor sensor and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. This work will be performed at no cost to the consumer.

VEHICLE SAFETY  
DEFECT SERVICE  
BULLETIN


The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall of this type must be adequately repaired at no cost to the owner within a reasonable time after the owner has tendered it for repair. Failure to repair within sixty (60) days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer service department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. (Please see the enclosed Letter to Country Coach Owners) Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time.

Your assistance with this important matter is greatly appreciated. We apologize for any inconvenience this may cause you.

Sincerely,



Dick Sabath  
Senior Manager, Compliance Administration

Enclosures (2)

## 06V-285 Coach Listing

Coach #	Model	VIN
60459	BC2-45-MH-01	2PCW33495Y1027187
L014	BC2-45-EMBY-05	2PCW3349941028322
L019	BC2-45-EMBY-05	2PCW3349451028360
L023	BC2-45-EMBY-06	2PCW3349X51028377
L024	BC2-45-MNSM-06	2PCW3349251028390
L025	BC2-45-SIFA-06	2PCW3349351028396
L027	BC2-45-EMBY-06	2PCW3349551028416
L028	BC2-45-PRIL-06	2PCW3349251028423
L029	BC2-45-SIFA-06	2PCW3349251028440
L033	BC2-45-SIFA-06	2PCW3349X51028489
L034	BC2-45-EMBY-06	2PCW3349751028496
L035	BC2-45-SIFA-06	2PCW3349051028534
L038	BC2-45-MNSM-06	2PCW3349851028572
L041	BC2-45-PRIL-06	2PCW3349651028604
L042	BC2-45-EMBY-06	2PCW3349051028615
L043	BC2-45-SIFA-06	2PCW3349X51028640
L045	BC2-45-SIFA-06	2PCW3349651028683
L047	BC2-45-PRIL-06	2PCW3349151028686
L048	BC2-45-EMBY-07	2PCW3349X51028721
L049	BC2-45-SIFA-07	2PCW3349551028724
L050	BC2-45-SIFA-07	2PCW3349851028748
L051	BC2-45-PACO-07	2PCW3349951028757
L052	BC2-45-PACO-07	2PCW3349051028761
L053	BC2-45-PACO-07	2PCW3349461028800
L054	BC2-45-PACO-07	2PCW3349161028785
L055	BC2-45-PACO-07	2PCW3349861028791



## COUNTRY COACH

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED,  
AND FIRST CLASS MAIL

August 7, 2006

**RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 06V-285**

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

**DESCRIPTION OF SAFETY DEFECT:**

Prevost Car Inc. has decided that certain bus shells converted to motor homes by Country Coach Inc. may have a safety defect in the exhaust system of the Detroit Diesel Series 60 Motor Home engine. The turbocharger could fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

**MODELS AFFECTED:**

**Model Year:** 2001

**VIN Range:** 2PCW33495Y1027187

**Model Year:** 2005

**VIN Range:** 2PCW3349941028322 – 2PCW3349X51028377

**Model Year:** 2006

**VIN Range:** 2PCW339251028390 – 2PCW3349151028686

**Model Year:** 2007

**VIN Range:** 2PCW3349X51028721 – 2PCW3349861028791

**Not all units within these VIN ranges are affected. Please refer to the attached Listing for specific units.**

The attached Detroit Diesel Corporation notification directs that all necessary repairs to be made by an authorized Detroit Diesel distributor. All reimbursements for labor and parts will be processed through the Detroit Diesel Corporation. If your vehicle is equipped with one of the affected engines, Detroit Diesel Corporation will reprogram the ECM to prevent the possibility of a turbocharger failure. It is estimated that this will take 0.5 hours. In addition, certain model year engines will need to have a barometric processor sensor and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. Please contact your nearest Detroit Diesel Corporation as soon as possible to arrange a service date. When you take your motor home in to be serviced present this letter. If you need assistance in locating the nearest Detroit Diesel Corporation service facility, please contact Country Coach's customer service department at 1-800-452-8015.

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Detroit Diesel Corporation at 313-592-5791.

Country Coach bus conversion dealers have been notified of this recall. If your dealer or the service facility fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Detroit Diesel Corporation at 313-592-5791 for further assistance.

If after contacting both your dealer/service facility and Prevost Car Inc. you are not satisfied that the noncompliance has been remedied within a reasonable time at no cost to you, you may wish to contact the National Highway Traffic Safety Administration at the following address or call the Auto Safety Hotline's toll free number:

Administrator  
National Highway Traffic Safety Administration  
400 7th Street, S.W.  
Washington D.C. 40990

Or call the Vehicle Safety Hotline's toll free number at 1-888-327-4236 (TTY: 1-800-424-9153)

Or go to <http://www.safercar.gov>

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Dick Sabath  
Senior Manager, Compliance Administration

Enclosures (2)