



U.S. Department  
of Transportation

400 Seventh Street, SW  
Washington, DC 20590

**National Highway  
Traffic Safety  
Administration**

*February 15, 2007*

L. TAYLOR WARD III  
VICE PRESIDENT & GENERAL MANAGER  
SOUTHEAST TOYOTA DISTRIBUTORS, LLC  
100 JIM MORAN BOULEVARD  
DEERFIELD BEACH FL 33442

NVS-215paw  
07V-048

Subject: CRUISE CONTROL MODULE/ROSTRA PRECISION

Dear MR. WARD:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

TOYOTA/SCION XA/2006-2007  
TOYOTA/SCION XB/2006-2007

**NHTSA Campaign Number:** 07V-048

**Mfg's Report Date:** January 16, 2007

**Components:** VEHICLE SPEED CONTROL:CRUISE CONTROL

**Potential Number of Units Affected:** 716

**Summary:**

CERTAIN ROSTRA PRECISION CONTROLS' SPEED CONTROLS MAY HAVE A FAULTY MODULE. THESE CONTROLS WERE INSTALLED BY SOUTHEAST TOYOTA DEALERS OR AT THEIR VEHICLE PROCESSING CENTER ON CERTAIN PASSENGER VEHICLES. WHEN THE SPEED CONTROL "ON/OFF" SWITCH IS PRESSED ONCE TO TURN THE UNIT OFF, THE THROTTLE DOES NOT RETURN TO IDLE. WHEN THE "ON/OFF" SWITCH IS PRESSED A SECOND TIME, THE THROTTLE WILL RETURN TO IDLE.

**Consequence:**

A CRASH COULD BE CAUSE IN THE EVENT THAT THE CRUISE CONTROL DOES NOT ALLOW THE ENGINE TO RETURN TO IDLE ON THE FIRST DEPRESSION OF THE “ON/OFF” SWITCH.

**Remedy:**

DEALERS WILL INSPECT AND/OR REPLACE THE SPEED CONTROL MODULE. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE FOR THIS CAMPAIGN. OWNERS MAY CONTACT SOUTHEAST TOYOTA AT 1-800-301-6859.

**Notes:**

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION’S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at [patricia.wallace@dot.gov](mailto:patricia.wallace@dot.gov) or [delia.lopez@dot.gov](mailto:delia.lopez@dot.gov). We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement