



U.S. Department  
of Transportation

400 Seventh Street, SW  
Washington, DC 20590

**National Highway  
Traffic Safety  
Administration**

*February 20, 2007*

CRAIG BIAZO  
DIRECTOR OF SERVICE  
TRAVEL TRAILER DIVISION  
FLEETWOOD ENTERPRISES, INC.  
3030 MYERS STREET PO BOX 7638  
RIVERSIDE CA 92513-7638

NVS-215paw  
07V-059

Subject: ABS MODULE LOCATION

Dear MR. BIAZO:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

FLEETWOOD/AMERICAN EAGLE/2007  
FLEETWOOD/AMERICAN TRADITION/2007

**NHTSA Campaign Number:** 07V-059

**Mfg's Report Date:** February 13, 2007

**Components:** SERVICE BRAKES, HYDRAULIC:ANTILOCK

**Potential Number of Units Affected:** 133

**Summary:**

ON CERTAIN AMERICAN EAGLE AND AMERICAN TRADITION CLASS A MOTOR HOMES, THE ANTI-LOCK BRAKE SYSTEM (ABS) MODULE MAY NOT HAVE BEEN PERMANENTLY MOUNTED. THE MODULE COULD DETACH FROM THE VEHICLE.

**Consequence:**

THE ANTI-LOCK FEATURE FOR THE BRAKE SYSTEM COULD BE LOST.

**Remedy:**

DEALERS WILL INSPECT AND PERMANENTLY MOUNT THE ABS MODULE TO THE INSIDE OF THE CHASSIS RAIL. THE RECALL IS EXPECTED TO BEGIN DURING FEBRUARY 2007. OWNERS MAY CONTACT FLEETWOOD AT 1-800-509-3418.

**Notes:**

FLEETWOOD RECALL NO. 70131. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).

Please provide the following additional information and be reminded of the following requirements:


You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during February 2007. Therefore, the first quarterly report will be due on or before April 30, 2007.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at [patricia.wallace@dot.gov](mailto:patricia.wallace@dot.gov) or [delia.lopez@dot.gov](mailto:delia.lopez@dot.gov). We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement