



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 24, 2007

GAY P. KENT
DIRECTOR, PRODUCT INVESTIGATIONS
STRUCTURE & SAFETY INTEGRATION
GENERAL MOTORS CORPORATION
30001 VAN DYKE – MAIL CODE 480-210-G11
WARREN MI 48090-9055

NVS-215dgl
07V-373

Subject: ABS WHEEL SPEED SENSOR WIRING

Dear MS. KENT:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
HUMMER/H2 SUT/2008
HUMMER/H2 UTILITY/2008

NHTSA Campaign Number: 07V-373

Mfg's Report Date: August 21, 2007

Components: SERVICE BRAKES, AIR:ANTILOCK:WHEEL SPEED SENSOR

Potential Number of Units Affected: 363

Summary:
ON CERTAIN VEHICLES, THE WIRING IN THE ABS WHEEL SPEED SENSOR FRONT OR REAR HARNESS MAY BE REVERSED.

Consequence:
THIS CONDITION COULD RESULT IN INCREASED STOPPING DISTANCE INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL CORRECT THE ABS WHEEL SPEED SENSOR WIRING AND, IF NECESSARY, REPROGRAM THE BRAKE CONTROL MODULE FREE OF CHARGE. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT HUMMER AT 800-732-5493.

Notes:

GM RECALL NO. N070221. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement