



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue, SE.
Washington, DC 20590

September 11, 2007

DEBRA S. DODGE
WARRANTY/SERVICE
TRAVEL SUPREME
66149 STATE ROAD 19
WAKARUSA IN 46573

NVS-215dgl
07V-408

Subject: GAS COOKING APPLIANCE/SUBURBAN

Dear MS. DODGE:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
TRAVEL SUPREME/MOTORHOME/2006

NHTSA Campaign Number: 07V-408

Mfg's Report Date: September 4, 2007

Components: EQUIPMENT:RECREATIONAL VEHICLE

Potential Number of Units Affected: 12

Summary:

ON CERTAIN MOTOR HOMES EQUIPPED WITH SUBURBAN GLASS TOP, SEALED BURNER RANGE OR SLIDE IN COOK TOP, A THREADED CONNECTOR ON THE TUBE BETWEEN THE BURNER VALVE AND THE BURNER MAY NOT HAVE BEEN FULLY TIGHTENED DURING THE MANUFACTURING PROCESS.

Consequence:

IF THE THREADED CONNECTOR IS NOT PROPERLY TIGHTENED, IT IS POSSIBLE FOR THE GAS TO LEAK FROM THE CONNECTION WHEN THE BURNER IS TURNED ON. LP GAS IS HEAVIER THAN AIR AND ANY LEAKED GAS COULD ACCUMULATE IN AN ENCLOSED OR LOW AREA IN YOUR RECREATION VEHICLE. A SUFFICIENT QUANTITY OF ACCUMULATED GAS, IF IGNITED, COULD CAUSE A FIRE OR EXPLOSION.

Remedy:

TRAVEL SUPREME IS WORKING WITH SUBURBAN TO HAVE THE BURNER TUBES REPLACED (PLEASE SEE 07E-050). OWNERS MAY CONTACT SUBURBAN AT 423-775-2131 OR TRAVEL SUPREME AT 574-862-1960.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Please provide the following additional information and be reminded of the following requirements:

We have reviewed your proposed owner letter and it meets the requirements of Part 577.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement