



James P. Vondale, Director
Automotive Safety Office
Environmental & Safety Engineering

Fairlane Plaza South
330 Town Center Drive
Dearborn, MI 48126-2738 USA

June 18, 2007

Mr. Daniel C. Smith
Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590


Dear Mr. Smith:

Subject: Amendment to the Ford Motor Company Notification Letter for Land Rover
Voluntary Recall No. P002 -- 2002 through 2005 Model Year Land Rover
Freelander Brake Lamp Switches

This is an amendment to a February 2, 2007, 49 CFR Part 573 Defect and Non-Compliance letter from Ford Motor Company (Ford) that provided notification of Land Rover recall number P002 concerning an interim repair for the reported condition. Information in the section 573.6 (c) (8) -Service Program is being updated to provide revised timing information.

In addition, to ensure that recall response rates can be correctly reported, Land Rover has allocated recall number P004 to the final action of installing the newly designed brake lamp switch and wire harness.

Sincerely,


James P. Vondale
Attachment



49 CFR Part 573 – DEFECT INFORMATION REPORT
P002 – 2002 THROUGH 2005 MODEL YEAR LAND ROVER FREELANDER BRAKE LAMP
SWITCHES

Pursuant to Part 573 of Title 49 of the Code of Federal Regulations, Defect and Non-compliance Reports, Ford submits the following amended information to that previously provided concerning a safety recall action that its wholly owned subsidiary, Land Rover, is initiating voluntarily.

573.6 (c) (8) Service Program

In the February 2, 2007, notification letter, it was stated that Land Rover would notify the additional owners during the week of May 28, 2007. Regrettably, Land Rover has identified a quality concern with the initial supply of replacement brake lamp switches, resulting in an insufficient supply of parts to support the timing stated for the permanent corrective action. The interim remedy remains in place while a sufficient quantity of parts to complete the permanent action is being obtained.

Land Rover now plans to notify owners during the week of July 30, 2007.

Commensurate with this revised timing, Land Rover will close the interim repair recall number P002 and to ensure that recall response rates can be correctly reported, Land Rover have allocated recall number P004 to this action of fitting the newly designed brake lamp switch and wire harness.