

RECEIVED

2007 MAR -9 A 10:30

OFFICE OF DEFECTS
INVESTIGATION/RMD

Roadmaster
310 Steury Avenue
Goshen, IN 46528
Phone: 574-537-0669

MAR 20 2007

February 27, 2007

07V-109
(2 pages)

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
U.S. Department of Transportation
400 Seventh Street SW
Washington, DC 20590

RE: Dometic Recall
NHTSA Safety Recall **063-076**

Dear Associate Administrator,

Pursuant to 49 CFR Part 573 Roadmaster, ("Roadmaster" or the "Company") is Submitting this report to NHTSA concerning a recall campaign, on record by Dometic Corporation, NHTSA Safety Recall **063-076**.

573.5(c)(2)

Affected recreational vehicles manufactured by Roadmaster, are yet to be determined.

The exact recall population has not yet been identified, but it will be determined from the Manufacturing records in Goshen, Indiana for the company's manufacturing plants.

573.5(c)(3)

Roadmaster is currently researching its records to compile for Dometic Corporation an Accurate list of Roadmaster units that had the recalled boiler tube. The company will Provide current owner information to Dometic Corporation for these affected units.

573.5(c)(4)

The recall population was determined by Dometic Corporation and the first and last Refrigerator serial numbers were provided to Roadmaster, from the Dometic Corporation. Based on the information provided by Dometic Corporation, 0.06% of the total number Of refrigerators involved are estimated to contain the defect.

573.5(c)(5)

Roadmaster, has been informed by Dometic Corporation of a safety defect (NHTSA **Safety Recall 063-076**) pertaining to the recalled boiler tube. Dometic Corporation has Filed with NHTSA a Part 573 notification concerning this matter.

The nature of the defect is that some refrigerators have boiler tubes that may develop a Fatigue crack. The consequences of the defect could be leaking pressurized coolant Solution into an area where an ignition source may be present. If this were to occur under Certain conditions, the coolant could ignite and result in a fire.


573.5(c)(6)

Roadmaster is not currently aware of any casualties or losses related to this issue.

573.5(c)(8)

The remedy provided by Dometic Corporation will involve a rework for the potential Defect at no charge for parts or labor. Dometic Corporation will be conducting the recall Campaign on behalf of the Company and reporting quarterly reports to NHTSA.

Sincerely.

A handwritten signature in black ink that reads "Larry Weaver". The signature is written in a cursive, flowing style.

Larry Weaver
Warranty Manager
Roadmaster LLC