

Fleetwood Enterprises, Inc.
3030 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwoodrv.com

August 6, 2007

Mr. Kenneth Weinstein
Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

07V-352
(3 pages)

Re: Safety Defect and Non-compliance Report

Dear Mr. Weinstein:

On August 3, 2007, Fleetwood Enterprises, Inc., decided that a non-compliance to the requirements of Part 567 "Certification" exists in travel trailers as listed below, and is furnishing this notification in accordance with 49 CFR Part 573 Defect and Non-compliance reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on August 6, 2007.
 - Fleetwood has assigned 70806 as an identification code to this recall.
- (1) The affected travel trailers were manufactured by the following wholly owned subsidiary of Fleetwood Enterprises, Inc.

Fleetwood Travel Trailers of Maryland, Inc. #53
10233 Governor Lane Blvd.
Williamsport, Maryland 21795 (please note: this plant is permanently closed)

The agency should contact the following person with respect to this recall:

Craig Biazio
Director of Service
Travel Trailer Division
3030 Myers Street
Riverside, California 92513-7638
Telephone: 951-351-3624 Fax: 951-351-3604

- (2) The vehicles involved in the recall are 2007 model year Prowler, Wilderness, Terry, 3902BDS, 390BDDS and 390BHDS model conventional travel trailers manufactured from October 9, 2006 through February 16, 2007. The February 16, 2007 coincides with stopping of production of the above mentioned models due to the manufacturing plant closure.

RECEIVED

2007 AUG 10 P 1:00

DEFECTS INVESTIGATION
RECALL MGMT DIV.

These travel trailers were built with a Fleetwood identification number range of:

1EC1B392775345215 thru 1EA1B392475345228

1ED1B392675345413 thru 1ED1B392675345430

1EC1B392275345526 thru 1ED1B392175345531

1EC1B392975345667 thru 1ED1B392475345684

- (3) Fleetwood reports 56 as an approximate number of Prowler, Wilderness, and Terry 3902BDS, 390BDDS and 390BHDS model travel trailers containing the non-compliance.
- (4) Fleetwood estimates that 100% of the Prowler, Wilderness, and Terry 3902BDS, 390BDDS and 390BHDS model travel trailers contain the non-compliance.
- (5) Fleetwood Enterprises, Inc., has become aware of a possible tire pressure rating error on the Travel Trailer Manufacturer Federal Certification tag. On Prowler, Wilderness, and Terry 3902BDS, 390BDDS and 390BHDS model travel trailers affected by this recall the 10-ply tires originally supplied with the travel trailer and rated "Load Range E", require tire inflation pressures of 80 PSI (pounds per square inch). The Certification tags were printed with a tire pressure rating of 65 PSI. The tire air pressure rating, printed on the Certification tag, must correspond with the Load Range of Tires currently installed on the travel trailer. Please note that all other values are correct.

Incorrect air pressure can cause tires to fail and may result in a vehicle crash.

- (6) Not applicable.
- (7) Fleetwood began an investigation in July, 2007 when a Fleetwood Service Technician noticed the error on a customers unit being serviced for a different issue.

Fleetwood is not aware of any accidents or injuries that have resulted from this non-compliance.

- (8) Fleetwood will mail correct travel trailer manufacturer Federal Certification tags to dealers and owner's of record and ask that they deface the original travel trailer manufacturer Federal Certification tag and replace it with the new serial number specific travel trailer manufacturer Federal Certification tag. Dealers and owner's of record will be asked to check and if necessary adjust the tire pressure to 80 PSI. Owners who are not comfortable installing this label or checking tire pressures will be asked to contact their selling dealer to have this service performed at no charge.
- (9) Fleetwood intends to conduct a dealer notification mailing on or about August 17, 2007. Fleetwood intends to conduct a customer notification mailing on or about August 17, 2007.

Fleetwood does not foresee any problems with implementing this voluntary recall campaign.

- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:

- I) Letter of dealer notification

- II) Letter of customer notification
- III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Shelley Krueger who can be reached by phone at (951) 351-3646 or by e-mail at skrueger@fleetwood.com.

Sincerely,

A handwritten signature in black ink, appearing to read 'Craig Biazio', with a stylized flourish at the end.

Craig Biazio
Director of Service
Travel Trailer Division